



15-Aug-2018
PCN #:E-18-008956

Subject:SMD High Frequency Inductors Type 3671 series

Description of Change: Due to technical difficulties, raw material challenges and uncertain market forecasts the 3671 series HiFrequency inductors will be discontinued with immediate effect.

Reason: Discontinuance.

Impact of Change:form - fit - function

Key Dates:

Last Order Date:17-Aug-2018

Last Ship/EOL Date:18-Aug-2018

Product Affected

1-2176222-6

(Alias Part Numbers:
"36712A27NJ")

1-2176221-3

(Alias Part Numbers:
"36711J12NJ")

2176220-4

(Alias Part Numbers:
"36711E1N3S")

2-2176221-0

(Alias Part Numbers:
"36711J47NJ")

Recommended Replacement

Product Affected**Recommended Replacement**

1-2176221-4

(Alias Part Numbers:
"36711J15NJ")

2176222-4

(Alias Part Numbers:
"36712A2N7S")

1-2176222-2

(Alias Part Numbers:
"36712A12NJ")

2-2176221-5

(Alias Part Numbers:
"36711JR12J")

1-2176222-5

(Alias Part Numbers:
"36712A22NJ")

1-2176222-1

(Alias Part Numbers:
"36712A10NJ")

2176222-3

(Alias Part Numbers:
"36712A2N2S")

2176221-6

(Alias Part Numbers:
"36711J3N3S")

2-2176220-6

(Alias Part Numbers:
"36711E56NJ")

2176220-8

(Alias Part Numbers:
"36711E2N0S")

Product Affected**Recommended Replacement**

2176222-6

(Alias Part Numbers:
"36712A3N9S")

2176221-7

(Alias Part Numbers:
"36711J3N9S")

1-2176222-8

(Alias Part Numbers:
"36712A39NJ")

2176220-7

(Alias Part Numbers:
"36711E1N8S")

1-2176220-1

(Alias Part Numbers:
"36711E2N7S")

1-2176222-3

(Alias Part Numbers:
"36712A15NJ")

1-2176221-2

(Alias Part Numbers:
"36711J10NJ")

1-2176220-9

(Alias Part Numbers:
"36711E15NJ")

2176222-7

(Alias Part Numbers:
"36712A4N7S")

1-2176220-3

(Alias Part Numbers:
"36711E3N3S")

Product Affected**Recommended Replacement**

2-2176221-1

(Alias Part Numbers:
"36711J56NJ")

1-2176220-2

(Alias Part Numbers:
"36711E3N0S")

2-2176221-7

(Alias Part Numbers:
"36711JR18J")

2176220-5

(Alias Part Numbers:
"36711E1N5S")

2176222-9

(Alias Part Numbers:
"36712A6N8J")

2-2176221-9

(Alias Part Numbers:
"36711JR27J")

2176222-8

(Alias Part Numbers:
"36712A5N6S")

2-2176221-2

(Alias Part Numbers:
"36711J68NJ")

2176220-3

(Alias Part Numbers:
"36711E1N2S")

1-2176220-6

(Alias Part Numbers:
"36711E8N2J")

Product Affected**Recommended Replacement**

1-2176222-0

(Alias Part Numbers:
"36712A8N2J")

2-2176222-2

(Alias Part Numbers:
"36712A82NJ")

2-2176220-9

(Alias Part Numbers:
"36711ER10J")

2-2176221-6

(Alias Part Numbers:
"36711JR15J")

1-2176220-5

(Alias Part Numbers:
"36711E6N8J")

1-2176222-4

(Alias Part Numbers:
"36712A18NJ")

2176220-6

(Alias Part Numbers:
"36711E1N6S")

2176222-5

(Alias Part Numbers:
"36712A3N3S")

1-2176222-7

(Alias Part Numbers:
"36712A33NJ")

1-2176221-6

(Alias Part Numbers:
"36711J22NJ")

Product Affected

Recommended Replacement

1-2176221-7

(Alias Part Numbers:
"36711J27NJ")

1-2176221-8

(Alias Part Numbers:
"36711J33NJ")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any

or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.