

# Honeywell Announces Obsolescence of Certain Industrial Limit Switches

Honeywell is announcing a last time buy for certain Industrial Limit Switches. A last time buy is being offered for the affected products listed below. Please refer to the Timeline of Events shown below for more details.

Due to a fixed amount of remaining capacity, fulfillment of last time buy orders will be limited and subject to cancellation at any time. It is recommended that orders be placed promptly to improve the likelihood of fulfillment.

## AFFECTED PART NUMBERS

This announcement serves as the formal communication that the SKUs listed in the addendum will no longer be available for sale in accordance with the Timeline shown below.

Affected Parts			
14CE1-4	JM1805ED4C2	LMD42-S	SL1-K125
14CE2-4	JM1808ED1C2	LMGEM-V36	SL1-PK
14CE28-2	JM3010ED1C2	LMGEM-VCEA	SL1-P-L
14CE3-3AH	JM3010ED4C2	LMGEM-VK36	SL1-T
1LS1-HOS-BLA	JM3015UD2C2	LMGEM-VKCEA	SL-E1
1LS1-HOS-BLU	JPA1705ED2C2	LMHT-52-S	SL-F
1LS56-4PGN149	JPA1705ED4C4	LML-2-S	SL-H2
2LS-J6K	JPA4020UD1C2	LMOHASAC-10K	SL-P1
4LS1-4C	JSM802ED2C2	LMPBSH12	SN1-17A
4LS1-4PG	LDVS-5314VK	LM-SP-492-S32	SR-1C-DC24V
6LS3-4PG	LM-09ARAC	LM-SP-492-S36	SSCEA31C
6PA111	LM-09ARAC10K	LM-SP-514-202	SZL-WLB-A-L3
8PA11	LM-09ARXU	LM-SP-515-578	SZL-WL-B-LE
914CE16-3A	LM-09ARXU-10K	LM-SP-515-670	SZL-WL-C-C01AH
914CE18-15	LM-09ASAC-5KOHMS	LMSP-522-621	SZL-WL-E-LE
914CE1-AQ1	LM-09ASXP10K	LM-SP-534-361	SZL-WL-I-L3
914CE20-3L1N97	LM121-S	LM-SP-975-18	SZL-WL-L
914CE29-Q	LM124-S	LM-SP-975-30	SZR-LY2-S-N1AC24V
91MCE16-P3	LM1-526-Q	LMSP-997-336	SZR-LY4-S-N1 DC12V
91MCE16-P3B	LM-3B-30A2-S	LMSP-997-337	SZR-LY4-S-N1AC110V
91MCE16-PQ	LM-3C-30A2-S	LM-SP-TWIN971-SM	ZLAC01A1B
91MCE16-S1BP	LM3P-30A2-S	LMT-91-D	ZLAC01A2BR
91MCE16-SQ	LM476-S	LMT-91-S	ZLAC01A4J
91MCE18-P3	LM491-S	LMT-91-SC36	ZLAC01B
91MCE18-PBQ	LM492-S	LMT-91-SC36A	ZLAC01C
91MCE18-S1	LM500-AN-2K	LMT-91-SCE	ZLAC06A4J

91MCE18-S3B	LM500-H-10K	LMT-91-SE	ZLBA01A1B
91MCE1-P1B	LM511-B	LMT-91-SWANOS	ZLC-4DRM-085
91MCE1-P2	LM511-B20	LMTWIN 3B-30A2-S	ZLC-4DSF-2
91MCE1-P2B	LM511-B20	LMTWIN 3C-30A2-S	ZLCA01A1B
91MCE1-P3	LM511-B4	LMTWIN 88SHI-05	ZLCA01D
91MCE1-PBQ	LM522-B14	LMTWIN T-91-SC48	ZLCA07A1B
91MCE1-PQ	LM522-F28	LMTWIN-635-S	ZLCB03A1B
91MCE1-SBQ	LM526-AA	LMTWIN-635-S	ZLCB03A1Y
91MCE1-SQ	LM531-SWH	LMTWIN-74	ZLCB03A4J
91MCE27-P1	LM531-SWHO	LMTWIN-971-SMC48	ZLCC01A2B
91MCE27-P2	LM531-SWHP3	LMTWIN-T-91-S	ZLCC01C-1
91MCE27-P5B	LM531-SWN	LMWP-541-S	ZLDA01A1B
91MCE27-S1	LM532-SWHOX	LMWP-541-SC	ZLDA01A1B-R
91MCE28-PQ	LM532-SWN	LS4J1A-7N	ZLDA01A1Y
91MCE2-P5B	LM533-SWHO	LSA6B-2D	ZLDA01A2A
91MCE2-PBQ	LM535-SWH	LSA7L-1D	ZLDA01C
91MCE2-S1	LM536-Q	LSD5A	ZLDA03C
91MCE2-S2	LM571-DWH	LSJ6B-7N	ZLDA03D
91MCE30-S1	LM571-DWHO	LSM6D-1P	ZLDA04B
91MCE3-P1B	LM574-DWHA	LSM7U	ZLDA04D
91MCE3-PBQ	LM574-DWHOXA	LSYRB6B	ZLDA06A2B
BZE6-2RN-C	LM632-D	LSZ3M	ZLDA06D
GLAC07C	LM632-DA	LSZ51F	ZLDA07A2B
GLAC20E7B	LM632-S	LSZ51R	ZLDC01C-R-2
GLCA01A9A	LM635-S	LSZ53E	ZLDC01D1-R-2
GLCB01A9A	LM636-S	LSZ55	ZLDC01D-R-2
GLEB33B	LM642-S	NGCMA00NX01A1B	ZLDC03C-R
GLFC24A2B	LM646-S	NGCMA00PX01P-L40	ZLDC03D-R
GLFC24A4J	LM68-S3	NGCMA02AX01C	ZLDC04B
GLLA01A1Y	LM72	NGCMA30AX01C	ZLDC06A1B
GLLA01A3B	LM81DH12	NGCMA50AX01C	ZLDC06C
GLLA03A2B	LM81SH12	NGCMB00NX01A1A	ZLDC06C-R1
GLLA03A2Y	LM-911-SZ	NGCMB02AX24A6B	ZLDC06D
GLLA03A4J	LM936-SWH	NGCMB10AX01Q	ZLDC06D-R1
GLLA03C	LM968-A3	NGCMC00PX01P-L40	ZLDC06DY-R1
GLLA03F	LM971 -DC26J	NGCPA02AX01C	ZLDC07B
GLLA04A2B	LM971-DC26H	NGCPA10AX01B	ZLDC07E7B
GLLA04C	LM971-DH	NGCPA20AX01S	ZLDD04A1B
GLLA06A1B	LM971-DHM	NGCPA20BX24J	ZLDXA01A4J
GLLC01A1Y	LM971-DJ	NGCPB10AX01A6D	ZLDXA01C

GLLC01F	LM971-DJM	NGCPB10BX01P-L40	ZLDXA01D
GLLC03A2B	LM971-S	NGCPB10BX07A6A-M01	ZLDXC01A2Y
GLLC03D	LM971-SA	NGCPB10BX07A6A-M02	ZLDXC01E7B-R1
GLLC04A2B	LM971-SB	NGCPB10BX07C	ZLDXC06K
GLLC06A1B	LM971-SC26	NGCQA02AX01A6D	ZLXD01A2B
GLZ303	LM971-SM	NGCQA10BX24C-T	ZLEA01A1B
GLZ336	LM971-SWN0210	NGCQA10BX24J-T	ZLEA01D
GTS0041-5	LM971-SY	NGCQA50AX01C	ZLEC01C
GTS0068DS-1	LM972-S	SL1-AKFXG2	ZLEC01D
HLS-D	LM974-S	SL1-AL	ZLFA01A1B
HLS-H	LM981-SC36	SL1-E-K	ZLFA01D
JM1202ED1C2	LMD41-SN028	SL1-HFXG2	ZLFC03C
JM1204UD1C2			

**TIMELINE OF EVENTS**

The following timeline pertains to all retired SKUs. These dates are subject to change based on availability.

Action	Description	Date
Last Time Buy	Current price honored to support historical usage through November 31, 2020.	Now to November 30, 2020
Last Time Buy	Orders placed within this period will receive parts at a 20% increased price.	November 30 to December 31, 2020
Last Ship Date	Orders must be placed with requested delivery dates in this window. Depending upon overall demand, Honeywell will contact customers to recommend alternate delivery dates.	Now to December 31, 2020

**REGIONS AFFECTED**

- Asia Pacific (APAC)
- Europe, Middle East, Africa (EMEA)
- Greater China (GrCH)
- Latin America (LATAM)
- North America (NA)

**CONTACT INFORMATION**

Honeywell is committed to providing you with a superior level of customer service. Please contact your Honeywell representative for additional information regarding this communication.

• **Product marketing:**

- Global: David Szemborski, Sr. Global Offering Manager, [david.szemborski@honeywell.com](mailto:david.szemborski@honeywell.com)

- North America: Pam Davis, Sr. Customer Marketing Manager, [pam.davis@honeywell.com](mailto:pam.davis@honeywell.com)
  - EMEA: Stephanie Edmonson, Sr. Customer Marketing Manager, [stephanie.edmonson@honeywell.com](mailto:stephanie.edmonson@honeywell.com)
  - China: Teddy Zhang, Sr. Customer Marketing Manager, [Zhang.SiHua@Honeywell.com](mailto:Zhang.SiHua@Honeywell.com)
  - ASEAN: Bernice Wan, Sr. Customer Marketing Manager, [HueSoo.Wan@Honeywell.com](mailto:HueSoo.Wan@Honeywell.com)
  - India: Jeevesh, Bawa, Sr. Customer Marketing Manager, [Jeevesh.Bawa@Honeywell.com](mailto:Jeevesh.Bawa@Honeywell.com)
- **Application engineering:**
    - Global: Darryl Ballard, Advanced Application Engineer, [darryl.ballard@honeywell.com](mailto:darryl.ballard@honeywell.com)


Please note that Honeywell has specific warranty provisions applicable to obsolete products. The relevant language is set forth below.

## WARRANTY/REMEDY

Subject to the following conditions, Honeywell warrants goods of its manufacture as being free of defective materials and faulty workmanship during the applicable warranty period. Honeywell's standard product warranty applies unless agreed to otherwise by Honeywell in writing; please refer to your order acknowledgement or consult your local sales office for specific warranty details. If warranted goods are returned to Honeywell during the period of coverage, Honeywell will repair or replace, at its option, without charge those items that Honeywell, in its sole discretion, finds defective. **Notwithstanding the foregoing, in the event of a product end-of-life or obsolescence, or inability of Honeywell to manufacture or source materials or component parts for a product, for whatever reason, and/or any associated last-time buy in relation to a product (an "Obsolescence"), Honeywell shall engage in commercially reasonable efforts to repair or replace products in accordance with the terms of its standard warranty, but in no event shall it be liable if it is unable to do so due to the Obsolescence. The foregoing is buyer's sole remedy and is in lieu of all other warranties, expressed or implied, including those of merchantability and fitness for a particular purpose. In no event shall Honeywell be liable for consequential, special, or indirect damages.**

If you have any questions, please contact your sales representative for Honeywell products.

Best Regards,



Amrita G. Khemchandani

VP Marketing, Sensing and IoT