



Product Termination Notification



Product Group: Opto Modules & Visibles 28-JAN-2021 / PTN OMV-1160-2020 Rev. 0

TITLE: Obsolescence of Products impacted by material obsolescence and Products with low sales

DESCRIPTION OF CHANGE: The Products defined in this Product Termination Notice have reached their end of life and are being made obsolete

CLASSIFICATION OF CHANGE: Product Obsolescence

REASON FOR CHANGE: Obsolescence of the emitter die by the manufacturer.
Parts with low sales.

PRODUCT CATEGORY: LEDs

PART NUMBERS / SERIES / FAMILIES AFFECTED:

Little Star:

VLMR71AAAC-GS08, VLMW712T2T3QN-GS08, VLMW712T3U3US-GS08, VLMW712U2U3XV-GS08, VLMY71AAAC-GS08

0603 white and blue selected parts using CREE die:

TLMB1100-GS08, VLMW11R2S2-5K8L-08

3mm and 5mm LED selected parts using CREE die:

TLHB4200, TLHB4201, TLHB4400, TLHB44K2M1, TLHB5100, TLHB5102, TLHB5400, TLHB5800

3mm white LEDs:

VLHW4100, VLHW4101-YLWU, VLHW4400-JKPL, VLHW4400-LKNL, VLHW4400-QPMM

PLCC2-Plus:

VLMK51Z1AA-GS08, VLMR51Z1AA-GS08, VLMW51Q2R3-GS08, VLMY51Z1AA-GS08

PLCC2 selected parts using CREE die:

1.030.023.078, 8928B50056, VLMB3000L-GS08, VLMB31J2K2-3-GS18, VLMB31J2K2-GS08, VLMB31J2K2-GS18, VLMB31K2L2-GS08, VLMB31K2L2-GS18, VLMB31K2L2-3-GS18, VLMB31K2L2-3-GS18, VLMB31K2L2-GS08, VLMB31K2L2-GS18

PLCC4 LEDs selected parts:

VLMK322U1V2-GS08, VLMK32ABBB-GS08, VLMPG32P1Q1-GS08, VLMR32ABBB-GS08, VLMRGB343-ST-UV-RS, VLMS322T2V1-GS08, VLMY32ABBB-GS08

IRED LEDs selected parts:

TSUS4300, TSUS4300-ASZ, TSUS4400, TSUS4400-CSZ, TSUS4402, TSUS5200, TSUS5201, TSUS5202, TSUS5202-AS12, TSUS5400, TSUS5400-AS12, TSUS5401, TSUS5402, TSUS5402-AS12Z, TSUS6202, TSUS6402, VSMB11940X01, VSMY7850X01-GS08, VSMY7852X01-GS08, VSMY99445DS

VISHAY BRAND(s): VISHAY SEMICONDUCTORS

TIME SCHEDULE:

Last Time Buy Date: 01-MAY-2021

Last Time Shipment Date: 01-DEC-2021

Annotations about time schedule:

SAMPLES AVAILABLE BEGINNING:

We need samples of replacement parts for evaluation:

Yes No

If Yes return this form to contact information below.

This PCN is considered approved, without further notification, unless we receive specific customer concerns before: 01-MAR-2021 or as specified by contract.

ISSUED BY:

PM: Harald Lunt, Product Marketing Visibles

Phone: +49 7131 7498-615

Email: harald.lunt@vishay.com

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

**VISHAY Intertechnology Asia Pte. Ltd.
Business Marketing Asia/Japan**

25 Tampines Street 92
Keppel Building # 02-00
Singapore 528877

Phone: +65 6780 7879
Fax: +65 6780 7897

**VISHAY Intertechnologies, Inc.
Business Marketing The Americas - Opto**

2585 Junction Avenue
San Jose, California 95134-1923
United States of America

Phone: +1-408-567-8358
Fax: +1 408-240-5687

**VISHAY Semiconductor GmbH
Business Marketing Europe Opto**

Theresienstr. 2
D-74025 Heilbronn
Germany

Phone: +49-7131-67-2113
Fax: +49-7131-67-3144



Product Termination Notification



Product Group: Opto Modules & Visibles 28-JAN-2021 / PTN OMV-1160-2020 Rev. 0

Attached Part Number List:

Material
VLMR71AAAC-GS08
VLMW712T2T3QN-GS08
VLMW712T3U3US-GS08
VLMW712U2U3XV-GS08
VLMY71AAAC-GS08
TLMB1100-GS08
VLMW11R2S2-5K8L-08
TLHB4200
TLHB4201
TLHB4400
TLHB44K2M1
TLHB5100
TLHB5102
TLHB5400
TLHB5800
VLHW4100
VLHW4101-YLWU
VLHW4400-JKPL
VLHW4400-LKNL
VLHW4400-QPMM
VLMK51Z1AA-GS08
VLMR51Z1AA-GS08
VLMW51Q2R3-GS08
VLMY51Z1AA-GS08
1.030.023.078
8928B50056
VLMB3000L-GS08
VLMB31J2K2-3-GS18
VLMB31J2K2-GS08
VLMB31J2K2-GS18
VLMB31J2L2-GS08
VLMB31J2L2-GS18
VLMB31K1L2-3-GS18

VLMB31K2L2-3-GS18
VLMB31K2L2-GS08
VLMB31K2L2-GS18
VLMK322U1V2-GS08
VLMK32ABBB-GS08
VLMPG32P1Q1-GS08
VLMR32ABBB-GS08
VLMRGB343-ST-UV-RS
VLMS322T2V1-GS08
VLMY32ABBB-GS08
TSUS4300
TSUS4300-ASZ
TSUS4400
TSUS4400-CSZ
TSUS4402
TSUS5200
TSUS5201
TSUS5202
TSUS5202-AS12
TSUS5400
TSUS5400-AS12
TSUS5401
TSUS5402
TSUS5402-AS12Z
TSUS6202
TSUS6402
VSMB11940X01
VSMY7850X01-GS08
VSMY7852X01-GS08
VSMY99445DS