

PRODUCT CHANGE NOTIFICATION (PCN)

Product Category POWER CONNECTORS **20210303-2**

Product Group POWER CONNECTORS GROUNDING AND STEEL

ISSUE DATE: ☒ **NA** ☒ **EMEA** ☒ **LATAM** ☒ **AP** 20210219

IMPACTED REGIONS: ☒ **DISCONTINUATION**

REASON FOR CHANGE: ☐ **OTHER**

DESCRIPTION OF CHANGE: (Required)

Replacement of the CT-720 hand crimping tool and 15 dies and tool kits with 2 tools. We are introducing the CT-810 and CT-1250 require no individual dies instead an integrated turn wheel.

Discontinued
CT-720



Replacement CT-810
& CT-1250



IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2021	3	31
Old product discontinuation date*	2021	5	31

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-Customer-Service@panduit.com	CHINA: 800-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) IND-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
LATIN AMERICA			
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

Impacted Part Numbers	Compatibility Type	Replacement Part 1	Replacement Part 2	Grouping (For Complex only)	Discontinuation Date
CD-720-3	Complex	CT-1250			5/31/2021
CD-720-4	No Replacement	NO-REPLACEMENT			5/31/2021
CD-720-5	No Replacement	NO-REPLACEMENT			5/31/2021
CD-720-6	No Replacement	NO-REPLACEMENT			5/31/2021
CD-720-7	No Replacement	NO-REPLACEMENT			5/31/2021
CD-720PV8-2	Complex	CT-810			5/31/2021
CT-720-7	Compatible	CT-810	CT-1250		5/31/2021
CT-720-3	Compatible	CT-810	CT-1250		5/31/2021
CT-720-3CC	No Replacement	NO-REPLACEMENT			5/31/2021

CT-720-7CC	No Replacement	NO-REPLACEMENT			5/31/2021
CT-720	Compatible	CT-810			5/31/2021
CT-720	Compatible	CT-1250			5/31/2021
CC-720	No Replacement	NO-REPLACEMENT			5/31/2021
C-720	No Replacement	NO-REPLACEMENT			5/31/2021
CD-720-1	Complex	CT-810			5/31/2021
CD-720-2	Complex	CT-1250			5/31/2021