

Desoldering Stations

Electronically Controlled Desoldering Stations

NEW



reddot design award
winner 2007



Order No.	Model	Description
005 33 683 99	WR 3000M	Same as model WR 3000M (left side) but with desoldering iron DXV 80

Hot air nozzles: see page 128–130
Soldering tips: see page 79 / 80
Desoldering nozzles: see page 115 / 116
Spare parts: see www.weller.eu

consists of:		
005 33 666 99	WR 3M	Power unit 230 V
005 27 116 99	HAP 200	Hot air iron 200 W / 24 V
005 15 152 99	WDH 30	Safety rest for HAP 200
005 15 153 99	WDH 40	Safety rest for DXV 80
005 13 180 99	DXV 80	Inline desoldering iron 80 W, 24 V
005 29 180 99	WP 80	Soldering iron 80 W with soldering tip LT B
005 15 161 98	WDH 10T	Safety rest with Stop+Go function for WP 80
005 29 184 99	WVP	Vacuum pick up
		USB cable and software

Accessory:		
005 87 388 50		Adaptor for footswitch
005 13 120 99		Food switch 1-step