


1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	007	001	020070010000002316	See list below	Connector	2565 Appliance Inlet C6	n/a
<small>*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)</small>							
List of part numbers affected							
3-104-688	6160.0039	6160.0040	6160.0083	6160.0090			
6160.0100	6163.0015	6163.0020	6163.0021				

2 Type of change

UL upgrade from UL 498 to UL 60320-1.
Marking for UL rating 7A/125V~ updated.

3 Detailed description of change



4 Reason of change

Standards update according to the new UL/CSA 60320-1.

5 Release date

The change takes effect in ww 19/2021 (Date code 2119 or higher on label).

6 Impact of change and recommended action

Form	Yes	Change of rating marking.
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	No	-
Packaging	No	-

7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet 2565	

Product Change Notification					2565 Change of marking		
owner	creation date	release date	released by	change order no	rev	page	
zeierjo	31.03.2021	31.03.2021	muehlema	2020050	C	1 of 1	D10-052-457