Broadcom

408 E. Plumeria Drive San Jose, CA 95134 **broadcom.com**



Product Obsolescence Notification

PON#: PON-20210505-F01A0 Issue Date: May 5, 2021

Dear Customer,

Broadcom announces the obsolescence of the following OSD Products.

The part numbers have approached the end of product life cycle. As a result Broadcom has to announce obsolescence for the following products. A suggested replacement product with the same mechanical form factor and laser type is indicated in the table below.

Broadcom P/N	Product Description	Suggested replacement P/N ¹
AFBR-592xALZ AFBR-592xALZ-xxx AFBR-59M5LZ AFBR-59R5xxxLZ AFBR-59R5xxxLZ-xxx SFBR-59xxLZ	4G SFF SW Tcvr	N/A
AFBR-57J5APZ AFBR-57J5APZ-xxx AFBR-57M5APZ AFBR-57M5APZ-xxx AFBR-57R5AxZ AFBR-57R5AxZ-xxx AFBR-57R6AxZ AFBR-57R6AxZ-xxx	4G SFP SW Tcvr	AFBR-710xxMZ

¹ Suggested replacement P/N may differ in performance from the original product and interoperability has not been verified.

This notification is effective **May 3, 2021**. The key milestones are:

Last Time Buy Date is October 31, 2021, allowing 6 months for final customer orders.

Last Time Ship Date is October 31, 2022, allowing up to 12 months for final shipments.

Please note that orders will be accepted on a non-cancellable, non-returnable (NCNR) basis only. Broadcom reserves the right to limit last time buy quantities based on capacity and material availability.

If you have any questions about this obsolescence, please contact your Broadcom Field Sales Engineer or Contact Center (https://www.broadcom.com/company/contact) for any questions or support requirements.

^{*}Special exceptions may apply for specific customers.