



23-Jun-2021

PCN #:PCN-21-105150

Subject:POWER DBL LOCK PLUG HSG 3P

Description of Change: Improved Packaging

Reason: As a valued TE customer you are receiving notification of a change to the process or documentation related to the below listed part numbers. Process or documentation changes do not result from any type of engineering change or revision. We show record of you having purchased a part, or multiple parts listed below and are therefore informing you of the change.

Key Dates:

Contact By Date:19-Sep-2021

Implementation Date:19-Sep-2021

Product Affected	Alias Part Number
------------------	-------------------

3-177899-6	
------------	--

5-177898-1	
------------	--

2301328-1	
-----------	--

177899-4	
----------	--

3-177898-1	
------------	--

177898-5	
----------	--

177898-6	
----------	--

177898-4	
----------	--

5-177899-1	
------------	--

3-177899-1	
------------	--

177899-6	
----------	--

177898-1	
----------	--

177899-1	
----------	--

177898-2	
----------	--

177899-2	
----------	--

Product Affected
177898-9

Alias Part Number

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE

Connectivity.