

OFFICIAL ANNOUNCEMENT
- Discontinuation Note -

TOSHIBA

Please find the **official announcement** that TOSHIBA, in line with previous verbal information, will stop all promotion and sales activities for products in following attachment:

Related products:

see next pages

Substitution level:

0 No replacement

1 Package and characteristics are mostly same or better, not necessary to change other circuit to replace.

2 Package and characteristics are mostly same or better, but some modification of the other circuit is necessary.

3 Characteristics are same or better, but package/pin arrangement are different, so the other circuit modification is necessary.

4 Other reason.

Reason:

1 Version Up

2 Chip Shrink

3 Integration of products

4 Discontinuation of Assembly Machine

5 No Order Forecast

6 Mask disposal rule applied

9 Others

Discontinuation schedule:

1) Official announcement to Customer Date: 27.04.2021

2) Last date of order entry to Toshiba's local Sales Office in March 2022

3) Last date of delivery to customer in September 2022

Date 27.04.2021

generated by M.Piela / G.Tchouangue - Senior Product Marketing Engineers

Toshiba local Sales Office

.....

(document transmitted by E-Mail, valid without signature)

Date	BU	P/N	Phase-Out Last order entry	Obsolete Last delivery	Substitution	Replacement Company	Replacement P/N	Reason*	Remarks (English)	TEE
202104	X33	2SJ360(2RALPSTK,ZF	202203	202209	3	TOSHIBA	SSM3J356R	3		
202104	X33	2SJ360(T2LMBS-S,ZF	202203	202209	3	TOSHIBA	SSM3J356R	3		
202104	X33	2SJ360(T2LPED,ZF)	202203	202209	3	TOSHIBA	SSM3J356R	3		
202104	X33	2SK2615(2LIMASENZF	202203	202209	3	TOSHIBA	SSM3K2615R	3		
202104	X33	2SK2615(T2LALPS,ZF	202203	202209	3	TOSHIBA	SSM3K2615R	3		
202104	X33	2SK2615(T2LALPSAZF	202203	202209	3	TOSHIBA	SSM3K2615R	3		
202104	X33	2SK2615(T2LUSNH,ZF	202203	202209	3	TOSHIBA	SSM3K2615R	3		
202104	X33	2SK2615(T2LYAZK,ZF	202203	202209	3	TOSHIBA	SSM3K2615R	3		
202104	X33	2SK2615,LASNZF(O	202203	202209	3	TOSHIBA	SSM3K2615R	3		
202104	X33	2SK2964(T2LMDNSIZF	202203	202209	3	TOSHIBA	SSM3K336R	3		
202104	X33	JS2M27F-A1S(SUNA)	202203	202209	0			3		
202104	X33	JS3T60-A1S(AST)	202203	202209	0			3		
202104	X33	TJ100F04M3L(4LHS,Q	202203	202209	3	TOSHIBA	TJ90S04M3L	3		
202104	X33	TJ100F04M3L(T4L,Q)	202203	202209	3	TOSHIBA	TJ90S04M3L	3		
202104	X33	TJ100F04M3L,LDOQ(O	202203	202209	3	TOSHIBA	TJ90S04M3L	3		
202104	X33	TJ100F04M3L,LMNQ(O	202203	202209	3	TOSHIBA	TJ90S04M3L	3		
202104	X33	TJ100F04M3L,LYQ(O	202203	202209	3	TOSHIBA	TJ90S04M3L	3		
202104	X33	TJ100F06M3L,LKEQ(O	202203	202209	3	TOSHIBA	TJ60S06M3L	3		
202104	X33	TJ100F06M3L,LLSQ(O	202203	202209	3	TOSHIBA	TJ60S06M3L	3		
202104	X33	TJ100F06M3L,LPAQ(O	202203	202209	3	TOSHIBA	TJ60S06M3L	3		
202104	X33	TJ100F06M3L,LSYQ(O	202203	202209	3	TOSHIBA	TJ60S06M3L	3		
202104	X33	TJ100F06M3L,LTJQ(O	202203	202209	3	TOSHIBA	TJ60S06M3L	3		
202104	X33	TJ100F06M3L,LXGQ(O	202203	202209	3	TOSHIBA	TJ60S06M3L	3		
202104	X33	TJ11A10M3(LS1CN,AQ	202203	202209	3	TOSHIBA	TJ15S10M3	3		
202104	X33	TJ11A10M3(LS1CN,QM	202203	202209	3	TOSHIBA	TJ15S10M3	3		
202104	X33	TJ11A10M3,Q(M	202203	202209	3	TOSHIBA	TJ15S10M3	3		
202104	X33	TJ11A10M3,S5PPQ(M	202203	202209	3	TOSHIBA	TJ15S10M3	3		
202104	X33	TJ11A10M3,S5Q(J	202203	202209	3	TOSHIBA	TJ15S10M3	3		
202104	X33	TJ11A10M3,S5Q(M	202203	202209	3	TOSHIBA	TJ15S10M3	3		
202104	X33	TJ150F06M3L(4LCM,Q	202203	202209	2	ONSemiconductor	BBS3002	4		
202104	X33	TJ150F06M3L(4LSY,Q	202203	202209	2	ONSemiconductor	BBS3002	4		
202104	X33	TJ150F06M3L,LKEQ(O	202203	202209	2	ONSemiconductor	BBS3002	4		
202104	X33	TJ150F06M3L,LPIQ(O	202203	202209	2	ONSemiconductor	BBS3002	4		
202104	X33	TJ150F06M3L,LYQ(O	202203	202209	2	ONSemiconductor	BBS3002	4		
202104	X33	TJ20A10M3(A,Q)	202203	202209	1	ONSemiconductor	NVATS68301PZ	4		
202104	X33	TJ20A10M3(Q,M)	202203	202209	1	ONSemiconductor	NVATS68301PZ	4		
202104	X33	TJ20A10M3(S5SO,A,Q	202203	202209	1	ONSemiconductor	NVATS68301PZ	4		
202104	X33	TJ20A10M3(S5SO,Q,M	202203	202209	1	ONSemiconductor	NVATS68301PZ	4		
202104	X33	TJ20A10M3(SO,Q,M	202203	202209	1	ONSemiconductor	NVATS68301PZ	4		
202104	X33	TJ20A10M3,S5MBHQ(M	202203	202209	1	ONSemiconductor	NVATS68301PZ	4		
202104	X33	TJ20A10M3,S5MBSQ(M	202203	202209	1	ONSemiconductor	NVATS68301PZ	4		
202104	X33	TJ20A10M3,S5Q(J	202203	202209	1	ONSemiconductor	NVATS68301PZ	4		
202104	X33	TJ20A10M3,S5TOJQ(M	202203	202209	1	ONSemiconductor	NVATS68301PZ	4		
202104	X33	TJ9A10M3,S5Q(J	202203	202209	3	TOSHIBA	TJ15S10M3	3		
202104	X33	TK100F04K3(4LHLS,Q	202203	202209	1	TOSHIBA	TK1R4F04PB	3		
202104	X33	TK100F04K3(4LHTA,Q	202203	202209	1	TOSHIBA	TK1R4F04PB	3		
202104	X33	TK100F04K3(4LSOY,Q	202203	202209	1	TOSHIBA	TK1R4F04PB	3		

202104	X33	TK100F04K3,LSKWQ(O	202203	202209	1	TOSHIBA	TK1R4F04PB	3	
202104	X33	TK100F04K3L(T4L,Q)	202203	202209	1	TOSHIBA	TK1R4F04PB	3	
202104	X33	TK100F06K3(4LHIJ,Q	202203	202209	3	TOSHIBA	TK90S06N1L	3	
202104	X33	TK100F06K3(4LMIB,Q	202203	202209	3	TOSHIBA	TK90S06N1L	3	
202104	X33	TK100F06K3(LUSNH,Q	202203	202209	3	TOSHIBA	TK90S06N1L	3	
202104	X33	TK100F06K3,LSKRQ(O	202203	202209	3	TOSHIBA	TK90S06N1L	3	
202104	X33	TK10A60D(LBS1CN,QM	202203	202209	2	TOSHIBA	TK750A60F,S4X(S	2	
202104	X33	TK10A60D(LS1SO6,QM	202203	202209	2	TOSHIBA	TK750A60F,S4X(S	2	
202104	X33	TK10A60D(MURA6,Q,M	202203	202209	2	TOSHIBA	TK750A60F,S4X(S	2	
202104	X33	TK10A60D(S4TEJ,X,S	202203	202209	2	TOSHIBA	TK750A60F,S4X(S	2	
202104	X33	TK10A60D,LS2JUKQ(J	202203	202209	2	TOSHIBA	TK750A60F,S4X(S	2	
202104	X33	TK10A60D,S5NORIQ(M	202203	202209	0			2	
202104	X33	TK10S04K3L,LCKQ(O	202203	202209	1	TOSHIBA	TK15S04N1L	3	
202104	X33	TK10S04K3L,LPPQ(O	202203	202209	1	TOSHIBA	TK15S04N1L	3	
202104	X33	TK11A60D(S4TEJ,X,S	202203	202209	2	TOSHIBA	TK650A60F,S4X(S	5	
202104	X33	TK12A10K3(STA4,Q,M	202203	202209	1	TOSHIBA	TK22A10N1	3	
202104	X33	TK12A10K3,S4Q(M	202203	202209	1	TOSHIBA	TK22A10N1	3	
202104	X33	TK12A10K3,S5Q(J	202203	202209	1	TOSHIBA	TK22A10N1	3	
202104	X33	TK12A10K3,S5SOYQ(M	202203	202209	1	TOSHIBA	TK22A10N1	3	
202104	X33	TK12A50D5,NDSQ(M	202203	202209	1	TOSHIBA	TK7A60W5	3	
202104	X33	TK12A60U(LBS1CNOQM	202203	202209	2	TOSHIBA	TK380A60Y,S4X(S	2	
202104	X33	TK130F06K3(4LSOY,Q	202203	202209	3	TOSHIBA	TK90S06N1L	3	
202104	X33	TK13A60D(LS1SP6,QM	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60D(PHIL,Q,M)	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	5	
202104	X33	TK13A60D(S4PHI,QM)	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60D(S4SA6,Q,M	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60D(S4SAN6,QM	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60D(SO6,A,Q)	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60D(SO6,Q,M)	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60D(STA4,A,Q)	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60D(STA4,X,M)	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60D,S4X(S	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60D,S5Q(J	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60D,S5SO6Q(M	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60DR(Q,M)	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60DR(STA4,Q,M	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60DR(STA4,X,M	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK13A60DR(STA4,X,S	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	
202104	X33	TK150F04K3L(T4L,Q)	202203	202209	3	TOSHIBA	TPH1R204PB	3	
202104	X33	TK15A60D(Q,M)	202203	202209	2	TOSHIBA	TK370A60F,S4X(S	2	
202104	X33	TK15A60D(STA4,A,Q)	202203	202209	2	TOSHIBA	TK370A60F,S4X(S	2	
202104	X33	TK15A60D(STA4,Q,M)	202203	202209	2	TOSHIBA	TK370A60F,S4X(S	2	
202104	X33	TK15A60D(STA4,X,M)	202203	202209	2	TOSHIBA	TK370A60F,S4X(S	2	
202104	X33	TK15A60D,S5Q(J	202203	202209	2	TOSHIBA	TK370A60F,S4X(S	2	
202104	X33	TK18A60V,LS1PA1X(M	202203	202209	2	TOSHIBA	TK190A65Z,S4X(S	2	
202104	X33	TK18A60V,LS1SHRQ(M	202203	202209	2	TOSHIBA	TK190A65Z,S4X(S	2	
202104	X33	TK18A60V,S4SONYX(M	202203	202209	2	TOSHIBA	TK190A65Z,S4X(S	2	
202104	X33	TK18E10K3,S1X(S	202203	202209	1	TOSHIBA	TK110E10PL	3	
202104	X33	TK20A60U(LS1CN,Q,M	202203	202209	2	TOSHIBA	TK190A65Z,S4X(S	2	
202104	X33	TK20A60U(S5PP,Q,M)	202203	202209	0			2	
202104	X33	TK20A60U,LS1NA1Q(J	202203	202209	2	TOSHIBA	TK190A65Z,S4X(S	2	
202104	X33	TK20A60U,LS1NA2Q(J	202203	202209	2	TOSHIBA	TK190A65Z,S4X(S	2	

202104	X33	TK20F25D,LQ(O	202203	202209	3	TOSHIBA	TPH1110FNNH	3	
202104	X33	TK20J60U(PAIRCOS,F	202203	202209	2	TOSHIBA	TK16J60W,S1VE(S	2	
202104	X33	TK20J60U(S1MURAT,F	202203	202209	2	TOSHIBA	TK16J60W,S1VE(S	2	
202104	X33	TK20J60U(S1TEAL,F)	202203	202209	2	TOSHIBA	TK16J60W,S1VE(S	2	
202104	X33	TK20J60U(S1TET1,F)	202203	202209	2	TOSHIBA	TK16J60W,S1VE(S	2	
202104	X33	TK20J60UA(S1PHA,F)	202203	202209	2	TOSHIBA	TK16J60W,S1VE(S	2	
202104	X33	TK20S04K3L(L1DN,NX	202203	202209	2	TOSHIBA	TK15S04N1L	3	
202104	X33	TK20S04K3L(L1JK,NQ	202203	202209	2	TOSHIBA	TK15S04N1L	3	
202104	X33	TK20S04K3L,LMTSQ(O	202203	202209	2	TOSHIBA	TK15S04N1L	3	
202104	X33	TK20S06K3L(L1CK,NQ	202203	202209	1	TOSHIBA	TK25S06N1L	3	
202104	X33	TK20S06K3L(L1DN,NX	202203	202209	1	TOSHIBA	TK25S06N1L	3	
202104	X33	TK20S06K3L(L1FD,NQ	202203	202209	1	TOSHIBA	TK25S06N1L	3	
202104	X33	TK20S06K3L(L1HD,NQ	202203	202209	1	TOSHIBA	TK25S06N1L	3	
202104	X33	TK20S06K3L,LMIYQ(O	202203	202209	1	TOSHIBA	TK25S06N1L	3	
202104	X33	TK20S06K3L,LXHQ(O	202203	202209	1	TOSHIBA	TK25S06N1L	3	
202104	X33	TK25A10K3(A,Q)	202203	202209	1	TOSHIBA	TK110A10PL	3	
202104	X33	TK25A10K3(Q,M)	202203	202209	1	TOSHIBA	TK110A10PL	3	
202104	X33	TK25A10K3(STA4,Q,M	202203	202209	1	TOSHIBA	TK110A10PL	3	
202104	X33	TK25A10K3,S5PSEQ(J	202203	202209	3	TOSHIBA	TK11S10N1L	3	
202104	X33	TK25A10K3,S5Q(J	202203	202209	1	TOSHIBA	TK110A10PL	3	
202104	X33	TK2Q60D(PHI,Q)	202203	202209	1	TOSHIBA	TK2Q60D,Q(VO	5	
202104	X33	TK2Q60D(PHI,V)	202203	202209	1	TOSHIBA	TK2Q60D,Q(VO	5	
202104	X33	TK30S06K3L(L1FJ,NQ	202203	202209	2	TOSHIBA	TK25S06N1L	3	
202104	X33	TK30S06K3L(T6L1,NQ	202203	202209	2	TOSHIBA	TK25S06N1L	3	
202104	X33	TK30S06K3L,LDNSX(O	202203	202209	2	TOSHIBA	TK25S06N1L	3	
202104	X33	TK30S06K3L,LPESQ(O	202203	202209	2	TOSHIBA	TK25S06N1L	3	
202104	X33	TK30S06K3L,LUSNQ(O	202203	202209	2	TOSHIBA	TK25S06N1L	3	
202104	X33	TK33A60V,S5SYEDX(M	202203	202209	2	TOSHIBA	TK090A65Z,S4X(S	2	
202104	X33	TK40J60U(COSEL,F)	202203	202209	3	TOSHIBA	TK065N65Z,S1F(S	2	
202104	X33	TK40P03M1(T6RSS-Q)	202203	202209	3	TOSHIBA	TPN8R903NL	3	
202104	X33	TK40S10K3Z(L1SM,NX	202203	202209	1	TOSHIBA	TK33S10N1Z	3	
202104	X33	TK40S10K3Z,LTOJX(O	202203	202209	1	TOSHIBA	TK33S10N1Z	3	
202104	X33	TK45J60V,S1MTS,Q(O	202203	202209	0			2	
202104	X33	TK45P03M1,RQ(S	202203	202209	3	TOSHIBA	TPN8R903NL	3	
202104	X33	TK45S06K3L(T6L1,NQ	202203	202209	1	TOSHIBA	TK40S06N1L	3	
202104	X33	TK45S06K3L,LCKQ(O	202203	202209	1	TOSHIBA	TK40S06N1L	3	
202104	X33	TK45S06K3L,LMTSQ(O	202203	202209	1	TOSHIBA	TK40S06N1L	3	
202104	X33	TK45S06K3L,LXHQ(O	202203	202209	1	TOSHIBA	TK40S06N1L	3	
202104	X33	TK4A60D(Q,M)	202203	202209	2	TOSHIBA	TK1K7A60F,S4X(S	2	
202104	X33	TK4A60D(STA4,A,Q)	202203	202209	2	TOSHIBA	TK1K7A60F,S4X(S	2	
202104	X33	TK4A60D,S4PBSQ(M	202203	202209	2	TOSHIBA	TK1K7A60F,S4X(S	2	
202104	X33	TK4A60D,S5Q(J	202203	202209	2	TOSHIBA	TK1K7A60F,S4X(S	2	
202104	X33	TK4A60DA(STA4,A,Q)	202203	202209	2	TOSHIBA	TK2K2A60F,S4X(S	2	
202104	X33	TK4A60DA(STA4,X,S)	202203	202209	2	TOSHIBA	TK2K2A60F,S4X(S	2	
202104	X33	TK4A60DA,S5Q(J	202203	202209	2	TOSHIBA	TK2K2A60F,S4X(S	2	
202104	X33	TK4A60DAR(Q,M)	202203	202209	2	TOSHIBA	TK2K2A60F,S4X(S	2	
202104	X33	TK4A60DAR(STA4,Q,M	202203	202209	2	TOSHIBA	TK2K2A60F,S4X(S	2	
202104	X33	TK4A60DAR(STA4,X,M	202203	202209	2	TOSHIBA	TK2K2A60F,S4X(S	2	
202104	X33	TK4A60DAR,S4X(S	202203	202209	2	TOSHIBA	TK2K2A60F,S4X(S	2	
202104	X33	TK50A04K3,Q(M	202203	202209	3	TOSHIBA	TK3R1P04PL	3	
202104	X33	TK50A04K3,S5Q(J	202203	202209	3	TOSHIBA	TK3R1P04PL	3	
202104	X33	TK50A04K3,S5Q(M	202203	202209	3	TOSHIBA	TK3R1P04PL	3	

202104	X33	TK50A04K3,S5SKKQ(M	202203	202209	3	TOSHIBA	TK3R1P04PL	3	
202104	X33	TK50J60U(COSEL,Q)	202203	202209	3	TOSHIBA	TK065N65Z,S1F(S	2	
202104	X33	TK50P03M1(T6RSS-Q)	202203	202209	3	TOSHIBA	TPH8R903NL	3	
202104	X33	TK50P04M1,RSOYQ(S	202203	202209	3	TOSHIBA	TPN7R504PL	3	
202104	X33	TK50S04K3L(L1AS,NX	202203	202209	1	TOSHIBA	TK65S04N1L	3	
202104	X33	TK50S04K3L(T6L1,NQ	202203	202209	1	TOSHIBA	TK65S04N1L	3	
202104	X33	TK50S04K3L,LCHQ(O	202203	202209	1	TOSHIBA	TK65S04N1L	3	
202104	X33	TK50S04K3L,LMTSQ(O	202203	202209	1	TOSHIBA	TK65S04N1L	3	
202104	X33	TK50S04K3L,LPAMQ(O	202203	202209	1	TOSHIBA	TK65S04N1L	3	
202104	X33	TK50S04K3L,LPPQ(O	202203	202209	1	TOSHIBA	TK65S04N1L	3	
202104	X33	TK65G10N1,RSOYQ(S	202203	202209	3	TOSHIBA	TPH3R70APL	3	
202104	X33	TK65S04K3L(L1AS,NX	202203	202209	1	TOSHIBA	TK65S04N1L	3	
202104	X33	TK65S04K3L(L1JE,NQ	202203	202209	1	TOSHIBA	TK65S04N1L	3	
202104	X33	TK65S04K3L,LBWQ(O	202203	202209	1	TOSHIBA	TK65S04N1L	3	
202104	X33	TK6A60D(S4TEJ,X,S)	202203	202209	2	TOSHIBA	TK1K2A60F,S4X(S	2	
202104	X33	TK6A60D,LS1NORIQ(M	202203	202209	0			2	
202104	X33	TK6A60D,LS1RICOQ(J	202203	202209	2	TOSHIBA	TK1K2A60F,S4X(S	2	
202104	X33	TK6A60D,LS1RICOQ(M	202203	202209	2	TOSHIBA	TK1K2A60F,S4X(S	2	
202104	X33	TK70J04K3Z(S1ELI,Q	202203	202209	3	TOSHIBA	TK1R4F04PB	3	
202104	X33	TK70J04K3Z(STA1,Q)	202203	202209	3	TOSHIBA	TK1R4F04PB	3	
202104	X33	TK70J06K3(STA1,Q)	202203	202209	3	TOSHIBA	TK90S06N1L	3	
202104	X33	TK75J04K3Z(LS5DN,Q	202203	202209	3	TOSHIBA	TK1R4F04PB	3	
202104	X33	TK75J04K3Z(STA1,Q)	202203	202209	3	TOSHIBA	TK1R4F04PB	3	
202104	X33	TK80A04K3L,S5Q(M	202203	202209	2	TOSHIBA	TK3R1A04PL	3	
202104	X33	TK80A08K3(A,Q)	202203	202209	1	TOSHIBA	TK4R1A10PL	3	
202104	X33	TK80A08K3(Q,M)	202203	202209	1	TOSHIBA	TK4R1A10PL	3	
202104	X33	TK80A08K3(S5FJ,Q,M	202203	202209	3	TOSHIBA	XPH4R10ANB	3	
202104	X33	TK80A08K3(S5PP,A,Q	202203	202209	3	TOSHIBA	XPH4R10ANB	3	
202104	X33	TK80A08K3(STA4,Q,M	202203	202209	1	TOSHIBA	TK4R1A10PL	3	
202104	X33	TK80A08K3,LS1DIQ(J	202203	202209	3	TOSHIBA	XPH4R10ANB	3	
202104	X33	TK80A08K3,LS1DIQ(M	202203	202209	3	TOSHIBA	XPH4R10ANB	3	
202104	X33	TK80A08K3,LS1PSQ(J	202203	202209	3	TOSHIBA	XPH4R10ANB	3	
202104	X33	TK80A08K3,S4MUQ(M	202203	202209	3	TOSHIBA	XPH4R10ANB	3	
202104	X33	TK80A08K3,S5FJTQ(M	202203	202209	3	TOSHIBA	XPH4R10ANB	3	
202104	X33	TK80A08K3,S5MUQ(J	202203	202209	3	TOSHIBA	XPH4R10ANB	3	
202104	X33	TK80A08K3,S5MUQ(M	202203	202209	3	TOSHIBA	XPH4R10ANB	3	
202104	X33	TK80A08K3,S5Q(J	202203	202209	1	TOSHIBA	TK4R1A10PL	3	
202104	X33	TK80A08K3A,S5Q(M	202203	202209	1	TOSHIBA	TK46A08N1	3	
202104	X33	TK80F08K3(4LTOJS,Q	202203	202209	3	TOSHIBA	XPH4R10ANB	3	
202104	X33	TK80F08K3(TE24L,Q)	202203	202209	3	TOSHIBA	XPH4R10ANB	3	
202104	X33	TK80F08K3,LVICQ(O	202203	202209	3	TOSHIBA	XPH4R10ANB	3	
202104	X33	TK80S04K3L(L1AS,NX	202203	202209	1	TOSHIBA	TK100S04N1L	3	
202104	X33	TK80S04K3L(L1CH,NQ	202203	202209	1	TOSHIBA	TK100S04N1L	3	
202104	X33	TK80S04K3L(L1HL,NQ	202203	202209	1	TOSHIBA	TK100S04N1L	3	
202104	X33	TK80S04K3L(L1JE,NQ	202203	202209	1	TOSHIBA	TK100S04N1L	3	
202104	X33	TK80S04K3L(L1MB,NQ	202203	202209	1	TOSHIBA	TK100S04N1L	3	
202104	X33	TK80S04K3L(L1SB,NQ	202203	202209	1	TOSHIBA	TK100S04N1L	3	
202104	X33	TK80S06K3L(L1HT,NQ	202203	202209	1	TOSHIBA	TK90S06N1L	3	
202104	X33	TK80S06K3L(L1KE,NQ	202203	202209	1	TOSHIBA	TK90S06N1L	3	
202104	X33	TK80S06K3L(L1MI,NQ	202203	202209	1	TOSHIBA	TK90S06N1L	3	
202104	X33	TK80S06K3L(L1YM,NX	202203	202209	1	TOSHIBA	TK90S06N1L	3	
202104	X33	TK80S06K3L,RQ(O	202203	202209	1	TOSHIBA	TK90S06N1L	3	

202104	X33	TK8A10K3,Q(M	202203	202209	1	TOSHIBA	TK22A10N1	3	
202104	X33	TK8A10K3,S5Q(J	202203	202209	1	TOSHIBA	TK22A10N1	3	
202104	X33	TK8A10K3,S5Q(M	202203	202209	1	TOSHIBA	TK22A10N1	3	
202104	X33	TK8A60DA(LBS1LG,QM	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA(LBS2PA,QM	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA(LS1CN,A,Q	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA(LS1CN,Q,M	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA(MURA,Q,M)	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA(STA4,A,Q)	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA(STA4,X,M)	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA(STA4,X,S)	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA,LS1LG2Q(M	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA,LS1LGQ(J	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA,LS1PAPQ(M	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA,LS1SHRQ(M	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA,S5COSEQ(J	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA,S5PSDQ(J	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TK8A60DA,S5Q(J	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	
202104	X33	TPC6008-H(TE85L,FM	202203	202209	3	TOSHIBA	SSM6K516NU	3	
202104	X33	TPC6008-H,LF(CJ	202203	202209	3	TOSHIBA	SSM6K516NU	3	
202104	X33	TPC6008-H,LF(CM	202203	202209	3	TOSHIBA	SSM6K516NU	3	
202104	X33	TPC6008-H,LPPF(CJ	202203	202209	3	TOSHIBA	SSM6K516NU	3	
202104	X33	TPC6008-H,LPPF(CM	202203	202209	3	TOSHIBA	SSM6K516NU	3	
202104	X33	TPC6009-H(TE85L,FM	202203	202209	3	TOSHIBA	SSM3K341R	3	
202104	X33	TPC6009-H,LF(CJ	202203	202209	3	TOSHIBA	SSM3K341R	3	
202104	X33	TPC6009-H,LF(CM	202203	202209	3	TOSHIBA	SSM3K341R	3	
202104	X33	TPC6009-H,LPEDF(CJ	202203	202209	3	TOSHIBA	SSM3K341R	3	
202104	X33	TPC6009-H,LPEDF(J	202203	202209	3	TOSHIBA	SSM3K341R	3	
202104	X33	TPC6010-H,LF(CJ	202203	202209	3	TOSHIBA	SSM3K341R	3	
202104	X33	TPC6010-H,LSINF(CM	202203	202209	3	TOSHIBA	SSM3K341R	3	
202104	X33	TPC6010-H,LSOYF(CM	202203	202209	3	TOSHIBA	SSM3K341R	3	
202104	X33	TPC6010-H,LYKOF(CM	202203	202209	3	TOSHIBA	SSM3K341R	3	
202104	X33	TPC6011(T5L,A,F)	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6011(T5RSONY,AF	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6011(T5RSONY,FM	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6011,LADF(CJ	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6011,LCSF(CJ	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6011,LF(CJ	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6011,LF(CM	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6011,LNKODF(CJ	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6011,LPANAF(CJ	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6011,LPANAF(CM	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6011,LPANAF(J	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6011,LPANAF(M	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6011,RSONYF(CJ	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6011,RSONYF(CM	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6012(T5L,A,F)	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012(T5LS,F,M)	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LADF(CJ	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LF(CJ	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LF(CM	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LMU3F(CJ	202203	202209	3	TOSHIBA	SSM3K123TU	3	

202104	X33	TPC6012,LMU3F(CM	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LMU3F(J	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LMU3F(M	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LNKODF(CM	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LPANAF(CJ	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LPANAF(CM	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LPANAF(J	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LPANAF(M	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LSF(CJ	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LSF(CM	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LSF(J	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LSONYF(CJ	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LSONYF(CM	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LSPPF(CJ	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6012,LSPPF(CM	202203	202209	3	TOSHIBA	SSM3K123TU	3	
202104	X33	TPC6067,LF(J	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6067,LF(M	202203	202209	3	TOSHIBA	SSM6K504NU	3	
202104	X33	TPC6103(T5LASA,A,F	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103(T5LASA,F,M	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103(T5LCAN,A,F	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103(T5LCAN,F,M	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103(T5LDNS,A,F	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103(T5LDNS,F,M	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103(T5RSON,A,F	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103(T5RSON,F,M	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103(TE85L,F,M)	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103,LCSF(J	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103,LF(J	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103,LJKTF(J	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103,LJKTF(M	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103,LWNLf(J	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6103,LWNLf(M	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6104,LPASF(M	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6104,LPAVF(M	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6106(T5LDNS,F,M	202203	202209	3	TOSHIBA	SSM6J808R	3	
202104	X33	TPC6110(T5L,A,F)	202203	202209	3	TOSHIBA	SSM3J340R	3	
202104	X33	TPC6110(T5RSONY,AF	202203	202209	3	TOSHIBA	SSM3J340R	3	
202104	X33	TPC6110(T5RSONY,FM	202203	202209	3	TOSHIBA	SSM3J340R	3	
202104	X33	TPC6110,LAPF(CM	202203	202209	3	TOSHIBA	SSM3J340R	3	
202104	X33	TPC6110,LF(CJ	202203	202209	3	TOSHIBA	SSM3J340R	3	
202104	X33	TPC6110,LWNLf(J	202203	202209	3	TOSHIBA	SSM3J340R	3	
202104	X33	TPC6110,LWNLf(M	202203	202209	3	TOSHIBA	SSM3J340R	3	
202104	X33	TPC6110,RSONYF(CJ	202203	202209	3	TOSHIBA	SSM3J340R	3	
202104	X33	TPC6110,RSONYF(CM	202203	202209	3	TOSHIBA	SSM3J340R	3	
202104	X33	TPC6111(T5L,A,F)	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111(T5LPSD,A,F	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111(T5LPSD,F,M	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LADF(CJ	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LF(CJ	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPANAF(CJ	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPANAF(CM	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPANAF(J	202203	202209	3	TOSHIBA	SSM3J378R	3	

202104	X33	TPC6111,LPANAF(M	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPASF(CJ	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPASF(CM	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPASF(J	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPAVF(CJ	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPAVF(CM	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPAVF(J	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPAVF(M	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPSDF(CJ	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPSDF(CM	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPSEF(CJ	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPSEF(J	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6111,LPSEF(M	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113(T5L,A,F)	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113(T5LDNS,A,C	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113(T5LDNS,A,F	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113(T5RSONY,AF	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113(T5RSONY,FM	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113,LAWF(CM	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113,LCSF(CJ	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113,LDNSOF(CJ	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113,LF(CJ	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113,LMSKF(CJ	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113,LMSKF(J	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113,RF(CM	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113,RSONYF(CJ	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6113,RSONYF(CM	202203	202209	3	TOSHIBA	SSM3J378R	3	
202104	X33	TPC6130,LF(CJ	202203	202209	3	TOSHIBA	SSM3J377R	3	
202104	X33	TPC6130,LF(CM	202203	202209	3	TOSHIBA	SSM3J377R	3	
202104	X33	TPC6130,LF(J	202203	202209	3	TOSHIBA	SSM3J377R	3	
202104	X33	TPC6130,LF(M	202203	202209	3	TOSHIBA	SSM3J377R	3	
202104	X33	TPC8046-H(TE12L,V	202203	202209	2	TOSHIBA	TPH6R004PL	3	
202104	X33	TPC8047-H(TE12L,V	202203	202209	2	TOSHIBA	TPN7R504PL	3	
202104	X33	TPC8049-H(T2LPP,V	202203	202209	3	TOSHIBA	TK40S06N1L	3	
202104	X33	TPC8049-H(TE12L,V	202203	202209	2	TOSHIBA	TPH11006NL	3	
202104	X33	TPC8051-H(TE12L,V	202203	202209	3	TOSHIBA	TPN8R408QM	3	
202104	X33	TPC8052-H(T2LMTS,V	202203	202209	3	TOSHIBA	SSM6K514NU	3	
202104	X33	TPC8052-H(T2LPP,V	202203	202209	3	TOSHIBA	SSM6K514NU	3	
202104	X33	TPC8052-H(TE12L,V	202203	202209	3	TOSHIBA	SSM6K514NU	3	
202104	X33	TPC8053-H(T2LPAI,V	202203	202209	3	TOSHIBA	TPCP8012	3	
202104	X33	TPC8053-H(TE12L,V	202203	202209	3	TOSHIBA	TPCP8012	3	
202104	X33	TPC8089-H,LQ(S	202203	202209	3	TOSHIBA	SSM3K341R	3	
202104	X33	TPC8123(TE12L,V	202203	202209	2	TOSHIBA	TPC8125	3	
202104	X33	TPC8124(T2LAST,V	202203	202209	3	TOSHIBA	TJ60S04M3L	3	
202104	X33	TPC8124(T2LCLAR,V	202203	202209	3	TOSHIBA	TJ60S04M3L	3	
202104	X33	TPC8124(T2LHSN,V	202203	202209	3	TOSHIBA	TJ60S04M3L	3	
202104	X33	TPC8124(T2LPAV,V	202203	202209	2	TOSHIBA	TPC8133	3	
202104	X33	TPC8128(T2LSAN,V	202203	202209	3	TOSHIBA	TPCA8128	3	
202104	X33	TPC8128(TE12L,V	202203	202209	3	TOSHIBA	TPC8125	3	
202104	X33	TPCA8045-H(2L1PP,V	202203	202209	3	TOSHIBA	XP3R804NC	3	
202104	X33	TPCA8045-H(T2L1,V	202203	202209	2	TOSHIBA	TPH3R704PL	3	
202104	X33	TPCA8046-H(T2L1,V	202203	202209	2	TOSHIBA	TPH6R004PL	3	

202104	X33	TPCA8046-H(T2L1,VM	202203	202209	2	TOSHIBA	TPH6R004PL	3	
202104	X33	TPCA8047-H(T2L1,V)	202203	202209	2	TOSHIBA	TPH7R204PL	3	
202104	X33	TPCA8047-H(T2L1,VM	202203	202209	2	TOSHIBA	TPH7R204PL	3	
202104	X33	TPCA8047-H,L1CQ(CM	202203	202209	3	TOSHIBA	XPN7R104NC	3	
202104	X33	TPCA8048-H(T2L1,V)	202203	202209	2	TOSHIBA	TPH7R006PL	3	
202104	X33	TPCA8048-H(T2L1,VM	202203	202209	2	TOSHIBA	TPH7R006PL	3	
202104	X33	TPCA8049-H(2LMU1,Q	202203	202209	3	TOSHIBA	TK40S06N1L	3	
202104	X33	TPCA8049-H(T2L1,V)	202203	202209	2	TOSHIBA	TPH9R506PL	3	
202104	X33	TPCA8049-H(T2L1,VM	202203	202209	2	TOSHIBA	TPH9R506PL	3	
202104	X33	TPCA8049-H,LQ(O	202203	202209	2	TOSHIBA	TPH9R506PL	3	
202104	X33	TPCA8051-H(T2L1,V)	202203	202209	2	TOSHIBA	TPH8R008NH	3	
202104	X33	TPCA8051-H(T2L1PPV	202203	202209	3	TOSHIBA	TK33S10N1L	3	
202104	X33	TPCA8051-H(T2LPP,X	202203	202209	3	TOSHIBA	TK33S10N1L	3	
202104	X33	TPCA8053-H(2L1ASVM	202203	202209	3	TOSHIBA	TPCP8012	3	
202104	X33	TPCA8053-H(2L1HL,V	202203	202209	3	TOSHIBA	TPCP8012	3	
202104	X33	TPCA8053-H(2L1HLVM	202203	202209	3	TOSHIBA	TPCP8012	3	
202104	X33	TPCA8053-H(2LMU1,Q	202203	202209	3	TOSHIBA	TPCP8012	3	
202104	X33	TPCA8053-H(2LMU3,Q	202203	202209	3	TOSHIBA	TPCP8012	3	
202104	X33	TPCA8053-H(T2L1,AV	202203	202209	3	TOSHIBA	TPH7R006PL	3	
202104	X33	TPCA8053-H(T2L1,V)	202203	202209	3	TOSHIBA	TPH7R006PL	3	
202104	X33	TPCA8053-H(T2L1,VM	202203	202209	3	TOSHIBA	TPH7R006PL	3	
202104	X33	TPCA8053-H(T2L1PPV	202203	202209	3	TOSHIBA	TPCP8012	3	
202104	X33	TPCA8053-H,L1ASV(O	202203	202209	3	TOSHIBA	TPCP8012	3	
202104	X33	TPCA8083,L1Q(O	202203	202209	1	TOSHIBA	TPH2R104PL	3	
202104	X33	TPCA8121(2L1FJT,VM	202203	202209	2	TOSHIBA	XPH3R114MC	3	
202104	X33	TPCA8121(2L1TYG,VM	202203	202209	2	TOSHIBA	XPH3R114MC	3	
202104	X33	TPCA8121(T2L1TYG,V	202203	202209	2	TOSHIBA	XPH3R114MC	3	
202104	X33	TPCA8121(TE12L1,V)	202203	202209	2	TOSHIBA	XPH3R114MC	3	
202104	X33	TPCA8121,L1Q(CM	202203	202209	2	TOSHIBA	XPH3R114MC	3	
202104	X33	TPCA8124,L1Q(O	202203	202209	3	TOSHIBA	XPN9R614MC	3	
202104	X33	TPCC8103,L1Q(CJ	202203	202209	1	TOSHIBA	TPCC8104	3	
202104	X33	TPCC8103,L1Q(CM	202203	202209	1	TOSHIBA	TPCC8104	3	
202104	X33	TPCC8103,L1V25Q(CM	202203	202209	1	TOSHIBA	TPCC8104	3	
202104	X33	TPCP8007-H(5LMU1,F	202203	202209	3	TOSHIBA	SSM3K341R	3	
202104	X33	TPCP8204(BRA,F)	202203	202209	3	TOSHIBA	SSM6N55NU	3	
202104	X33	TPCP8204(T5LCANO,F	202203	202209	3	TOSHIBA	SSM6N55NU	3	
202104	X35	1500FXFGZ71(P)	202203	202209	1	TOSHIBA	1500FXFGZ71(P1)	4	
202104	X35	2SA1200-Y(2LONK,ZE	202203	202209	2	TOSHIBA	2SA1201-Y(TE12L,ZC	4	
202104	X35	2SA1200-Y(T2LHM,CF	202203	202209	1	TOSHIBA	2SA1200-Y(T2LXG,ZF	4	
202104	X35	2SA1201-Y(2LITW,CF	202203	202209	1	TOSHIBA	2SA1201-Y(T2LXG,ZC	4	
202104	X35	2SA1201-Y(2LMBI,CF	202203	202209	1	TOSHIBA	2SA1201-Y(T2LXG,ZC	4	
202104	X35	2SA1201-Y(C,F)	202203	202209	1	TOSHIBA	2SA1201-Y(TE12L,ZC	4	
202104	X35	2SA1201-Y(T2LAS,CF	202203	202209	1	TOSHIBA	2SA1201-Y(T2LXG,ZC	4	
202104	X35	2SA1201-Y(T2LBSHCF	202203	202209	1	TOSHIBA	2SA1201-Y(T2LXG,ZC	4	
202104	X35	2SA1201-Y(T2LHI,CF	202203	202209	1	TOSHIBA	2SA1201-Y(T2LXG,ZC	4	
202104	X35	2SA1201-Y(T2LNSECF	202203	202209	1	TOSHIBA	2SA1201-Y(T2LXG,ZC	4	
202104	X35	2SA1201-Y(T2LPEDCF	202203	202209	1	TOSHIBA	2SA1201-Y(T2LXG,ZC	4	
202104	X35	2SA1201-Y(T2LSOYCF	202203	202209	1	TOSHIBA	2SA1201-Y(T2LXG,ZC	4	
202104	X35	2SA1201-Y(T2LTR,CF	202203	202209	1	TOSHIBA	2SA1201-Y(T2LXG,ZC	4	
202104	X35	2SA1201-Y(T2LYZKCF	202203	202209	1	TOSHIBA	2SA1201-Y(T2LXG,ZC	4	
202104	X35	2SA1201-Y(T2RKD,CF	202203	202209	1	TOSHIBA	2SA1201-Y(T2RXG,ZC	4	
202104	X35	2SA1213-O(C,F)	202203	202209	1	TOSHIBA	2SA1213-Y(Te12L,ZC	4	

202104	X35	2SA1213-O(SONY,CF)	202203	202209	1	TOSHIBA	2SA1213-Y(T2LXG,ZC	4		
202104	X35	2SA1213-O(T2LFJTCTF	202203	202209	1	TOSHIBA	2SA1213-Y(T2LXG,ZC	4		
202104	X35	2SA1213-O(T2LSONYF	202203	202209	1	TOSHIBA	2SA1213-Y(T2LXG,ZC	4		
202104	X35	2SA1213-Y(C,F)	202203	202209	1	TOSHIBA	2SA1213-Y(TE12L,ZC	4		
202104	X35	2SA1213-Y(SONY,CF)	202203	202209	1	TOSHIBA	2SA1213-Y(T2LXG,ZC	4		
202104	X35	2SA1213-Y(T2LAL,CF	202203	202209	1	TOSHIBA	2SA1213-Y(T2LAL,ZF	4		
202104	X35	2SA1213-Y(T2LAOICF	202203	202209	1	TOSHIBA	2SA1213-Y(T2LXG,ZC	4		
202104	X35	2SA1213-Y(T2LCANOF	202203	202209	1	TOSHIBA	2SA1213-Y(T2LXG,ZC	4		
202104	X35	2SA1213-Y(T2LH,CF)	202203	202209	1	TOSHIBA	2SA1213-Y(TE12L,ZC	4		
202104	X35	2SA1213-Y(T2LMBSCF	202203	202209	1	TOSHIBA	2SA1213-Y(T2LXG,ZC	4		
202104	X35	2SA1213-Y(T2LMT1CF	202203	202209	1	TOSHIBA	2SA1213-Y(T2LXG,ZC	4		
202104	X35	2SA1213-Y(T2LNCN,F	202203	202209	1	TOSHIBA	2SA1213-Y(T2LXG,ZC	4		
202104	X35	2SA1213-Y(T2LOMICF	202203	202209	1	TOSHIBA	2SA1213-Y(T2LXG,ZC	4		
202104	X35	2SA1213-Y(T2LPP,CF	202203	202209	1	TOSHIBA	2SA1213-Y(T2LPP,ZC	4		
202104	X35	2SA1213-Y(T2LTLTCF	202203	202209	1	TOSHIBA	2SA1213-Y(T2LXG,ZC	4		
202104	X35	2SA1213-Y(T2RFNCCF	202203	202209	1	TOSHIBA	2SA1213-Y(T2RXG,ZC	4		
202104	X35	2SA1213-Y(T2RPP,CF	202203	202209	1	TOSHIBA	2SA1213-Y(T2RPP,ZC	4		
202104	X35	2SA1213-Y(T2RSINCF	202203	202209	1	TOSHIBA	2SA1213-Y(T2RXG,ZC	4		
202104	X35	2SA1213-Y(TE12L,F)	202203	202209	1	TOSHIBA	2SA1213-Y(TE12L,ZC	4		
202104	X35	2SA1213-Y(TE12R,F)	202203	202209	1	TOSHIBA	2SA1213-Y(TE12R,ZC	4		
202104	X35	2SA1483-Y(F)	202203	202209	2	TOSHIBA	2SA2070(TE12L,F)	4		
202104	X35	2SA1681(T2LSIND,F)	202203	202209	1	TOSHIBA	2SA1681(T2LXG,ZC)	4		
202104	X35	2SA1681(T2LTOLT,F)	202203	202209	1	TOSHIBA	2SA1681(T2LXG,ZC)	4		
202104	X35	2SA1736(2LMBSFK2,F	202203	202209	1	TOSHIBA	2SA1736(2LMBSPW,ZF	4		
202104	X35	2SA1736(F)	202203	202209	1	TOSHIBA	2SA1736(TE12L,ZC)	4		
202104	X35	2SA1736(T2LCLARI,F	202203	202209	1	TOSHIBA	2SA1736(T2LXG,ZC)	4		
202104	X35	2SA1736(T2LFD,F)	202203	202209	1	TOSHIBA	2SA1736(T2LXG,ZC)	4		
202104	X35	2SA1736(T2LHITC,F)	202203	202209	1	TOSHIBA	2SA1736(T2LXG,ZC)	4		
202104	X35	2SA1736(T2LHITJ,F)	202203	202209	1	TOSHIBA	2SA1736(T2LXG,ZC)	4		
202104	X35	2SA1736(T2LMDS,F)	202203	202209	1	TOSHIBA	2SA1736(T2LXG,ZC)	4		
202104	X35	2SA1736(T2LSANKD,F	202203	202209	1	TOSHIBA	2SA1736(T2LXG,ZC)	4		
202104	X35	2SA1736(T2LTOYOG,F	202203	202209	1	TOSHIBA	2SA1736(T2LXG,ZC)	4		
202104	X35	2SA1736(T2LYAZK,F)	202203	202209	1	TOSHIBA	2SA1736(T2LYAZK,ZF	4		
202104	X35	2SA1736(T2RFANUC,F	202203	202209	1	TOSHIBA	2SA1736(T2RXG,ZC)	4		
202104	X35	2SA1736(T2RSIND,F)	202203	202209	1	TOSHIBA	2SA1736(T2RXG,ZC)	4		
202104	X35	2SA1971(T2LPCC,F)	202203	202209	1	TOSHIBA	2SA1971(T2LXG,ZF)	4		
202104	X35	2SA2058(T5LPED,F)	202203	202209	1	TOSHIBA	2SA2065(T2LXG,ZF)	4		
202104	X35	2SA2058(T5LSONY,F)	202203	202209	1	TOSHIBA	2SA2065(T2LXG,ZF)	4		
202104	X35	2SA2058(TE85L,F)	202203	202209	1	TOSHIBA	2SA2065(TE85L,F)	4		
202104	X35	2SA2059(T2LHIT,F)	202203	202209	1	TOSHIBA	2SA2059(T2LXG,ZF)	4		
202104	X35	2SA2059(T2LPP,F)	202203	202209	1	TOSHIBA	2SA2059(T2LPP,ZF)	4		
202104	X35	2SA2059(T2LSONY,F)	202203	202209	1	TOSHIBA	2SA2059(T2LXG,ZF)	4		
202104	X35	2SA2059(T2RNMT,F)	202203	202209	1	TOSHIBA	2SA2059(T2RXG,ZF)	4		
202104	X35	2SA2060(T2LDIAMO,F	202203	202209	1	TOSHIBA	2SA2060(T2LXG,ZF)	4		
202104	X35	2SA2060(T2LHITM,F)	202203	202209	1	TOSHIBA	2SA2060(T2LXG,ZF)	4		
202104	X35	2SA2060(T2LHNDLK,F	202203	202209	1	TOSHIBA	2SA2060(T2LXG,ZF)	4		
202104	X35	2SA2060(T2LMBSK,F)	202203	202209	1	TOSHIBA	2SA2060(2LMBS2,ZF	4		
202104	X35	2SA2060(T2LMTD,F)	202203	202209	1	TOSHIBA	2SA2060(T2LXG,ZF)	4		
202104	X35	2SA2060(T2LPSS,F)	202203	202209	1	TOSHIBA	2SA2060(T2LXG,ZF)	4		
202104	X35	2SA2060(T2LRT,F)	202203	202209	1	TOSHIBA	2SA2060(T2LXG,ZF)	4		
202104	X35	2SA2060(T2LSIND,F)	202203	202209	1	TOSHIBA	2SA2060(T2LSIND,ZF	4		
202104	X35	2SA2060(T2LTOLT,F)	202203	202209	1	TOSHIBA	2SA2060(T2LXG,ZF)	4		

202104	X35	2SA2066(T2LPP,F)	202203	202209	1	TOSHIBA	2SA2069(TE12L,ZF)	4	
202104	X35	2SA2066(TE12L,F)	202203	202209	1	TOSHIBA	2SA2069(TE12L,ZF)	4	
202104	X35	2SA2070(T2LALPINEF)	202203	202209	1	TOSHIBA	2SA2070(T2LXG,ZF)	4	
202104	X35	2SA2070(T2LALPS,F)	202203	202209	1	TOSHIBA	2SA2070(T2LXG,ZF)	4	
202104	X35	2SA2070(T2LASHI,F)	202203	202209	1	TOSHIBA	2SA2070(T2LXG,ZF)	4	
202104	X35	2SA2070(T2LCLAR,F)	202203	202209	1	TOSHIBA	2SA2070(T2LXG,ZF)	4	
202104	X35	2SA2070(T2LHITJ,F)	202203	202209	1	TOSHIBA	2SA2070(T2LXG,ZF)	4	
202104	X35	2SA2070(T2LJTEK,F)	202203	202209	1	TOSHIBA	2SA2070(T2LXG,ZF)	4	
202104	X35	2SA2070(T2LPAV,F)	202203	202209	1	TOSHIBA	2SA2070(T2LXG,ZF)	4	
202104	X35	2SA2070(T2LPP,F)	202203	202209	1	TOSHIBA	2SA2070(T2LPP,ZF)	4	
202104	X35	2SA2070(T2LRT,F)	202203	202209	1	TOSHIBA	2SA2070(T2LXG,ZF)	4	
202104	X35	2SA2070(T2LSIND,F)	202203	202209	1	TOSHIBA	2SA2070(T2LXG,ZF)	4	
202104	X35	2SA2184(T6L1PCC,NQ)	202203	202209	1	TOSHIBA	2SA2184(TE16L1,NV)	3	
202104	X35	2SA2184(TE16L1,NQ)	202203	202209	1	TOSHIBA	2SA2184(TE16L1,NV)	3	
202104	X35	2SA2206(T2LHILX,F)	202203	202209	1	TOSHIBA	2SA2206(T2LHILX,ZF)	4	
202104	X35	2SC2873-O(C,F)	202203	202209	1	TOSHIBA	2SC2873-Y(TE12L,ZC)	4	
202104	X35	2SC2873-O(T2LCLACF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-O(T2LKENCF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-O(T2LSONYF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(C,F)	202203	202209	1	TOSHIBA	2SC2873-Y(TE12L,ZC)	4	
202104	X35	2SC2873-Y(F)	202203	202209	1	TOSHIBA	2SC2873-Y(TE12L,ZC)	4	
202104	X35	2SC2873-Y(T2LAW,CF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LCA-OF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LCOSEF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LD,ZC)	202203	202209	0			5	
202104	X35	2SC2873-Y(T2LDI,CF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LH,CF)	202203	202209	1	TOSHIBA	2SC2873-Y(TE12L,ZC)	4	
202104	X35	2SC2873-Y(T2LHITJF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LKENCF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LMATCF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LMBSCF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LMT1CF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LNCN,F)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LNSECF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LOMICF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LPP,CF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LPP,ZC)	4	
202104	X35	2SC2873-Y(T2LSNK,F)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LSONYF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LSUM,F)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LSZKCF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LTLTCF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LTO,CF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LTOYCF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2LYZKCF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2LXG,ZC)	4	
202104	X35	2SC2873-Y(T2RCN,CF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2RXG,ZC)	4	
202104	X35	2SC2873-Y(T2RD,ZC)	202203	202209	0			5	
202104	X35	2SC2873-Y(T2RIBM,F)	202203	202209	1	TOSHIBA	2SC2873-Y(T2RXG,ZC)	4	
202104	X35	2SC2873-Y(T2RKD,CF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2RXG,ZC)	4	
202104	X35	2SC2873-Y(T2RSINCF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2RXG,ZC)	4	
202104	X35	2SC2873-Y(T2RTOYCF)	202203	202209	1	TOSHIBA	2SC2873-Y(T2RXG,ZC)	4	
202104	X35	2SC2873-Y(TE12L,F)	202203	202209	1	TOSHIBA	2SC2873-Y(TE12L,ZC)	4	
202104	X35	2SC2873-Y(TE12L,KF)	202203	202209	1	TOSHIBA	2SC2873-Y(TE12L,ZC)	4	

202104	X35	2SC2873-Y(TE12R,F)	202203	202209	1	TOSHIBA	2SC2873-Y(TE12R,ZC	4	
202104	X35	2SC2880-Y(2LONK,ZE	202203	202209	2	TOSHIBA	2SC2881-Y(TE12L,ZC	4	
202104	X35	2SC2880-Y(T2LHM,CF	202203	202209	1	TOSHIBA	2SC2880-Y(T2LXG,ZF	4	
202104	X35	2SC2881-Y(2LHILX,F	202203	202209	1	TOSHIBA	2SC2881-Y(LHILX,ZC	4	
202104	X35	2SC2881-Y(2LITW,CF	202203	202209	1	TOSHIBA	2SC2881-Y(T2LXG,ZC	4	
202104	X35	2SC2881-Y(2LUS1,CF	202203	202209	1	TOSHIBA	2SC2881-Y(T2LUS,ZF	4	
202104	X35	2SC2881-Y(C,F)	202203	202209	1	TOSHIBA	2SC2881-Y(TE12L,ZC	4	
202104	X35	2SC2881-Y(T2LBHCF	202203	202209	1	TOSHIBA	2SC2881-Y(T2LXG,ZC	4	
202104	X35	2SC2881-Y(T2LCANOF	202203	202209	1	TOSHIBA	2SC2881-Y(T2LXG,ZC	4	
202104	X35	2SC2881-Y(T2LCOSEF	202203	202209	1	TOSHIBA	2SC2881-Y(T2LXG,ZC	4	
202104	X35	2SC2881-Y(T2LHG,CF	202203	202209	1	TOSHIBA	2SC2881-Y(T2LXG,ZC	4	
202104	X35	2SC2881-Y(T2LKO,CF	202203	202209	1	TOSHIBA	2SC2881-Y(T2LXG,ZC	4	
202104	X35	2SC2881-Y(T2LMBSCF	202203	202209	1	TOSHIBA	2SC2881-Y(2LMBS,ZC	4	
202104	X35	2SC2881Y(T2LNAMICF	202203	202209	1	TOSHIBA	2SC2881-Y(T2LXG,ZC	4	
202104	X35	2SC2881-Y(T2LNS,CF	202203	202209	1	TOSHIBA	2SC2881-Y(T2LXG,ZC	4	
202104	X35	2SC2881-Y(T2LSANCF	202203	202209	1	TOSHIBA	2SC2881-Y(T2LXG,ZC	4	
202104	X35	2SC2881-Y(T2LTLT,F	202203	202209	1	TOSHIBA	2SC2881-Y(T2LXG,ZC	4	
202104	X35	2SC2881-Y(T2LTORIF	202203	202209	1	TOSHIBA	2SC2881-Y(T2LTR,ZC	4	
202104	X35	2SC2881-Y(T2LYKOCF	202203	202209	1	TOSHIBA	2SC2881-Y(2LYKO,ZC	4	
202104	X35	2SC2881-Y(T2LYZKCF	202203	202209	1	TOSHIBA	2SC2881-Y(2LYZK,ZF	4	
202104	X35	2SC2881-Y(T2RFNCCF	202203	202209	1	TOSHIBA	2SC2881-Y(T2RXG,ZC	4	
202104	X35	2SC2881-Y(T2RSINCF	202203	202209	1	TOSHIBA	2SC2881-Y(T2RXG,ZC	4	
202104	X35	2SC4409(F)	202203	202209	1	TOSHIBA	2SC4409(TE12L,ZC)	4	
202104	X35	2SC4409(T2LASAW,F)	202203	202209	1	TOSHIBA	2SC4409(T2LXG,ZC)	4	
202104	X35	2SC4409(T2LSIND,F)	202203	202209	1	TOSHIBA	2SC4409(T2LXG,ZC)	4	
202104	X35	2SC4409(T2LTOLT,F)	202203	202209	1	TOSHIBA	2SC4409(T2LXG,ZC)	4	
202104	X35	2SC4409(TE12L,PP,F	202203	202209	1	TOSHIBA	2SC4409(T2LPP,ZC)	4	
202104	X35	2SC4541(2LMBSFK2,F	202203	202209	1	TOSHIBA	2SC4541(2LMBSPW,ZF	4	
202104	X35	2SC4541(F)	202203	202209	1	TOSHIBA	2SC4541(TE12L,ZC)	4	
202104	X35	2SC4541(T2LFANUC,F	202203	202209	1	TOSHIBA	2SC4541(T2LXG,ZC)	4	
202104	X35	2SC4541(T2LFD,F)	202203	202209	1	TOSHIBA	2SC4541(T2LXG,ZC)	4	
202104	X35	2SC4541(T2LHITJ,F)	202203	202209	1	TOSHIBA	2SC4541(T2LXG,ZC)	4	
202104	X35	2SC4541(T2LHNDLK,F	202203	202209	1	TOSHIBA	2SC4541(T2LXG,ZC)	4	
202104	X35	2SC4541(T2LKEHIN,F	202203	202209	1	TOSHIBA	2SC4541(T2LXG,ZC)	4	
202104	X35	2SC4541(T2LMDS,F)	202203	202209	1	TOSHIBA	2SC4541(T2LXG,ZC)	4	
202104	X35	2SC4541(T2LOMII,F)	202203	202209	1	TOSHIBA	2SC4541(T2LXG,ZC)	4	
202104	X35	2SC4541(T2LSLC,F)	202203	202209	1	TOSHIBA	2SC4541(T2LXG,ZC)	4	
202104	X35	2SC4541(T2LTOLT,F)	202203	202209	1	TOSHIBA	2SC4541(T2LXG,ZC)	4	
202104	X35	2SC4541(T2LTOYOG,F	202203	202209	1	TOSHIBA	2SC4541(T2LXG,ZC)	4	
202104	X35	2SC5307(T2LNAPI,ZF	202203	202209	1	TOSHIBA	TTC018(T2LXG,ZF)	4	
202104	X35	2SC5712(T2LHTL,F)	202203	202209	1	TOSHIBA	2SC5712(T2LXG,ZF)	4	
202104	X35	2SC5712(T2LMITSU,F	202203	202209	1	TOSHIBA	2SC5712(T2LXG,ZF)	4	
202104	X35	2SC5712(T2LNDS-S,F	202203	202209	1	TOSHIBA	2SC5712(TE12L,ZF)	4	
202104	X35	2SC5712(T2LPP,F)	202203	202209	1	TOSHIBA	2SC5712(T2LPP,ZF)	4	
202104	X35	2SC5712(T2LRT,F)	202203	202209	1	TOSHIBA	2SC5712(T2LXG,ZF)	4	
202104	X35	2SC5712(T2LSIND,F)	202203	202209	1	TOSHIBA	2SC5712(T2LXG,ZF)	4	
202104	X35	2SC5712(T2LSONY,F)	202203	202209	1	TOSHIBA	2SC5712(T2LXG,ZF)	4	
202104	X35	2SC5712(T2LTEA,F)	202203	202209	1	TOSHIBA	2SC5712(TE12L,ZF)	4	
202104	X35	2SC5713(TE12L,ZC)	202203	202209	1	TOSHIBA	2SC5714(TE12L,ZF)	4	
202104	X35	2SC5755(TE85L,F)	202203	202209	2	TOSHIBA	2SC5784(TE85L,F)	4	
202104	X35	2SC5785(T2LDM,ZF)	202203	202209	2	TOSHIBA	2SC5819(T2LXG,ZF)	4	
202104	X35	2SC5785(T2LHOTI,ZF	202203	202209	2	TOSHIBA	2SC5819(T2LXG,ZF)	4	

202104	X35	2SC5785(T2LSIND,F)	202203	202209	2	TOSHIBA	2SC5819(T2LXG,ZF)	4	
202104	X35	2SC5810(T2LASHI,F)	202203	202209	1	TOSHIBA	2SC5810(T2LXG,ZF)	4	
202104	X35	2SC5810(T2LCLAR,F)	202203	202209	1	TOSHIBA	2SC5810(T2LXG,ZF)	4	
202104	X35	2SC5810(T2LJTEK,F)	202203	202209	1	TOSHIBA	2SC5810(T2LXG,ZF)	4	
202104	X35	2SC5810(T2LMATUD,F)	202203	202209	1	TOSHIBA	2SC5810(T2LXG,ZF)	4	
202104	X35	2SC5810(T2LNITOK,F)	202203	202209	1	TOSHIBA	2SC5810(T2LXG,ZF)	4	
202104	X35	2SC5810(T2LPP,F)	202203	202209	1	TOSHIBA	2SC5810(T2LPP,ZF)	4	
202104	X35	2SC5810(T2LRT,F)	202203	202209	1	TOSHIBA	2SC5810(T2LXG,ZF)	4	
202104	X35	2SC5810(T2LSCMD,F)	202203	202209	1	TOSHIBA	2SC5810(T2LXG,ZF)	4	
202104	X35	2SC5906(T5LCHINONF)	202203	202209	2	TOSHIBA	2SC5976,LXGF(O	4	
202104	X35	2SC5906(T5LFUNAI,F)	202203	202209	2	TOSHIBA	2SC5976,LXGF(O	4	
202104	X35	2SC5906(T5LSTANR,F)	202203	202209	2	TOSHIBA	2SC5976,LXGF(O	4	
202104	X35	2SC6125(TE12L,C,ZE)	202203	202209	2	TOSHIBA	2SC6126(TE12L,ZF)	4	
202104	X35	2SC6125(TE12L,ZF)	202203	202209	2	TOSHIBA	2SC6126(TE12L,ZF)	4	
202104	X35	2SD1784(T2LNDSK,CF)	202203	202209	2	TOSHIBA	2SD2686(T2LXG,ZC)	4	
202104	X35	2SD2686(T2LPP,F)	202203	202209	1	TOSHIBA	2SD2686(T2LPP,ZC)	4	
202104	X35	CMC02(T2L,CANO,AQ)	202203	202209	2	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMC02(T2L,TEM,Q)	202203	202209	2	TOSHIBA	CMG03A,LQ(M	4	
202104	X35	CMC02(TE12L,Q,M)	202203	202209	2	TOSHIBA	CMG03A,LQ(M	4	
202104	X35	CMC02,LCSQ(J	202203	202209	0			5	
202104	X35	CMC02,LWNLQ(J	202203	202209	2	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMF01(T2L,DIAMO,Q)	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF01(T2L,SANYU,Q)	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF01(T2L,TEMQ)	202203	202209	1	TOSHIBA	CMF01A,LQ(M	4	
202104	X35	CMF01(TE12L,Q,M)	202203	202209	1	TOSHIBA	CMF01A,LQ(M	4	
202104	X35	CMF01(TE12R,Q,M)	202203	202209	1	TOSHIBA	CMF01A,RQ(M	4	
202104	X35	CMF01,LCSQ(J	202203	202209	0			5	
202104	X35	CMF01,LDIAMOQ(J	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF01,LDIAMOQ(M	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF01,LFUKUDQ(M	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF01,LHITJQ(M	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF01,LPANAQ(J	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF01,LPANAQ(M	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF01,LPASQ(O	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF01,LSANYUQ(J	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF01,LSANYUQ(M	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF01,LSONYQ(M	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF01,LWNLQ(J	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF01,LXGQ(M	202203	202209	1	TOSHIBA	CMF01A,LXGQ(M	4	
202104	X35	CMF02(T2L,APN,Q)	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02(T2L,HONDA,Q)	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02(T2L,SONY,QM)	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02(T2L,TEMQ)	202203	202209	1	TOSHIBA	CMF02A,LQ(M	4	
202104	X35	CMF02(T2L,TOYG,QM)	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02(T2L,YAZS,AQ)	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02(T2LSONY,A,Q)	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02(TE12L,PSD,Q)	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02(TE12L,Q)	202203	202209	1	TOSHIBA	CMF02A,LQ(M	4	
202104	X35	CMF02(TE12L,Q,M)	202203	202209	1	TOSHIBA	CMF02A,LQ(M	4	
202104	X35	CMF02(TE12L,TBI,Q)	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02(TE12R,Q,M)	202203	202209	1	TOSHIBA	CMF02A,RQ(M	4	
202104	X35	CMF02(TE12R,TEM,Q)	202203	202209	1	TOSHIBA	CMF02A,RQ(M	4	

202104	X35	CMF02,LAPNQ(M	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02,LCSQ(J	202203	202209	0			5	
202104	X35	CMF02,LHONDAQ(J	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02,LHONDAQ(M	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02,LMBDQ(M	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02,LPANAQ(J	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02,LPANAQ(M	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02,LPSDQ(J	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02,LTBIQ(J	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02,LWNLQ(J	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02,LXGQ(M	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF02,LYAZSQ(J	202203	202209	1	TOSHIBA	CMF02A,LXGQ(M	4	
202104	X35	CMF03,LCSQ(J	202203	202209	0			5	
202104	X35	CMF04(T2L,AUCS,AQ)	202203	202209	0			5	
202104	X35	CMF05(T2L,AUCS,AQ)	202203	202209	0			5	
202104	X35	CMG02(L,DAIHATU,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(L,FURUKA,AQ)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(L,FURUKA,QM)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,AISIN,AQ	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,AISIN,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,AISIN,QM	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,AUCS,AQ)	202203	202209	0			5	
202104	X35	CMG02(T2L,CANO,AQ)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,FJTN,AQ)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,FJTN,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,FJTN,QM)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,FURUKA,Q	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,HILX,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,JUKI,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,KEHIN,AQ	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,KEHIN,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,MATUD,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,MATUS,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,MKAI,A,Q	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,MKAI,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,MKAI,Q,M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,TEMQ)	202203	202209	1	TOSHIBA	CMG03A,LQ(M	4	
202104	X35	CMG02(T2L,YAZS,AQ)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(T2L,YAZS,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(TE12L,CANO,Q	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(TE12L,PEW,QM	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(TE12L,PEW,X)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02(TE12L,PP,A,Q	202203	202209	3	TOSHIBA	CMG03A,LQ(M	4	
202104	X35	CMG02(TE12L,PP,Q)	202203	202209	3	TOSHIBA	CMG03A,LQ(M	4	
202104	X35	CMG02(TE12L,PP,Q,M	202203	202209	3	TOSHIBA	CMG03A,LQ(M	4	
202104	X35	CMG02(TE12L,SPS,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LASTQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LASTQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LDIAHATUQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LDIAHATUQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LHILXQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LKEHINQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	

202104	X35	CMG02,LKEHINQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LKMQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LMAT-PAQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LMAT-PAQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LMATUDQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LMATUSQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LMATUSQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LMBJQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LMB5-IQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LNECATQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LNOHMIQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LPEWX(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LPEWX(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LSPSQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LSPSQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LSUMISQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LSUMISQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LTOYSQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LXHQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LYAZSQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LYAZSQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,LYKOQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG02,RQ(J	202203	202209	1	TOSHIBA	CMG03A,RQ(M	4	
202104	X35	CMG02,RQ(M	202203	202209	1	TOSHIBA	CMG03A,RQ(M	4	
202104	X35	CMG03(T2L,AST,AQ)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03(T2L,AUCS,AQ)	202203	202209	0			5	
202104	X35	CMG03(T2L,KOITS,AQ	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03(T2L,MSPR,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03(T2L,TCBN,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03(T2L,TEMQ)	202203	202209	1	TOSHIBA	CMG03A,LQ(M	4	
202104	X35	CMG03(T2L,SONY,A,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03(T2L,SONY,Q,M)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03(TE12L,AST,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03(TE12L,HLS,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03(TE12L,PP,A,Q	202203	202209	3	TOSHIBA	CMG03A,LQ(M	4	
202104	X35	CMG03(TE12L,PP,Q)	202203	202209	3	TOSHIBA	CMG03A,LQ(M	4	
202104	X35	CMG03(TE12L,PP,Q,M	202203	202209	3	TOSHIBA	CMG03A,LQ(M	4	
202104	X35	CMG03(TE12L,Q)	202203	202209	1	TOSHIBA	CMG03A,LQ(M	4	
202104	X35	CMG03(TE12R,Q,M)	202203	202209	1	TOSHIBA	CMG03A,RQ(M	4	
202104	X35	CMG03,LHLSQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03,LHLSQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03,LMB5-IQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03,LMSPRQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03,LMSPRQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03,LTCBNQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03,LTCBNQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03,LTDLQ(O	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03,LWNLQ(J	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG03,LXGQ(M	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	
202104	X35	CMG05(T2L,SANYU,Q)	202203	202209	1	TOSHIBA	CMG06A,LXGQ(M	4	
202104	X35	CMG05(T2L,TEM,Q)	202203	202209	1	TOSHIBA	CMG06A,LQ(M	4	
202104	X35	CMG05(TE12L,Q)	202203	202209	1	TOSHIBA	CMG06A,LQ(M	4	

202104	X35	CMG05(TE12L,Q,M)	202203	202209	1	TOSHIBA	CMG06A,LQ(M	4	
202104	X35	CMG05(TE12R,Q,M)	202203	202209	1	TOSHIBA	CMG06A,RQ(M	4	
202104	X35	CMG05,LCSQ(J	202203	202209	0			5	
202104	X35	CMG05,LSANYUQ(J	202203	202209	1	TOSHIBA	CMG06A,LXGQ(M	4	
202104	X35	CMG05,LSANYUQ(M	202203	202209	1	TOSHIBA	CMG06A,LXGQ(M	4	
202104	X35	CMG05,LXHQ(M	202203	202209	1	TOSHIBA	CMG06A,LXGQ(M	4	
202104	X35	CMG06(T2L,TEM,Q)	202203	202209	1	TOSHIBA	CMG06A,LQ(M	4	
202104	X35	CMG06(TE12L,Q)	202203	202209	1	TOSHIBA	CMG06A,LQ(M	4	
202104	X35	CMG06(TE12L,Q,M)	202203	202209	1	TOSHIBA	CMG06A,LQ(M	4	
202104	X35	CMG06(TE12R,Q,M)	202203	202209	1	TOSHIBA	CMG06A,RQ(M	4	
202104	X35	CMG06,LCSQ(J	202203	202209	0			5	
202104	X35	CMG06,LTBIQ(J	202203	202209	1	TOSHIBA	CMG06A,LXGQ(M	4	
202104	X35	CMG06,LWNLQ(J	202203	202209	1	TOSHIBA	CMG06A,LXGQ(M	4	
202104	X35	CMG07(T2L,AUCS,AQ)	202203	202209	0			5	
202104	X35	CMG07(T2L,TEM,Q)	202203	202209	1	TOSHIBA	CMG06A,LQ(M	4	
202104	X35	CMG07(TE12L,Q)	202203	202209	1	TOSHIBA	CMG06A,LQ(M	4	
202104	X35	CMG07(TE12L,Q,M)	202203	202209	1	TOSHIBA	CMG06A,LQ(M	4	
202104	X35	CMG07(TE12R,Q,M)	202203	202209	1	TOSHIBA	CMG06A,RQ(M	4	
202104	X35	CMG07,LXHQ(M	202203	202209	1	TOSHIBA	CMG06A,LXGQ(M	4	
202104	X35	CMG07,LXHQ(O	202203	202209	1	TOSHIBA	CMG06A,LXGQ(M	4	
202104	X35	CMG08(T2L,AUCS,AQ)	202203	202209	0			5	
202104	X35	CMG08(T2L,TEM,Q)	202203	202209	1	TOSHIBA	CMG06A,LQ(M	4	
202104	X35	CMG08(T2L,YAZB,AQ)	202203	202209	1	TOSHIBA	CMG06A,LXGQ(M	4	
202104	X35	CMG08(T2L,YAZB,Q)	202203	202209	1	TOSHIBA	CMG06A,LXGQ(M	4	
202104	X35	CMG08(T2L,YAZB,QM)	202203	202209	1	TOSHIBA	CMG06A,LXGQ(M	4	
202104	X35	CMG08(TE12L,Q)	202203	202209	1	TOSHIBA	CMG06A,LQ(M	4	
202104	X35	CMG08(TE12L,Q,M)	202203	202209	1	TOSHIBA	CMG06A,LQ(M	4	
202104	X35	CMG08(TE12R,Q,M)	202203	202209	1	TOSHIBA	CMG06A,RQ(M	4	
202104	X35	CMZ12,LCSQ(J	202203	202209	0			5	
202104	X35	CMZ13,LCSQ(J	202203	202209	0			5	
202104	X35	CMZ14,LCSQ(J	202203	202209	0			5	
202104	X35	CMZ15,LCSQ(J	202203	202209	0			5	
202104	X35	CMZ16,LCSQ(J	202203	202209	0			5	
202104	X35	CMZ18,LCSQ(J	202203	202209	0			5	
202104	X35	CMZ20,LCSQ(J	202203	202209	0			5	
202104	X35	CMZ24,LCSQ(J	202203	202209	0			5	
202104	X35	CMZ27(T2L,AUCS,AQ)	202203	202209	0			5	
202104	X35	CMZ30,LCSQ(J	202203	202209	0			5	
202104	X35	CMZ33(T2L,AUCS,AQ)	202203	202209	0			5	
202104	X35	CMZ36,LCSQ(J	202203	202209	0			5	
202104	X35	CMZ39,LCSQ(J	202203	202209	0			5	
202104	X35	CMZ43,LCSQ(J	202203	202209	0			5	
202104	X35	CMZ47,LCSQ(J	202203	202209	0			5	
202104	X35	CMZ51,LCSQ(J	202203	202209	0			5	
202104	X35	CMZB12,LCSQ(J	202203	202209	0			5	
202104	X35	CMZB13,LCSQ(J	202203	202209	0			5	
202104	X35	CMZB15,LCSQ(J	202203	202209	0			5	
202104	X35	CMZB18(T2L,AUCS,AQ	202203	202209	0			5	
202104	X35	CMZB20(T2L,AUCS,AQ	202203	202209	0			5	
202104	X35	CMZB24,LCSQ(J	202203	202209	0			5	
202104	X35	CMZB27(T2L,AUCS,AQ	202203	202209	0			5	
202104	X35	CMZB30(T2L,AUCS,AQ	202203	202209	0			5	

202104	X35	CMZB33(T2L,AUCS,AQ	202203	202209	0			5	
202104	X35	CMZB36(T2L,AUCS,AQ	202203	202209	0			5	
202104	X35	CMZB39,LCSQ(J	202203	202209	0			5	
202104	X35	CMZB43,LCSQ(J	202203	202209	0			5	
202104	X35	CMZB47(T2L,AUCS,AQ	202203	202209	0			5	
202104	X35	CMZB51,LCSQ(J	202203	202209	0			5	
202104	X35	CMZB68(T2L,AUCS,AQ	202203	202209	0			5	
202104	X35	CMZB75,LCSQ(J	202203	202209	0			5	
202104	X35	CMZB82,LCSQ(J	202203	202209	0			5	
202104	X35	CRF02,LCSQ(J	202203	202209	0			5	
202104	X35	CRF03(T5L,AUCS,AQ)	202203	202209	0			5	
202104	X35	CRF03(T5L,CANO,AQ)	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03(T5L,MATUD,Q)	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03(T5L,MBS-S,AQ	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03(T5L,MBS-S,QM	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03(T5L,NDS-S,QM	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03(T5L,TEMQ)	202203	202209	1	TOSHIBA	CRF03A,LQ(M	4	
202104	X35	CRF03(T5LCANO-O,AQ	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03(T5LCANO-O,QM	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03(T5R,NDS-S,QM	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03(TE85L,ASN,AQ	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03(TE85L,ASN,Q)	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03(TE85L,HO,Q)	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03(TE85L,PP,Q,M	202203	202209	3	TOSHIBA	CRF03A,LQ(M	4	
202104	X35	CRF03(TE85L,Q)	202203	202209	1	TOSHIBA	CRF03A,LQ(M	4	
202104	X35	CRF03(TE85R,Q,M)	202203	202209	1	TOSHIBA	CRF03A,RQ(M	4	
202104	X35	CRF03,LHOQ(J	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03,LMAT-MQ(J	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03,LMAT-MQ(M	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03,LMATUDQ(J	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03,LMATUDQ(M	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03,LPANAQ(J	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03,LWNLQ(J	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03,LXGQ(M	202203	202209	1	TOSHIBA	CRF03A,LXGQ(M	4	
202104	X35	CRF03,RQ(J	202203	202209	1	TOSHIBA	CRF03A,RQ(M	4	
202104	X35	CRG04(T5L,AUCS,AQ)	202203	202209	0			5	
202104	X35	CRG04(T5L,HILX,Q)	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04(T5L,KEHIN,AQ	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04(T5L,KEHIN,QM	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04(T5L,MBS-S,AQ	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04(T5L,MBS-S,QM	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04(T5L,RT,Q)	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04(T5L,SUMIS,AQ	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04(T5L,TEMQ)	202203	202209	1	TOSHIBA	CRG04A,LQ(M	4	
202104	X35	CRG04(TE85L,IKI,Q)	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04(TE85L,KGE,AQ	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04(TE85L,KGE,Q)	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04(TE85L,KGE,QM	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04(TE85L,PP,A,Q	202203	202209	3	TOSHIBA	CRG04A,LQ(M	4	
202104	X35	CRG04(TE85L,PP,Q)	202203	202209	3	TOSHIBA	CRG04A,LQ(M	4	
202104	X35	CRG04(TE85L,PP,Q,M	202203	202209	3	TOSHIBA	CRG04A,LQ(M	4	
202104	X35	CRG04(TE85R,Q,M)	202203	202209	1	TOSHIBA	CRG04A,RQ(M	4	

202104	X35	CRG04,LHILXQ(J	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04,LHILXQ(M	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04,LICHIQ(M	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04,LOZDX(M	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04,LPANAQ(J	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04,LPESQ(J	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04,LRTQ(M	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04,LSUMISQ(J	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04,LSUMISQ(M	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG04,LWNLQ(J	202203	202209	1	TOSHIBA	CRG04A,LQ(M	4	
202104	X35	CRG04,LXHQ(M	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	
202104	X35	CRG05(T5L,AUCS,AQ)	202203	202209	0			5	
202104	X35	CRS02,LWNLQ(J	202203	202209	1	TOSHIBA	CRS10I30A(T5L,TEMQ	4	
202104	X35	MG1500FXF1US71(DAE	202203	202209	1	TOSHIBA	MG1500FXF1US71(P1)	4	
202104	X35	MG1500FXF1US71(P)	202203	202209	1	TOSHIBA	MG1500FXF1US71(P1)	4	
202104	X35	S3W97	202203	202209	0			9	Individual case for specific customer
202104	X35	S3W98	202203	202209	0			9	Individual case for specific customer
202104	X35	T1JM4F,HQ(S	202203	202209	0			4	
202104	X35	T2TJ4FG(EL)	202203	202209	0			9	Individual case for specific customer
202104	X35	TPC6501(T5L,TEM,F)	202203	202209	3	TOSHIBA	2SC5714(TE12L,ZF)	4	
202104	X35	TPC6501(TE85L,F,M)	202203	202209	3	TOSHIBA	2SC5714(TE12L,ZF)	4	
202104	X35	TPC6501,LCSF(J	202203	202209	0			5	
202104	X35	TPC6502(5LMBS-S,AF	202203	202209	3	TOSHIBA	2SC5712(T2LXG,ZF)	4	
202104	X35	TPC6502(T5L,TEM,F)	202203	202209	3	TOSHIBA	2SC5712(TE12L,ZF)	4	
202104	X35	TPC6502(TE85L,F,M)	202203	202209	3	TOSHIBA	2SC5712(TE12L,ZF)	4	
202104	X35	TPC6502,LCSF(J	202203	202209	0			5	
202104	X35	TPC6502,LF(J	202203	202209	3	TOSHIBA	2SC5712(TE12L,ZF)	4	
202104	X35	TPC6502,LF(M	202203	202209	3	TOSHIBA	2SC5712(TE12L,ZF)	4	
202104	X35	TPC6503(TE85L,F,M)	202203	202209	3	TOSHIBA	2SC5819(TE12L,ZF)	4	
202104	X35	TPC6504,LCSF(J	202203	202209	0			5	
202104	X35	TPC6504,LF(M	202203	202209	3	TOSHIBA	2SC5810(TE12L,ZF)	4	
202104	X35	TPC6601(T5L,TEM,F)	202203	202209	3	TOSHIBA	2SA2060(TE12L,ZF)	4	
202104	X35	TPC6601(TE85L,F,M)	202203	202209	3	TOSHIBA	2SA2060(TE12L,ZF)	4	
202104	X35	TPC6601,LCSF(J	202203	202209	0			5	
202104	X35	TPC6601,LF(J	202203	202209	3	TOSHIBA	2SA2060(TE12L,ZF)	4	
202104	X35	TPC6602(TE85L,F,M)	202203	202209	3	TOSHIBA	2SA2069(TE12L,ZF)	4	
202104	X35	TPC6603(T5L,TEM,F)	202203	202209	3	TOSHIBA	2SA2059(TE12L,ZF)	4	
202104	X35	TPC6603(T5LEKA,A,F	202203	202209	3	TOSHIBA	2SA2059(T2LXG,F)	4	
202104	X35	TPC6603(TE85L,F,M)	202203	202209	3	TOSHIBA	2SA2059(TE12L,ZF)	4	
202104	X35	TPC6603,LCSF(J	202203	202209	0			5	
202104	X35	TPC6603,LF(J	202203	202209	3	TOSHIBA	2SA2059(TE12L,ZF)	4	
202104	X35	TPC6604(T5RSONY,FM	202203	202209	3	TOSHIBA	2SA2070(TE12L,ZF)	4	
202104	X35	TPC6604(T5RSOY,A,F	202203	202209	3	TOSHIBA	2SA2070(TE12L,ZF)	4	
202104	X35	TPC6604(T5RSOY,F,M	202203	202209	3	TOSHIBA	2SA2070(TE12L,ZF)	4	
202104	X35	TPC6604(TE85L,F,M)	202203	202209	3	TOSHIBA	2SA2070(TE12L,ZF)	4	
202104	X35	TPC6604,LCSF(J	202203	202209	0			5	
202104	X35	TPC6604,LF(J	202203	202209	3	TOSHIBA	2SA2070(TE12L,ZF)	4	
202104	X35	TPC6604,LXGF(M	202203	202209	3	TOSHIBA	2SA2070(T2LXG,ZF)	4	
202104	X35	TPC6701(TE85L,F,M)	202203	202209	3	TOSHIBA	TPCP8701(TE85L,F)	4	

202104	X35	TPC6701,LCSF(J	202203	202209	0			5	
202104	X35	TPC6701,LF(J	202203	202209	3	TOSHIBA	TPCP8701(TE85L,F)	4	
202104	X35	TPC6701,LJECOF(M	202203	202209	3	TOSHIBA	TPCP8701(T5LXG,F)	4	
202104	X35	TPC6901A,LCSF(J	202203	202209	0			5	
202104	X35	TPC6901A,LF(J	202203	202209	3	TOSHIBA	TPCP8901(TE85L,F)	4	
202104	X35	TPC6901A,LTOJSE(J	202203	202209	3	TOSHIBA	TPCP8901,LTOJSHE(O	4	
202104	X35	TPC6901A,LTOJSHE(M	202203	202209	3	TOSHIBA	TPCP8901,LTOJSHE(O	4	
202104	X35	TPC6901A,LTOJSX(J	202203	202209	3	TOSHIBA	TPCP8901,LTOJSHE(O	4	
202104	X35	TPC6901A,LWNLF(J	202203	202209	3	TOSHIBA	TPCP8901(TE85L,F)	4	
202104	X35	TPC6902(T5L,TEM,F)	202203	202209	3	TOSHIBA	TPCP8902(TE85L,F)	4	
202104	X35	TPC6902,LCSF(J	202203	202209	0			5	
202104	X35	TPC6902,LF(M	202203	202209	3	TOSHIBA	TPCP8902(TE85L,F)	4	
202104	X35	TPC6902,LXGF(M	202203	202209	3	TOSHIBA	TPCP8902(T5LXG,F)	4	
202104	X35	TPCP8504(BRA,F)	202203	202209	1	TOSHIBA	TPCP8505(TE85L,F)	4	
202104	X35	TPCP8504(TE85L,F)	202203	202209	1	TOSHIBA	TPCP8505(TE85L,F)	4	
202104	X35	TPD1030F(2LDIAMO,Q	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1030F(T2LADN,Q)	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1030F(T2LAISINQ	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1030F(T2LBOSCHQ	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1030F(T2LHILX,Q	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1030F(T2LMBSH,Q	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1030F(T2LPAE,Q)	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1030F(T2LPP,Q)	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1030F(T2LPPH,X)	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1030F(T2LSMC,Q)	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1030F(TE12LAL,Q	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1030F(TE12LCK,Q	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1032F(T2LMBS-HQ	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1032F(T2LPP,Q)	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1036F(T2LASAW,Q	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1036F(T2LFJTN,Q	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1036F(T2LPEV,Q)	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1036F(T2LVTSJ,Q	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1036F(TE12L,Q)	202203	202209	3	TOSHIBA	TPD1044F	4	
202104	X35	TPD1039F(T2LBSHA,Q	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1039F(T2LHNDLKQ	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1039F(T2LPP,Q)	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1039F(TE12L,Q)	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1044F(5LASAW2,E	202203	202209	1	TOSHIBA	TPD1044F,LXHF(O	5	
202104	X35	TPD1044F(T5LAISI,E	202203	202209	1	TOSHIBA	TPD1044F,LXHF(O	5	
202104	X35	TPD1044F(T5LFJTN,F	202203	202209	1	TOSHIBA	TPD1044F,LXHF(O	5	
202104	X35	TPD1044F(T5LNIKKIF	202203	202209	1	TOSHIBA	TPD1044F,LXHF(O	5	
202104	X35	TPD1044F(T5LPEW,F)	202203	202209	1	TOSHIBA	TPD1044F,LXHF(O	5	
202104	X35	TPD1046F(T2LASHI,Q	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1046F(T2LBSHA,Q	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1046F(T2LDNSO,X	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1046F(T2LKEHI,Q	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1046F(T2LPAS,Q)	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1046F(T2LPPH,Q)	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1046F(T2LSMI,Q)	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1046F(T2RHITJ,Q	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1046F(TE12LPP,Q	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	

202104	X35	TPD1046F,LACRCQ(O	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1046F,LAISINX(O	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1046F,LMBHAQ(O	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4	
202104	X35	TPD1047F(T2LDNSO1Q	202203	202209	3	TOSHIBA	TPD1055FA	3	
202104	X35	TPD1047F(T2LMC,Q)	202203	202209	3	TOSHIBA	TPD1055FA	3	
202104	X35	TPD1047F(T2LMITS,Q	202203	202209	3	TOSHIBA	TPD1055FA	3	
202104	X35	TPD1053F(T2LHITJ,Q	202203	202209	3	TOSHIBA	TPD1055FA	3	
202104	X35	TPD1053F(T2LKEHI,Q	202203	202209	3	TOSHIBA	TPD1055FA	3	
202104	X35	TPD1053F(T2LMC,Q)	202203	202209	3	TOSHIBA	TPD1055FA	3	
202104	X35	TPD1053F,LASTCHQ(O	202203	202209	3	TOSHIBA	TPD1055FA	3	
202104	X35	TPD1053F,LMBHAQ(O	202203	202209	3	TOSHIBA	TPD1055FA	3	
202104	X35	TPD1053F,LPPQ(O	202203	202209	3	TOSHIBA	TPD1055FA	3	
202104	X35	TPD1053F,LQ(O	202203	202209	3	TOSHIBA	TPD1055FA	3	
202104	X35	TPD1053F,LSTANRQ(O	202203	202209	3	TOSHIBA	TPD1055FA	3	
202104	X35	TPD1053F,LSUMISQ(O	202203	202209	3	TOSHIBA	TPD1055FA	3	
202104	X35	TPD1053F,LXHQ(O	202203	202209	3	TOSHIBA	TPD1055FA	3	
202104	X35	TPD1060F,LMCQ(O	202203	202209	3	TOSHIBA	TPD1055FA	4	
202104	X35	TPD1060F,LTOJSQ(O	202203	202209	3	TOSHIBA	TPD1055FA	4	
202104	X35	TPD2002AF,L1ALJF(S	202203	202209	0			5	
202104	X35	TPD2005F(EL1,F)	202203	202209	3	TOSHIBA	TPD2015FN[UD]	9	Termination of process
202104	X35	TPD2005F(EL1KUBOTF	202203	202209	3	TOSHIBA	TPD2015FN[UD]	9	Termination of process
202104	X35	TPD2005F(EL1PP,F)	202203	202209	3	TOSHIBA	TPD2015FN[UD]	9	Termination of process
202104	X35	TPD2005F(EL1PP1,F)	202203	202209	3	TOSHIBA	TPD2015FN[UD]	9	Termination of process
202104	X35	TPD2005F(ELBOSCH,F	202203	202209	3	TOSHIBA	TPD2015FN[UD]	9	Termination of process
202104	X35	TPD2005F(ELDIAMO,F	202203	202209	3	TOSHIBA	TPD2015FN[UD]	9	Termination of process
202104	X35	TPD2005F(ELPP,F)	202203	202209	3	TOSHIBA	TPD2015FN[UD]	9	Termination of process
202104	X35	TPD2005F(ELPP1,F)	202203	202209	3	TOSHIBA	TPD2015FN[UD]	9	Termination of process
202104	X35	TPD2007F(EL1,F)	202203	202209	3	TOSHIBA	TPD2017FN[UD]	9	Termination of process
202104	X35	TPD2007F(EL1KUBOTF	202203	202209	3	TOSHIBA	TPD2017FN[UD]	9	Termination of process
202104	X35	TPD2007F(EL1PP,F)	202203	202209	3	TOSHIBA	TPD2017FN[UD]	9	Termination of process
202104	X35	TPD2007F(EL1PP1,F)	202203	202209	3	TOSHIBA	TPD2017FN[UD]	9	Termination of process
202104	X35	TPD2007F(ELPP,F)	202203	202209	3	TOSHIBA	TPD2017FN[UD]	9	Termination of process
202104	X35	TPD2007F(ELPP1,F)	202203	202209	3	TOSHIBA	TPD2017FN[UD]	9	Termination of process
202104	X35	TPD2007F,L1MBIF(O	202203	202209	3	TOSHIBA	TPD2017FN[UD]	9	Termination of process
202104	X35	TPD4122K,NTMNHQ(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4122K,NTMQ(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4131K,FUGQ(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4131K,NTMNHQ(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4131K,NTMQ(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4132K,FUGQ(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4132K,NDSKQ(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4142K,NDSKQ(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4146K,NTMNHQ(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4146K,NTMQ(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4146K,Q(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4151AK,FUGQ(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4151AK,Q(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4151F,BF(S	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4151F,LF(S	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4151K,Q(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4152K,Q(M	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	
202104	X35	TPD4152K,Q(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4	

202104	X35	TPD7101F(EL1AISINF	202203	202209	3	TOSHIBA	TPD7106F/04AF/07F	3	
202104	X35	TPD7101F(EL1HLS,F)	202203	202209	3	TOSHIBA	TPD7106F/04AF/07F	3	
202104	X35	TPD7101F(EL1KEHINF	202203	202209	3	TOSHIBA	TPD7106F/04AF/07F	3	
202104	X35	TPD7101F(EL1TOYOGF	202203	202209	3	TOSHIBA	TPD7106F/04AF/07F	3	
202104	X35	TPD7101F(ELAISIN,F	202203	202209	3	TOSHIBA	TPD7106F/04AF/07F	3	
202104	X35	TPD7101F(ELDNSO,F)	202203	202209	3	TOSHIBA	TPD7106F/04AF/07F	3	
202104	X35	TPD7101F(ELMC,F)	202203	202209	3	TOSHIBA	TPD7106F/04AF/07F	3	
202104	X35	TPD7101F(ELTEE,F)	202203	202209	3	TOSHIBA	TPD7106F/04AF/07F	3	
202104	X35	TPD7101F(ELTOYOGF)	202203	202209	3	TOSHIBA	TPD7106F/04AF/07F	3	
202104	X35	TPD7102F(T5LDNS1,E	202203	202209	3	TOSHIBA	TPD7104AF	3	
202104	X35	TPD7102F(T5LDNSO,E	202203	202209	3	TOSHIBA	TPD7104AF	3	
202104	X35	TPD7102F(T5LDWAV,E	202203	202209	3	TOSHIBA	TPD7104AF	3	
202104	X35	TPD7102F(T5LMC,F)	202203	202209	3	TOSHIBA	TPD7104AF	3	
202104	X35	TPD7102F(T5LMITS,F	202203	202209	3	TOSHIBA	TPD7104AF	3	
202104	X35	TPD7210F(EL1AISINF	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1ASAW,F	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1DAIHAF	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1DIAM,F	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1DNSO,F	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1FJTN,F	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1HITC,F	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1HITJ,F	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1HLS,F)	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1JUKI,F	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1KEHINF	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1MITSUF	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1NMB,F)	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1OMA,F)	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1OMII,F	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(EL1SIND,F	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(ELAISIN,F	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(ELDNSO,F)	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(ELHILX,F)	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(ELHITJ,F	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(ELJTEK,F)	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(ELKSTEC,F	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(ELMAKIT,F	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(ELMC,F)	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F(ELTEE,F)	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F,L1ELITF(O	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TPD7210F,L1XHF(O	202203	202209	3	TOSHIBA	TPD7212F/FN	3	
202104	X35	TTC012(Q)	202203	202209	2	TOSHIBA	2SC6142(Q)	4	
202104	X35	TTC012,XGQ(O	202203	202209	2	TOSHIBA	2SC6142,XGQ(O	4	
202104	X35	2SA1213-Y(T2LSONYF	202203	202209	1	TOSHIBA	2SA1213-Y(T2LXG,ZC	4	Y
202104	X35	2SA1483-Y(T2LPAS,F	202203	202209	2	TOSHIBA	2SA2070(T2LXG,ZF)	4	Y
202104	X35	2SA1483-Y(TE12L,F)	202203	202209	2	TOSHIBA	2SA2070(TE12L,F)	4	Y
202104	X35	2SA1736(T2LKEHIN,F	202203	202209	1	TOSHIBA	2SA1736(T2LXG,ZC)	4	Y
202104	X35	2SA2060(T2LPAV,F)	202203	202209	1	TOSHIBA	2SA2060(T2LXG,ZF)	4	Y
202104	X35	2SC5785(TE12L,F)	202203	202209	2	TOSHIBA	2SC5819(TE12L,F)	4	Y
202104	X35	2SC5906(TE85L,F)	202203	202209	2	TOSHIBA	2SC5976(TE85L,F)	4	Y
202104	X35	2SC6000(TE16L1,NQ)	202203	202209	2	TOSHIBA	TTC016,L1Q(O	4	Y
202104	X35	CMC02(TE12L,Q)	202203	202209	2	TOSHIBA	CMG03A,LQ(M	4	Y

202104	X35	CMF01(TE12L,Q)	202203	202209	1	TOSHIBA	CMF01A,LQ(M	4	Y
202104	X35	CMG02(T2L,MAT-PA,Q	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	Y
202104	X35	CMG02(TE12L,Q)	202203	202209	1	TOSHIBA	CMG03A,LQ(M	4	Y
202104	X35	CMG02(TE12L,Q,M)	202203	202209	1	TOSHIBA	CMG03A,LQ(M	4	Y
202104	X35	CMG03(T2L,KOITS,Q)	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	Y
202104	X35	CMG03(T2L,KOITS,QM	202203	202209	1	TOSHIBA	CMG03A,LXGQ(M	4	Y
202104	X35	CMG03(TE12L,Q,M)	202203	202209	1	TOSHIBA	CMG03A,LQ(M	4	Y
202104	X35	CRF03(TE85L,Q,M)	202203	202209	1	TOSHIBA	CRF03A,LQ(M	4	Y
202104	X35	CRG04(T5L,SUMIS,Q)	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	Y
202104	X35	CRG04(TE85L,Q)	202203	202209	1	TOSHIBA	CRG04A,LQ(M	4	Y
202104	X35	CRG04(TE85L,Q,M)	202203	202209	1	TOSHIBA	CRG04A,LQ(M	4	Y
202104	X35	CRG04(TE85LKEHIN,Q	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	Y
202104	X35	CRG04,LKEHINQ(J	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	Y
202104	X35	CRG04,LKEHINQ(M	202203	202209	1	TOSHIBA	CRG04A,LXGQ(M	4	Y
202104	X33	TJ100F06M3L(T4L,Q)	202203	202209	3	TOSHIBA	TJ60S06M3L	3	Y
202104	X33	TJ150F06M3L(T4L,Q)	202203	202209	3	TOSHIBA	TJ60S06M3L	3	Y
202104	X33	TJ20A10M3(STA4,Q,M	202203	202209	1	ONSemiconductor	NVATS68301PZ	4	Y
202104	X33	TJ9A10M3,S4Q(M	202203	202209	3	TOSHIBA	TJ15S10M3	3	Y
202104	X33	TK100F04K3(4LMIB,Q	202203	202209	1	TOSHIBA	TK1R4F04PB	3	Y
202104	X33	TK100F04K3(TE24L,Q	202203	202209	1	TOSHIBA	TK1R4F04PB	3	Y
202104	X33	TK100F06K3(TE24L,Q	202203	202209	3	TOSHIBA	TK90S06N1L	3	Y
202104	X33	TK10S04K3L(T6L1,NQ	202203	202209	1	TOSHIBA	TK15S04N1L	3	Y
202104	X33	TK130F06K3(TE24L,Q	202203	202209	3	TOSHIBA	TK90S06N1L	3	Y
202104	X33	TK13A60D(Q,M)	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	Y
202104	X33	TK13A60D(STA4,Q,M)	202203	202209	2	TOSHIBA	TK430A60F,S4X(S	2	Y
202104	X33	TK15A60U(S4PHI,Q,M	202203	202209	2	TOSHIBA	TK290A60Y,S4X(S	2	Y
202104	X33	TK20A60U(S4PHI,Q,M	202203	202209	2	TOSHIBA	TK190A65Z,S4X(S	2	Y
202104	X33	TK20J60U(S1PED,F)	202203	202209	2	TOSHIBA	TK16J60W,S1VE(S	2	Y
202104	X33	TK20P04M1,RQ(S	202203	202209	1	TOSHIBA	TK15S04N1L	3	Y
202104	X33	TK20S04K3L(T6L1,NQ	202203	202209	2	TOSHIBA	TK15S04N1L	3	Y
202104	X33	TK20S06K3L(L1VA,NQ	202203	202209	1	TOSHIBA	TK25S06N1L	3	Y
202104	X33	TK20S06K3L(T6L1,NQ	202203	202209	1	TOSHIBA	TK25S06N1L	3	Y
202104	X33	TK40P04M1(T6RSS-Q)	202203	202209	3	TOSHIBA	TK3R1P04PL	3	Y
202104	X33	TK40S10K3Z(T6L1,NQ	202203	202209	1	TOSHIBA	TK33S10N1Z	3	Y
202104	X33	TK4A60D(STA4,Q,M)	202203	202209	2	TOSHIBA	TK1K7A60F,S4X(S	2	Y
202104	X33	TK4A60DA(Q,M)	202203	202209	2	TOSHIBA	TK2K2A60F,S4X(S	2	Y
202104	X33	TK4A60DA(STA4,Q,M)	202203	202209	2	TOSHIBA	TK2K2A60F,S4X(S	2	Y
202104	X33	TK4A60DA(STA4,X,M)	202203	202209	2	TOSHIBA	TK2K2A60F,S4X(S	2	Y
202104	X33	TK50P04M1(T6RSS-Q)	202203	202209	3	TOSHIBA	TK3R1P04PL	3	Y
202104	X33	TK65G10N1,RQ(S	202203	202209	3	TOSHIBA	TPH3R70APL	3	Y
202104	X33	TK65S04K3L(T6L1,NQ	202203	202209	1	TOSHIBA	TK65S04N1L	3	Y
202104	X33	TK6A60D(S4PHI,Q,M)	202203	202209	2	TOSHIBA	TK1K2A60F,S4X(S	2	Y
202104	X33	TK6A60D(S4PHI,X,S)	202203	202209	2	TOSHIBA	TK1K2A60F,S4X(S	2	Y
202104	X33	TK80S04K3L(L1MI,NQ	202203	202209	1	TOSHIBA	TK100S04N1L	3	Y
202104	X33	TK80S04K3L(T6L1,NQ	202203	202209	1	TOSHIBA	TK100S04N1L	3	Y
202104	X33	TK80S04K3L,LMI1Q(O	202203	202209	1	TOSHIBA	TK100S04N1L	3	Y
202104	X33	TK80S06K3L(T6L1,NQ	202203	202209	1	TOSHIBA	TK90S06N1L	3	Y
202104	X33	TK80S06K3L,LXHQ(O	202203	202209	1	TOSHIBA	TK90S06N1L	3	Y
202104	X33	TK8A60DA(Q,M)	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	Y
202104	X33	TK8A60DA(STA4,Q,M)	202203	202209	2	TOSHIBA	TK1K0A60F,S4X(S	2	Y
202104	X33	TPC6010-H(TE85L,FM	202203	202209	3	TOSHIBA	SSM3K341R	3	Y
202104	X33	TPC6010-H,LF(CM	202203	202209	3	TOSHIBA	SSM3K341R	3	Y

202104	X33	TPC6011(TE85L,F,M)	202203	202209	3	TOSHIBA	SSM6K504NU	3		Y
202104	X33	TPC6012(TE85L,F,M)	202203	202209	3	TOSHIBA	SSM3K123TU	3		Y
202104	X33	TPC6110(TE85L,F,M)	202203	202209	3	TOSHIBA	SSM3J340R	3		Y
202104	X33	TPC6110,LF(CM	202203	202209	3	TOSHIBA	SSM3J340R	3		Y
202104	X33	TPC6111(TE85L,F,M)	202203	202209	3	TOSHIBA	SSM3J378R	3		Y
202104	X33	TPC6111,LF(CM	202203	202209	3	TOSHIBA	SSM3J378R	3		Y
202104	X33	TPC6111,LPASF(M	202203	202209	3	TOSHIBA	SSM3J378R	3		Y
202104	X33	TPC6113(TE85L,F,M)	202203	202209	3	TOSHIBA	SSM3J378R	3		Y
202104	X33	TPC6113,LF(CM	202203	202209	3	TOSHIBA	SSM3J378R	3		Y
202104	X35	TPC6901A,LF(M	202203	202209	3	TOSHIBA	TPCP8901(TE85L,F)	4		Y
202104	X35	TPC6902(TE85L,F,M)	202203	202209	3	TOSHIBA	TPCP8902(TE85L,F)	4		Y
202104	X33	TPC8048-H(TE12L,V)	202203	202209	2	TOSHIBA	TPH7R006PL	3		Y
202104	X33	TPC8050-H(TE12L,V)	202203	202209	1	TOSHIBA	TPH11006NL	3		Y
202104	X33	TPC8120(TE12L,V)	202203	202209	3	TOSHIBA	TPC8125	3		Y
202104	X33	TPC8124(TE12L,V)	202203	202209	2	TOSHIBA	TPC8133	3		Y
202104	X33	TPC8227-H,LQ(S	202203	202209	1	ROHM	SP8K24HZG	4		Y
202104	X33	TPC8228-H,LQ(S	202203	202209	1	ROHM	SP8K32HZG	4		Y
202104	X33	TPC8229-H,LQ(S	202203	202209	2	ROHM	SP8K41HZG	4		Y
202104	X33	TPCA8045-H(T2L1,VM	202203	202209	2	TOSHIBA	TPH3R704PL	3		Y
202104	X33	TPCA8051-H(T2L1,VM	202203	202209	2	TOSHIBA	TPH8R008NH	3		Y
202104	X33	TPCA8084,L1Q(O	202203	202209	1	TOSHIBA	TPH3R506PL	3		Y
202104	X33	TPCA8085,L1Q(O	202203	202209	1	TOSHIBA	TPH3R704PL	3		Y
202104	X33	TPCA8086,L1Q(O	202203	202209	1	TOSHIBA	TPH9R506PL	3		Y
202104	X33	TPCA8122,L1Q(O	202203	202209	3	TOSHIBA	TJ80S04M3L	3		Y
202104	X33	TPCA8123,L1Q(O	202203	202209	3	TOSHIBA	TJ60S06M3L	3		Y
202104	X33	TPCA8125,L1Q(O	202203	202209	3	TOSHIBA	TJ30S06M3L	3		Y
202104	X33	TPCC8069,L1Q(O	202203	202209	1	TOSHIBA	XPN7R104NC	3		Y
202104	X33	TPCC8106,L1Q(O	202203	202209	1	TOSHIBA	XPN9R614MC	3		Y
202104	X33	TPCC8107,L1Q(O	202203	202209	3	TOSHIBA	TJ30S06M3L	3		Y
202104	X35	TPD1030F(T2LKEHINQ	202203	202209	3	TOSHIBA	TPD1044F	4		Y
202104	X35	TPD1030F(TE12L,Q)	202203	202209	3	TOSHIBA	TPD1044F	4		Y
202104	X35	TPD1032F(T2LKEHINQ	202203	202209	3	TOSHIBA	TPD1044F	4		Y
202104	X35	TPD1032F(TE12L,Q)	202203	202209	3	TOSHIBA	TPD1044F	4		Y
202104	X35	TPD1046F(T2LHITJ,Q	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4		Y
202104	X35	TPD1046F(TE12L,Q)	202203	202209	3	TOSHIBA	TPD1044F/TPD1058FA	4		Y
202104	X35	TPD2005F(EL,F)	202203	202209	3	TOSHIBA	TPD2015FN[UD]	9	Termination of process	Y
202104	X35	TPD2007F(EL,F)	202203	202209	3	TOSHIBA	TPD2017FN[UD]	9	Termination of process	Y
202104	X35	TPD4123AK(C,Q)	202203	202209	3	TOSHIBA	TPD4165K[UD]/4204F	4		Y
202104	X35	TPD4123K(C,Q)	202203	202209	3	TOSHIBA	TPD4165K[UD]/4204F	4		Y
202104	X35	TPD4135AK(HID,Q)	202203	202209	3	TOSHIBA	TPD4165K[UD]/4204F	4		Y
202104	X35	TPD4135AK(Q)	202203	202209	3	TOSHIBA	TPD4165K[UD]/4204F	4		Y
202104	X35	TPD4135K(HID,Q)	202203	202209	3	TOSHIBA	TPD4165K[UD]/4204F	4		Y
202104	X35	TPD4135K(Q)	202203	202209	3	TOSHIBA	TPD4165K[UD]/4204F	4		Y
202104	X35	TPD4142K,Q(O	202203	202209	3	TOSHIBA	TPD4162F,LF(S	4		Y
202104	X35	TPD4144AK,Q(O	202203	202209	3	TOSHIBA	TPD4164K[UD]/4204F	4		Y
202104	X35	TPD4144K,Q(O	202203	202209	3	TOSHIBA	TPD4164K[UD]/4204F	4		Y
202104	X35	TRS10A65F,S1Q(S	202203	202209	1	TOSHIBA	TRS10A65F,S1Q(S2	3		Y
202104	X35	TRS4A65F,S1Q(S	202203	202209	1	TOSHIBA	TRS4A65F,S1Q(S2	3		Y
202104	X35	TRS6A65F,S1Q(S	202203	202209	1	TOSHIBA	TRS6A65F,S1Q(S2	3		Y
202104	X35	TRS8A65F,S1Q(S	202203	202209	1	TOSHIBA	TRS8A65F,S1Q(S2	3		Y