

## **Product Change Notification**



Product Group: TC/Mon Feb 7, 2022/PCN-TC-001-2022-REV-0

## Addition of Lot ID code to product marking for T52 family

**DESCRIPTION OF CHANGE:** Add four digit Lot ID code to capacitor marking in order to provide individual unit traceability.

REASON FOR CHANGE: Improvement of individual unit traceability

EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: There is no effect on quality and reliability

PART NUMBERS/SERIES/FAMILIES AFFECTED: Please see materials list on the succeeding page.

VISHAY BRAND(s): Vishay

TIME SCHEDULE:

Start Shipment Date: Mon Jul 18, 2022

**SAMPLE AVAILABILITY: Upon Request** 

PRODUCT IDENTIFICATION: Not Applicable

**QUALIFICATION DATA: Not Applicable** 

This PCN is considered approved, without further notification, unless we receive specific customer concerns before Tue Jan 18, 2022 or as specified by contract.

ISSUED BY: Yuri Stangrit, Yuri.Stangrit@vishay.com

For further information, please contact your regional Vishay office.

## **CONTACT INFORMATION:**

Americas	Europe	Asia
David Bellomy	Thomas Poessnecker	Boon Hooi Tan
7557 Rambler Road, Suite 575	DrFelix-Zandman-Platz 1	37A Tampines Street 92 #07-01
Dallas TX United States 75231-4142	Selb Germany 95100	Singapore Singapore 528886
David.Bellomy@vishay.com	Thomas.Poessnecker@vishay.com	Boonhooi.Tan@Vishay.com
Phone: (254)479-0010	Phone: + 49 9287 712 595	Phone: + 65 - 6780 - 7759
Fax: +1 214-363-9444	Fax: + 49 9287 712 274	Fax: + 65 - 6780 - 7749





## **Product Change Notification**




Product Group: TC/Mon Feb 7, 2022/PCN-TC-001-2022-REV-0

T52B2476M016C0200	T52E5107M020C0055	T52E5157M016C0050	T52E5476M025C0055	T52E5476M035C0055
T52E5476M035C0070	T52E5476M035C0100	T52M1107M035C0055	T52M1107M035C0100	T52M1157M025C0055
T52M1227M010C0055	T52M1227M016C0055	T52M1227M016C0070	T52M1227M025C0055	T52M1227M025C0100
T52M1337M010C0055	T52M1337M016C0040	T52M1337M016C0055		









**New marking** 

**Previous marking** 

