

PRODUCT CHANGE NOTIFICATION

Product Category COPPER CONNECTORS 20220308-1

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: **NJ** **EMEA** **LATAM** **AP** Mar-22

IMPACTED REGIONS: **DISCONTINUATION**

REASON FOR CHANGE: **OTHER**

DESCRIPTION OF CHANGE: (Required)

Panduit's Cat 6A UTP Jacks use an aluminum foil tape applied to the jack housing to achieve industry leading alien crosstalk performance. Panduit is making a permanent change to the color of the foil tape on Pan-Net Cat 6A UTP Jacks. The old foil tape was colored similar to the color of the housing. Due to global material shortages Panduit will be providing jacks, independent of housing color, with a silver colored foil tape. This change took place in Panduit's manufacturing facilities in Nov 2021 and will now be permanent. This change does not affect fit, form, function, or jack performance.

See images of the new silver foil tape to the right.

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	3	21
Old product discontinuation date*			

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com	
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com	
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com	
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com		
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerService@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com	
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com	

IMPACTED PART NUMBER(s)


CJ6X88TGBL-C
CJ6X88TGIG
CJ6X88TGOR
CJ6X88TGVL
CJ6X88TGAW
CJ6X88TGAW-24
CJ6X88TGAW-C
CJ6X88TGBL
CJ6X88TGBL-24
CJ6X88TGBU
CJ6X88TGBU-24
CJ6X88TGBU-C
CJ6X88TGEI
CJ6X88TGEI-24

CJ6X88TGEI-C
CJ6X88TGGR
CJ6X88TGGR-24
CJ6X88TGGR-C
CJ6X88TGIG-24
CJ6X88TGIG-C
CJ6X88TGIW
CJ6X88TGIW-24
CJ6X88TGIW-C
CJ6X88TGOR-24
CJ6X88TGOR-C
CJ6X88TGPk
CJ6X88TGRD
CJ6X88TGRD-24
CJ6X88TGRD-C
CJ6X88TGVL-24
CJ6X88TGVL-C
CJ6X88TGWH
CJ6X88TGWH-24
CJ6X88TGWH-C
CJ6X88TGYL
CJ6X88TGYL-24
CJ6X88TGYL-C
CJT6X88TGAW
CJT6X88TGBU
CJT6X88TGEI
CJT6X88TGGR
CJT6X88TGIG
CJT6X88TGIW
CJT6X88TGOR
CJT6X88TGRD
CJT6X88TGVL
CJT6X88TGYL
CJT6X88TGBL
CJT6X88TGWH
CJE6X88TGBL
CJE6X88TGBU
CJE6X88TGIW
CJE6X88TGRD
CJK6X88TGBL
CJK6X88TGBU
CJK6X88TGGR
CJK6X88TGOR
CJK6X88TGRD
CJK6X88TGYL
CJQ6X88TGBL
CJH6X88TGAW
CJH6X88TGBL
CJH6X88TGBU
CJH6X88TGEI
CJH6X88TGGR
CJH6X88TGIG
CJH6X88TGIW
CJH6X88TGOR
CJH6X88TGRD
CJH6X88TGVL
CJH6X88TGWH
CJH6X88TGYL
CJLR6X88TGAW
CJLR6X88TGEI
CJLR6X88TGIG
CJLR6X88TGIW
CJLR6X88TGRD
CJLR6X88TGVL
CJLR6X88TGYL
CJLR6X88TGBL
CJLR6X88TGBU
CJLR6X88TGGR
CJLR6X88TGOR

CJLR6X88TGW
CJUD6X88TGA
CJUD6X88TGE
CJUD6X88TGI
CJUD6X88TIW
CJUD6X88TGR
CJUD6X88TGV
CJUD6X88TGB
CJUD6X88TGBU
CJUD6X88TGR
CJUD6X88TGRD
CJUD6X88TGW
CJUD6X88TGY



Example below: current color matched tape may be substituted with silver color. This will apply to any color jack.



This shows the new tape color that may be utilized.

