



23-Mar-2022

**PCN #:** PCN-21-122445

**Subject :** The listed part numbers are being discontinued and no longer available. Please consult with your local customer sales.

**Description of Change :** The listed part numbers are being discontinued and no longer available. Please consult with your local customer sales.

The listed part numbers below will be discontinued and no longer available.

Reason of Changes: One of TE's manufacturing plant located in Norwood will be closed.

**Reason :**

**Key Dates :**

**Last Order Date:**14-Jan-2022

**Last Ship/EOL Date:**31-Jul-2022

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
225557-6			
415490-4			
5413558-1			
415504-3	"1120368"		
5887046-1			
415504-4			
415490-2			
415490-3			
1050766-1	"2001-7947-00"		
5415105-1			
6274124-2			
5413589-9			
5225557-6			

1408337-1			
5413589-7			
1050756-1			
5413558-3			
5413558-5			
5413515-2			
2-5221128-1			
1046222-1	"1250-0562-00"		
5413589-5			
1274124-2			
1050717-1	"2001-7141-00"		
415377-2			
415377-5			
415490-1			
1050999-1	"2004-7195-00"		
1-5413589-6			
5413959-1			
1-5221128-7			
1050564-1	"2001-5119-00"		
415377-1			
5413986-1			
1046313-1	"1250-2450-00"		
414244-1			
5413589-2			
5413589-3			
415380-1			
1-5227079-1			
1053378-1			
5413589-1			
5415085-1			
1-5221128-1	"1017916"		
1051139-1			
1051013-1			

5413558-2			
5413771-1			
415504-2			
201143-1			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.