

05-Aug-2022

PCN #: PCN-22-148191

Subject : M8&M12 cordset and connector of European version

Description of Change : The listed part numbers are being discontinued and no longer available. Suggested substitute part numbers are shown below, with any significant difference described. Please verify that all substitute part numbers provided below are suitable for your specific application. Drawings are available via TE.com.

Reason: Product Discontinuance

Key Dates:

Last Order Date:30-Sep-2022 Last Ship/EOL Date:10-Oct-2022

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
1838838-2		T4032014041 -000	
1838258-1		T4151410005 -020	
1838242-3		T4151310003 -005	
1838298-3		T4051410004 -005	
1838240-3		T4151110005 -005	
1838240-1		T4151110005 -020	
1838238-3		T4151110004 -005	
1838246-3		T4151310005 -005	
1838296-3		T4051410003 -005	
1838244-1		T4151310004 -020	

1838256-1	T4151410004 -020	
1838839-1	T4033014031 -000	

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.