



16-Nov-2022

PCN #: PCN-22-154501

Subject : MODII HDR SRST B/A .100CL

Description of Change : Supersede low temp parts

Reason : Offer only high temp housings.

Key Dates :

Last Order Date:07-Feb-2023

Last Ship/EOL Date:07-May-2023

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
103747-5		5-146285-5	
4-103747-0		9-146285-0	
102976-2		5-146277-2	
102976-4		5-146277-4	
102976-5		5-146277-5	
103185-8		5-146280-8	
103185-9		5-146280-9	
103327-7		5-146278-7	
103741-5		5-146282-5	
1-103321-6		6-146274-6	
4-103321-6		5-146274-8	
4-103327-5		5-146278-3	
103321-3	"651-1044-01"	5-146274-3	
1-103239-6		6-146281-6	
5-103327-1		5-146278-4	
4-103321-0		9-146274-0	
103327-2		5-146278-2	

103327-1		5-146278-1	
103747-6		5-146285-6	
103747-9		5-146285-9	
1-103747-6		6-146285-6	
146089-3		5-146279-3	
103239-2		5-146281-2	
103321-6		5-146274-6	
103741-2		5-146282-2	
103741-3		5-146282-3	
103741-7		5-146282-7	
103741-9		5-146282-9	
4-146382-0		9-146283-0	
4-146404-0		9-146278-0	
103747-7	"651-1125-01"	5-146285-7	"1372110"
1-103239-2		6-146281-2	
9-146411-0		9-146283-0	
1-103327-4		6-146278-4	
103747-4		5-146285-4	
1-103747-2		6-146285-2	
1-102972-0		6-146276-0	
3-102972-0		8-146276-0	
102976-3		5-146277-3	
103185-3		5-146280-3	
103185-7		5-146280-7	
4-103239-0		9-146281-0	
103321-5		5-146274-5	
103321-7		5-146274-7	
103741-1		5-146282-1	
103741-4		5-146282-4	
103741-8		5-146282-8	
1-103239-4		6-146281-4	
4-103321-8		9-146274-0	
2-103185-4		7-146280-4	
1-102976-3		6-146277-3	
4-103327-0		9-146278-0	

4-103321-5		5-146274-3	
103321-2		5-146274-2	
102972-5		5-146276-5	
102972-8		5-146276-8	
1-102972-1		6-146276-1	
3-102972-2		8-146276-2	
103185-6		5-146280-6	
103239-1		5-146281-1	
103239-8		5-146281-8	
2-103321-5		7-146274-5	
1-102972-2		6-146276-2	
4-103321-7		6-146274-6	
9-146404-0		9-146278-0	
1-103327-1		6-146278-1	
103747-1		5-146285-1	
2-103747-0		7-146285-0	
102972-9		5-146276-9	
102976-1		5-146277-1	
102976-6		5-146277-6	
1-102976-4		6-146277-4	
2-102976-0		7-146277-0	
4-146089-0		9-146279-0	
103185-4		5-146280-4	
103185-5		5-146280-5	
103239-6		5-146281-6	
103321-4		5-146274-4	
2-103239-0	"651-1068-01"	7-146281-0	
103327-4		5-146278-4	
103327-8		5-146278-8	
103239-9		5-146281-9	
1-103327-6		6-146278-6	
1-103321-4		6-146274-4	
1-102972-7		6-146276-7	
4-102972-0		9-146276-0	
1-102976-0		6-146277-0	

1-103185-1		6-146280-1	
4-103185-0		9-146280-0	
103239-3	"651-1034-01"	5-146281-3	"1359880"
103321-1		5-146274-1	
103327-6		5-146278-6	
103321-8		5-146274-8	
102976-9		5-146277-9	
4-103327-6		5-146278-6	
4-146411-0		9-146282-0	
102972-2		5-146276-2	
102972-3		5-146276-3	
102976-8		5-146277-8	
103185-1		5-146280-1	
103185-2		5-146280-2	
1-103185-4		6-146280-4	
103239-4		5-146281-4	
1-103239-0		6-146281-0	
103321-9		5-146274-9	
1-103327-0		6-146278-0	
4-103327-4		5-146278-2	
4-103327-9		9-146278-0	
3-103327-6		8-146278-6	
1-103327-8		6-146278-8	
1-103185-2		6-146280-2	
103327-3		5-146278-3	
103747-3		5-146285-3	
103747-8		5-146285-8	
102972-1		5-146276-1	
102972-4		5-146276-4	
102972-6		5-146276-6	
1-102976-6		6-146277-6	
4-102976-0		9-146277-0	
3-103185-6	"2-28226-0010"	8-146280-6	"1358928"
103239-5		5-146281-5	

1-103321-0		6-146274-0	
3-103321-6	"2-28226-0113"	8-146274-6	
103327-5		5-146278-5	
103741-6		5-146282-6	
4-103741-0		9-146282-0	
4-103321-4		5-146274-2	
1-103239-5		6-146281-5	
2-103185-0		7-146280-0	
103239-7		5-146281-7	
4-103327-3		5-146278-1	
1-103747-0		6-146285-0	
103747-2	"651-1105-01"	5-146285-2	
1-102976-1		6-146277-1	
102972-7			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.