

## **Product Termination Notification**

Product Group: TC/Tue Aug 29, 2023/PTN-TC-005-2023-REV-0



## Terminate manufacturing of T58W9476M6R3C0150

For further information, please contact your regional Vishay office.

## **CONTACT INFORMATION**

Americas	Europe	Asia
David Bellomy	Thomas Poessnecker	Boon Hooi Tan
7557 Rambler Road, Suite 575	DrFelix-Zandman-Platz 1	37A Tampines Street 92, #07-00
-	-	-
Dallas TX United States 75231-4142	Selb Germany D-95100	Singapore Singapore 528886
Phone: (254)479-0010	Phone: + 49 9287 712 595	Phone: +65-6780-7759
Fax: +1 214-363-9444	Fax: + 49 9287 712 274	Fax: +65-6780-7749
David.Bellomy@vishay.com	Thomas.Poessnecker@Vishay.com	Boonhooi.Tan@Vishay.com

**Description of Change:** Vishay will discontinue production of T58W9476M6R3C0150.

**Reason for Change:** Manufacturing of T58W9476M6R3C0150 is no longer cost effective. T58W9476M6R3C0200 part number is available for replacement.

Expected Influence on Quality/Reliability/Performance: NO

Part Numbers/Series/Families Affected: T58W9476M6R3C0150

Vishay Brand(S): Vishay

Time Schedule:

Last Time Buy Date: Mon May 27, 2024 Last Time Ship Date: Tue Aug 27, 2024

Sample Availability: Will be supported with T58W9476M6R3C0200 only

Product Identification: N/A

Qualification Data: N/A

This PTN is considered approved, without further notification, unless we receive specific customer concerns before Thu Sep 28, 2023 or as specified by contract.

Issued By: Yuri Stangrit, Yuri.Stangrit@vishay.com