



## Product Discontinuance

Document #:PD25324XD1

Issue Date:05 Sep 2023

<b>Title of Change:</b>	Update to PD25324 series - Reactivation of previously discontinued part FPF1039UCX
<b>Last Time Buy Date:</b>	NA
<b>Last Ship Date:</b>	NA
<b>Contact information:</b>	Contact your local onsemi Sales Office or <a href="mailto:Wayne.Cheng@onsemi.com">Wayne.Cheng@onsemi.com</a>

### Description and Purpose:

onsemi wishes to inform our customers of reactivation of device below that was previously discontinued in PD25324 series.

The part shall be considered active.

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

#### Americas:

Tom Siegel (tom.siegel@onsemi.com)

☎ +1 765 868 5022

USA

#### Japan:

Isao Usuki (isao.usuki@onsemi.com)

☎ +81 3 6880 1771

Japan

#### Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)

☎ +421 33790 2229

Slovakia

#### Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)

☎ +852 2689 0209

China

### List of Affected Parts:

**Note:** Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

Part Number	Replacement part	Supplier
FPF1039UCX	#NONE	#NA