



October 18, 2023

Subject: Xenon strobe product discontinuation

Dear Customer,

The following Edwards Signaling xenon strobe products are being discontinued effective immediately due to end-of-life components and cost increases combined with an increased demand for more efficient LED products. We have replacement options in LED, Halogen or Incandescent depending on the model. Not all products have replacement options. Attached is a chart with potential/closest replacement part options. Please work with our customer service team to update any current orders to an active replacement part.

Thank you.

Regards,

Mfr PN	Mfr PN	Mfr PN	Mfr PN
101STCG1	92BR5	94CN5	96DV2GN5
101STGN5	92CN5	94CR5	96DV2MN5
101STRG1	92CR5	94DDV2AG1	96DV2RN5
101STRN5	92GN5	94DDV2BG1	97AEK
102LSSTN5	92GR5	94DDV2CG1	97AMP
105HISTAN5	92LST	94DDV2GG1	97BEK
105HISTRN5	92MN5	94DDV2MG1	97BMP
105STAG1	92MR5	94DDV2RG1	97CEK
105STAN5	92PLCAN5	94DFAN5	97CMP
105STRG1	92PLCBN5	94DFAR5	97DFAEK
105STRN5	92PLCCN5	94DFBN5	97DFAMP
116EXMSTN5SA	92PLCDFAN5	94DFBR5	97DFBEK
116EXSTCFJSA	92PLCDFBN5	94DFCN5	97DFBMP
116EXSTEKSA	92PLCDFCN5	94DFCR5	97DFCEK
125STRHA120A	92PLCDFGN5	94DFGN5	97DFCMP

125STRHR120A	92PLCDFMN5	94DFGR5	97DFGEK
57EDFAG1	92PLCDFRN5	94DFMN5	97DFGMP
57EDFAN5	92PLCGN5	94DFMR5	97DFMEK
57EDFAR5	92PLCMN5	94DFRN5	97DFMMP
57EDFBG1	92PLCRN5	94DFRR5	97DFREK
57EDFBN5	92RN5	94DV2AN5	97DFRMP
57EDFBR5	92RR5	94DV2BN5	97GEK
57EDFCG1	92ST	94DV2CN5	97GMP
57EDFCN5	93AN5	94DV2GN5	97MEK
57EDFCR5	93AR5	94DV2MN5	97MMP
57EDFGG1	93BN5	94GN5	97REK
57EDFGN5	93BR5	94GR5	97RMP
57EDFGR5	93CN5	94MR5	98BAE1
57EDFMN5	93CR5	94RR5	98BAFY
57EDFMR5	93DFAN5	95AN5	98BAG1
57EDFRG1	93DFAR5	95BN5	98BBE1
57EDFRN5	93DFBN5	95CN5	98BBFY
57EDFRR5	93DFBR5	95GN5	98BBG1
90AN5	93DFCN5	95MN5	98BCE1
90BN5	93DFCR5	95RN5	98BCFY
90CN5	93DFGN5	96BAN5	98BCG1
90GN5	93DFGR5	96BAR5	98BGE1
90MN5	93DFMN5	96BBN5	98BGFY
90RN5	93DFMR5	96BBR5	98BGG1
91AST	93DFRN5	96BCN5	98BME1
91BA	93DFRR5	96BCR5	98BMFY
91BB	93GN5	96BGN5	98BMG1
91BC	93GR5	96BGR5	98BRE1
91BG	93MN5	96BMN5	98BRFY
91BM	93MR5	96BMR5	98BRG1
91BR	93RN5	96BRN5	S106DSTD2
91BST	93RR5	96BRR5	92BN5
92AN5	94AR5	96DV2AN5	94BR5
92AR5	94BN5	96DV2BN5	96DV2CN5