



infrastructure for a connected world

PRODUCT CHANGE NOTIFICATION

Product Category PATHWAYS 20240306-1

Product Group CONNECTIVITY & PATHWAYS

ISSUE DATE: ☒ 1/1/24 ☒ EMEA ☒ LATAM ☒ AP Mar-24

IMPACTED REGIONS: ☒ DISCONTINUATION

REASON FOR CHANGE: ☐ OTHER

DESCRIPTION OF CHANGE: (Required)

All Wyr-Grid Pathways and Accessories are being discontinued for migration from Wyr-Grid to the new Panduit Wire Basket Cable Routing System.

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2024	6	4

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

IMPACTED PART NUMBER(s)	Replacement Part 1	Replacement Part 2
WG12BL10	PWB2X12BL	PWB2X12EZ
WG18BL10	PWB2X12BL	PWB2X12EZ
WG24BL10	PWB2X24BL	PWB2X24EZ
WG30BL10	-	
WG8BL10	PWB2X8BL	PWB2X8EZ
WG2PRB12BL	-	
WG2PRB18BL	-	
WGBTMWFBL	PWBWFWBL	PWBWFWEZ
WGCB12BL	PWBCB12BL	PWBCB12EZ
WGCB18BL	PWBCB18BL	PWBCB18EZ
WGCB24BL	PWBCB12BL	PWBCB12EZ
WGDW2PG	PWBDW2PG	PWBDW2BL
WGDW4PG	PWBDW4PG	PWBDW4BL
WGDW6PG	PWBDW6PG	PWBDW6BL
WGESPL2430BL	PWBFESBL	PWBHKBL
WGESPLBL	PWBFESBL	PWBHKBL
WGIBRC2BL	PWBIB2BL	PWBHKBL
WGIBRC4BL	PWBIB4BL	PWBHKBL
WGINTBRC2BL	PWBIB2BL	PWBHKBL
WGINTBRC4BL	PWBIB4BL	PWBHKBL
WGSKBL	PWBSCEZ	PWBSCEZ
WGSPL1218BL	PWBSPLBL	PWBSPLEZ
WGSPL2430BL	PWBSPLBL	PWBSPLEZ
WGINTSPLBL	PWBHKBL	PWBIB2BL
WGSW2BL	-	
WGSW6BL	-	
WGSWF4BL	-	
WGTBS12BL	PWBTB12BL	PWBHKBL
WGTBS18BL	PWBTB18BL	PWBHKBL

WGTBS24BL	PWBTB24BL	PWBHKBL
WGTBS8BL	PWBTB8BL	PWBHKBL
WG24FRTBBL	-	
WG30FRTBBL	-	
WGTL12PG	PWBTL12BL	PWBTL12PG
WGTL18PG	PWBTL18BL	PWBTL18PG
WGTL24PG	PWBTL24BL	PWBTL24PG
WGTL8PG	PWBTL8BL	PWBTL8PG
WGVWMBEZ	PWBWMBVBL	PWBHKBL
WGWMTB12BL	PWBWMNBL	PWBHKBL
WGWMTB1830BL	PWBWMWBL	PWBHKBL
WGWMTB8BL	PWBWMWBL	PWBHKBL
WG12IBRC2BL	-	
WGHWDWKTBL	PWBSPL2BL	PWBSPL5BL
WGIBRC6BL	PWBIB6BL	PWBHKBL
WGINTBRC6BL	PWBIB6BL	PWBHKBL
WGTBS30BL	-	
WG18FRTBBL	-	
WGSW4BL	-	
WG2PRB24BL	-	
WG12FRTBBL	-	
WGTL30PG	-	