



06-May-2024

**PCN #:** PCN-24-205810

**Subject :** Geometry change for the coil pins at the Power Relay 41063 and 41083

**Description of Change :** The geometry of the coil pin is changed from a square to a round pin. This change has no impacts on the previously specified values.

**Reason for Change:** Product improvement.

**Key Dates :**

**Contact By Date:**13-Aug-2024

**Implementation Date:**13-Aug-2024

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
6-1415536-4	41063042005WG, 41063042005WG		
6-1415536-7	41063046005WG, 41063046005WG		
6-1415536-9	41063053005WG, 41063053005WG		
8-1415536-6	41083046001WG, 41083046001WG		
8-1415536-7	41083050001WG, 41083050001WG		
9-1415535-3	41063050005WG, 41063050005WG		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by Accuris based on content provided by TE Connectivity.