

Amphenol Taiwan Corporation
Product Change Notification

Part Numbers Concerned :	10112632 series, 10112633 series, 10112666 series, 10120666 series, 10120667 series, 10127912 series	Originator:	Jim Hsu
Customer P/N:	NA	Issue Date:	2024/8/28
Product Description:	FCI MiniSAS HD	PCN NO:	20240609-002
Distribution:	NA		

Product Change Notice

End of life for product, MiniSAS HD(FCI part numbers) due to tool service cycle

Background:

Production tooling worn out

Product Part Number Affected:

EOL PN	Alternatives
FCI part number	Amphenol part number
10112632-101LF	G40H11331HR
10112632-121LF	NA
10112633-101LF	G40H12331HR
10112633-121LF	NA
10112666-101ALF	NA
10120666-101LF	NA
10120666-301LF	NA
10120667-101LF	NA
10120667-301LF	NA
10127912-1101BLF	G40HC132211HR
10127912-1201LF	G40H3232211HR
10112634-101LF	G40H13331HR
10120666-301LF	NA
10127912-1101LF	G40H3132211HR

Implementation date:

2024/6/9

Recommended Action:

Sales representative to inform customers .

Last Time Buy : 2024/12/31