



infrastructure for a connected world

PRODUCT CHANGE NOTIFICATION

Product Category LOOSE PIECE CABLE TIES 20240906-1

Product Group PLASTIC CABLE TIES

ISSUE DATE: ☒ 11/1/24 ☒ EMEA ☒ LATAM ☒ 14-Sep-24

IMPACTED REGIONS: ☒ DISCONTINUATION

REASON FOR CHANGE: ☐ OTHER

DESCRIPTION OF CHANGE: (Required)

We are obsoleting the weather resistant nylon 12 (-120) cable ties. There are replacement parts available.
Thank you for your continued business.

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2024	12	5

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

IMPACTED PART NUMBER(s)	Replacement Part(s)
PLT1M-M120	PLT1M-M6120
PLT1M-C120	PLT1M-C6120
PLT1.5I-M120	PLT1.5I-M6120
PLT2S-M120	PLT2S-M6120
PLT2S-C120	PLT2S-C6120
PLT3S-M120	PLT3S-M6120
PLT3S-C120	PLT3S-C6120
PLT4S-M120	PLT4S-M6120
PLT4S-C120	PLT4S-C6120
PLT4H-TL120	PLT4H-TL6120
PLT7LH-C120	PLT7LH-C6120
PLT8LH-C120	PLT8LH-C6120
PLT1.5I-C120	PLT1.5I-C6120