



25-Nov-2024

PCN #: PCN-24-227755-01

Subject : Variety of Relays

Description of Change : The listed part numbers are being discontinued and no longer available. Please consult with your local customer sales representative for further details.

Reason for Change: Product Discontinuance due to Low/no sales

Key Dates :

Last Order Date:28-Feb-2025

Last Ship/EOL Date:07-Mar-2025

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
1-1415054-1	SR4M4036		
1-1415354-1	SR6M4110		
1393258-9	V23047-A1018-A511, V23047A1018A511		
1393260-2	V23050-A1006-A542, V23050A1006A542		
1415012-1	V23047-A1060-A501, V23047A1060A501		
1415018-1	V23050-A1009-A533, V23050A1009A533		
1415354-1	SR6M4018		
2-1393258-1	V23047-A1040-A501, V23047A1040A501		
2-1393258-2	V23047-A1040-A511, V23047A1040A511		
2-1393258-3	V23047-A1060-A511, V23047A1060A511		
2-1415017-1	V23050-A1005-A551, V23050A1005A551		
2-1415054-1	SR4M4040		
2-1415543-2	SR6V6K15		
2-1415543-3	SR6V6K36		
3-1415011-1	V23047-A1006-A501, V23047A1006A501		
3-1415019-1	V23050-A1060-A551, V23050A1060A551		
3-1415367-1	SR4D4015		
4-1415021-1	V23047-A1080-A511, V23047A1080A511		
4-1415054-1	SR4M4060		
4-1415055-1	SR4D4036		
4-1415542-3	SR6V6K05		

4-1415542-4	SR6V6K21		
4-1415542-5	SR6V6K48		
4-1415542-6	SR6V6L10		
5-1415054-1	SR4M4085		
5-1415055-1	SR4D4040		
5-1415537-9	SR6A6K06		
6-1415353-1	SR6M4021		
6-1415537-0	SR6A6K09		
6-1415537-2	SR6A6K15		
6-1415537-6	SR6A6K36		
6-1415537-7	SR6A6K40		
6-1415537-8	SR6A6K48		
6-1415537-9	SR6A6K60		
6-1415538-0	SR6C6L10		
6-1415538-1	SR6C6K30		
6-1415538-2	SR6B6K30		
6-1415538-4	SR6A6K30		
7-1415011-1	V23047-A1009-A511, V23047A1009A511		
7-1415055-1	SR4D4060		
7-1415353-1	SR6M4012		
7-1415354-1	SR6D4018		
7-1415537-0	SR6A6K85		
7-1415537-2	SR6B6K05		
7-1415537-4	SR6B6K06		
7-1415537-5	SR6B6K09		
7-1415537-7	SR6B6K15		
7-1415543-5	V23047-P1009-A501		
7-1415543-7	V23047-P1021-A501		
7-1415543-9	V23047-P1036-A501		
8-1415011-1	V23047-A1036-A511, V23047A1036A511		
8-1415018-1	V23050-A1085-A533, V23050A1085A533	7-1415537-0	SR6A6K85
8-1415054-1	SR4D4006		
8-1415055-1	SR4D4085		
8-1415353-1	SR6D4021		
8-1415537-1	SR6B6K36		
8-1415537-2	SR6B6K40		
8-1415537-3	SR6B6K48		
8-1415537-4	SR6B6K60		
8-1415537-5	SR6B6K85		
8-1415537-6	SR6B6L10		
8-1415537-7	SR6C6K05		
8-1415537-8	SR6C6K06		
8-1415537-9	SR6C6K09		
9-1415054-1	SR4D4009		
9-1415366-1	SR6D4040		
9-1415537-1	SR6C6K15		
9-1415537-2	SR6C6K18		
9-1415537-3	SR6C6K21		
9-1415537-5	SR6C6K36		
9-1415537-6	SR6C6K40		
9-1415537-7	SR6C6K48		
9-1415537-8	SR6C6K60		
9-1415537-9	SR6C6K85		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by Accuris based on content provided by TE Connectivity.