




PRODUCT CHANGE NOTIFICATION

SURGE PROTECTIVE DEVICES



Select Bourns® Surge Protective Devices

Changes to Inner Packaging

Riverside, California – December 17, 2024 – As part of our continuous improvement and waste reduction efforts, effective April 1, 2025, Bourns will change the packaging for the Model [1250A](#), [1260](#), [1270](#), [1280](#), [1420A](#), [1430](#), and [1440](#) Series Surge Protective Devices. A list of affected part numbers is shown below.

To meet the EU Plastic Tax Regulation, we will eliminate the plastic bag which is used to hold the remote signal terminal of the SPD. Consequently, we will change the inner packaging structure with a notch to fit and protect the remote signal terminal. The packaging size will be changed accordingly.


Affected Part Numbers			
1250A-1S-xxx	1250A-2S-xxx	1250A-3S-xxx	1250A-4S-xxx
1260-1S-xxx	1260-2S-xxx	1260-3S-xxx	1260-4S-xxx
1260-1SMG-xxx	1260-2SMG-xxx	1260-3SMG-xxx	1260-4SMG-xxx
1260-2NS-xxx	1260-4NS-xxx	1260-2NSMG-xxx	1250A-4S-xxx
1270-1S-xxx	1270-2S-xxx	1270-3S-xxx	1260-4S-xxx
1270-2NS-xxx	1270-4NS-xxx		
1280-1S-xxx	1280-2S-xxx	1280-3S-xxx	1280-4S-xxx
1280-2NS-xxx	1280-4NS-xxx		
1420A-PV-xxx-P	1420A-PV-xxx-D	1420A-PV-xxx-Y	
1430-PV-xxx-P	1430-PV-xxx-D	1430-PV-xxx-Y	
1440-PV-xxx-P	1440-PV-xxx-D	1440-PV-xxx-Y	

xxx stands for the Operating Voltage.

Users should verify that the described changes will not impact the performance of the product in their specific applications.

SPD2443

The change to the inner packaging will have no effect on the form, fit, function, quality, or reliability of the affected part numbers as this is a packaging change only. The product specifications will not change.



Implementation dates are as follows:

Date that the use of the current packaging will cease: **April 1, 2025**

Date that the use of the new packaging will begin: **April 2, 2025**

First date codes using the above changes: **2513**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

Users should verify that the described changes will not impact the performance of the product in their specific applications.