



## Product Change Notification: CAAN-28BEVA428

---

### Date:

11-Mar-2025

### Product Category:

USB Bridge, USB Transceivers

### Notification Subject:

eSign #EOL0000444: End of Life (EOL) of USB3330E-GL-TR, USB3333E-GL-TR, USB3338E-GL-TR, USB3331E-GL-TR, USB2227-NU-11 and USB2228-NU-11 catalog part numbers (CPN).

### Affected CPNs:

**[CAAN-28BEVA428\\_Affected\\_CPN\\_03112025.pdf](#)**

**[CAAN-28BEVA428\\_Affected\\_CPN\\_03112025.csv](#)**

**PCN Status:** End of Life (EOL) Notification

### Microchip Parts Affected:

Please open one of the files found in the Affected CPNs section.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

**EOL Description:** The USB3330E-GL-TR, USB3333E-GL-TR, USB3338E-GL-TR, USB3331E-GL-TR, USB2227-NU-11 and USB2228-NU-11 catalog part numbers (CPN) will be moving to End of Life (EOL) status effective today. These catalog part numbers will no longer be offered after June 29, 2026. Please review the attached parts affected list below for the details about replacement parts if applicable.

**Note:** If replacement parts are not listed in the attached list please contact your **Local Sales Representative**

**Reason for EOL:** No longer have manufacturing support for the CPN listed in the attachment.

**Estimated Effective Dates:** Customers affected by this EOL notice are advised to place last time buy (LTB) orders as follows:

**Last Date for Bookings (LTB):** 01 June 2025

**Last Date for Shipments LTS:** 29 June 2026

**Revision History:** March 11, 2025: Issued EOL notification.

**Note:** The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable product.

## **Attachments:**

**PCN\_CAAN-28BEVA428\_Suggested Replacements.pdf**

**PCN\_CAAN-28BEVA428\_Suggested Replacements.xlsx**

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

## **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN):

USB3330E-GL-TR

USB3333E-GL-TR

USB3338E-GL-TR

USB3331E-GL-TR

USB2227-NU-11

USB2228-NU-11

PCN_CAA-28BEVA428			
EOL Catalog Part Number (CPN)	Recommended Replacement	Notes About Recommended Replacement Parts	
USB3330E-GL-TR	USB3340-EZK USB3340-EZK-TR	<a href="#">Contact Your Local Sales Office</a>	
USB3333E-GL-TR	USB3343-CP USB3343-CP-TR	Only available in 26 MHz clock frequency	<a href="#">Contact Your Local Sales Office</a>
USB3338E-GL-TR	USB3346-CP USB3346-CP-TR	A doubling of the clock frequency is required	<a href="#">Contact Your Local Sales Office</a>
USB3331E-GL-TR	USB3341-CP USB3341-CP-TR	<a href="#">Contact Your Local Sales Office</a>	
USB2227-NU-11	<a href="#">Contact Your Local Sales Office</a>		
USB2228-NU-11	<a href="#">Contact Your Local Sales Office</a>		