

Product discontinuation notification (PDN)

Title / short description	Discontinuation of VARIOCON item selection
Affected article category	Connector
Change category	Discontinuation
Change number	IAB250001-01
Reason for PCN/PDN Revision	

Purpose/objective of the change

Discontinuation due to portfolio streamlining

Detailed description of the change

Our goal is to provide you with state-of-the-art products for your applications. However, it may be necessary to phase out certain components from time to time for commercial or technical reasons. For this reason, the listed items will be discontinued in due time.

Identifying characteristics

Start of Production (SOP)	-	Last Time Delivery (LTD)	2026-06-30
Effective date (EOP)	2026-06-30	End of Service (EOSR)	-
End of Sales (EOS)	2025-12-31		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PDN-IAB250001-01_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1852820	VC-TFS 8	-	-	-	-
1854022	VC-AMS 8				
1855128	VC-K-T4-R				
1852862	VC-AF				
1853913	VC-K-KV-PG21(11,5-15,5)				
1852846	VC-TFS 2				
1886566	VC-MEMV-T2-Z-M25				
1886579	VC-MEMV-T3-Z-M25				
1853476	VC-TFS 6				
1855115	VC-K-T3-R				
1424368	VC-K-T3-IN (13-25)				
1855102	VC-K-T2-R				
1607474	VC-TFS 5-PEA				
1852927	VC-TR4/5M				
1853900	VC-K-KV-PG21(9-13)				
1853007	VC-AR4/5M				
1607274	VC-TR4/5M-PEA-S88888-SET				
1853528	VC-AMS 2				
1885978	VC-AML-L228-2AF NZ				
1852833	VC-AML 8				
1853531	VC-AML 6				
1852985	VC-AR2/3M				
1855092	VC-K-T1-R				
1884885	VC-AMLV 8				
1647734	VC-AR3/4M(2+6)-EMV NZ				
1852930	VC-K-T1-Z				
1852972	VC-AR1/2M				
1852998	VC-AR3/4M				
1853890	VC-K-KV-PG21(7-10,5)				
1855107	VC-K-T2-R-M25				
1687244	VC-AMLV-L228-2AF NZ				
1583878	VC-AMC 5				
1885237	VC-AMLV-L2266-2AF NZ				
1886663	VC-MP-T4-R-M25				
1852914	VC-TR3/4M				
1852901	VC-TR2/3M				
1886605	VC-MEMV-T2-R-M25				
1852891	VC-TR1/2M				

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
old	new				
1607407	VC-AR2/3M-S888-SET				
1852948	VC-K-T2-Z-M25				
1607748	VC-AMS 5				
1853751	VC-K-KV-PG16(7-10,5)				
1855120	VC-K-T3-R-M25				
1607745	VC-AMS 4				
1853764	VC-K-KV-PG16(9-13)				
1853939	VC-K-KV-PG21(17-20,5)				
1885224	VC-AR3/4M-EMV NZ				
1607467	VC-TFS 4-PEA				
1582520	VC-TR-PE-POL4 METALL				
1854019	VC-AMS 6				
1853683	VC-SD2				
1607774	VC-AR2/3M-PEA				
1607178	VC-TR4/5M-PEA-S22222-SET				
1607154	VC-TR2/3M-PEA-S222-SET				
1607509	VC-AML 4				
1853696	VC-SD3				
1885567	VC-K-KV-PG21 2X7,2/1X10,5				
1853227	VC-AR2-EMV				
1607088	VC-TR4/5M-PEA				
1628246	VC-MP-T2/18 PEA				
1853353	VC-MEMV-T4-Z				
1583872	VC-TR2/3M-SEW				
1852859	VC-AML 2				
1623598	VC-M-T2/10() S822 NZ:TS02				
1884911	VC-MP-T3-Z				
1607732	VC-MP-S1-2M6				
1583880	VC-K-T2-IN (10-25) G				
1607761	VC-AR1/2M-PEA				
1852943	VC-K-T2-Z				
1886760	VC-SD-A1				
1583874	VC-TR3/4M-SEW				
1607298	VC-AR1/2M-S22-SET				
1854200	VC-EMV-KV-PG21(9-13/ 9,5)				
1607062	VC-TR2/3M-PEA				
1884568	VC-MP-K1				
1853926	VC-K-KV-PG21(14-18)				
1607059	VC-TR1/2M-PEA				

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
old	new				
1855133	VC-K-T4-R-M25				
1607457	VC-HS-M3X14				
1886647	VC-MP-T2-R-M25				
1854857	VC-M-KV-PG16(11,5-15,5)	-	-	-	-
1853230	VC-AR3-EMV				
1607143	VC-TR1/2M-PEA-S22-SET				
1607431	VC-AR4/5M-S88888-SET				
1886773	VC-SD-A2				
1886634	VC-MP-T1-R-M20				
1607841	VC-T4-PR-DI				
1854035	VC-M-KV-PG21(11,5-15,5)				
1583542	VC-AMS 2-PE				
1886650	VC-MP-T3-R-M25				
1854242	VC-EMV-KV-PG21(11,5-15,5/13,5)				
1886635	VC-MP-T1-R-M25				
1852875	VC-BZS WH				
1607523	VC-AML 5				
1855157	VC-MEMV-T3-R				
1855097	VC-K-T1-R-M20				
1853243	VC-AR4-EMV				
1665075	EWR				
1607075	VC-TR3/4M-PEA				
1855131	VC-MEMV-T1-R				