

Product change notification (PCN)

Title / short description	Conversion to laser printing; UKCA approval no longer applicable at UM...Modules
Affected article category	System cabling for controllers
Change category	Marking
Change number	CDK250099E10-00
Reason for PCN/PDN Revision	

Purpose/objective of the change

Conversion to laser printing and UKCA approval not applicable

Detailed description of the change

The article labeling will be changed from printed labels to laser printing. In addition, the UKCA approval will be removed from all products in the article list.

No measures are required on the customer side. The change has no effect on the technical data of the products.

Identifying characteristics

see picture

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2026-03-01	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- PCN_CDK250099E10_ picture.pdf
- Material_list.csv
- PCN-CDK250099E10-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
2293514	UM 45-FLK10/ZFKDS	4	5		
2293527	UM 45-FLK14/ZFKDS	4	5		
2293530	UM 45-FLK16/ZFKDS	4	5		
2293543	UM 45-FLK20/ZFKDS	4	5		
2293556	UM 45-FLK26/ZFKDS	4	5		
2293569	UM 45-FLK34/ZFKDS	4	5		
2293572	UM 45-FLK40/ZFKDS	4	5		
2293585	UM 45-FLK50/ZFKDS	4	5		
2293611	UM 45-D 9SUB/S/ZFKDS	5	6		
2293624	UM 45-D15SUB/S/ZFKDS	5	6		
2293637	UM 45-D25SUB/S/ZFKDS	5	6		
2293640	UM 45-D37SUB/S/ZFKDS	6	7		
2293653	UM 45-D50SUB/S/ZFKDS	6	7		
2293666	UM 45-D 9SUB/B/ZFKDS	5	6		
2293679	UM 45-D15SUB/B/ZFKDS	5	6		
2293682	UM 45-D25SUB/B/ZFKDS	5	6		
2293695	UM 45-D37SUB/B/ZFKDS	6	7		
2293705	UM 45-D50SUB/B/ZFKDS	6	7		
2301383	UM 45-FLK20/FX2	4	5		
2962544	UM 45-FLK10	4	5		
2962557	UM 45-FLK14	4	5		
2962560	UM 45-FLK16	4	5		
2962573	UM 45-FLK20	4	5		
2962586	UM 45-FLK26	4	5		
2962599	UM 45-FLK34	4	5		
2962609	UM 45-FLK40	4	5		
2962612	UM 45-FLK50	4	5		
2962638	UM 45-FLK64	4	5		
2962641	UM 45-FLKS16	4	5		
2962654	UM 45-FLKS20	4	5		
2962670	UM 45-FLKS34	4	5		
2962683	UM 45-FLKS40	4	5		
2962696	UM 45-FLKS50	4	5		
2962719	UM 45-FLKS64	4	5		
2962722	UM 45-D 9SUB/B	5	6		
2962735	UM 45-D15SUB/B	4	5		
2962748	UM 45-D25SUB/B	4	5		
2962751	UM 45-D37SUB/B	5	6		

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
old	new				
2962764	UM 45-D50SUB/B	5	6		
2962777	UM 45-D 9SUB/S	5	6		
2962780	UM 45-D15SUB/S	4	5		
2962793	UM 45-D25SUB/S	4	5		
2962803	UM 45-D37SUB/S	5	6		
2962816	UM 45-D50SUB/S	5	6		
2965143	UM 45- 2FLK14/S7	5	6		
2965156	UM 45- 2FLK14/ZFKDS/S7	4	5		
2965211	UM 45-FLK14/ 8IM/ZFKDS/PLC	4	5		
2965224	UM 45-FLK50/32IM/ZFKDS/PLC	4	5		
2968409	UM 45-FLKS20/ZFKDS	4	5		
2968425	UM 45-FLKS34/ZFKDS	4	5		
2968438	UM 45-FLKS40/ZFKDS	4	5		
2968470	UM 45-FLKS50/ZFKDS	4	5		