## Accessories

	Product No.	Description
	3043	Interconnect Cord, 5 ft. (1,5 m). Molded-in male snap fastener at each end. Connects all 3M static control mats and runners to each other.
	3044	Ground Cord, 15 ft. (4,6 m). Molded-in male snap fastener at one end, preinstalled alligator clip at other end.
	3047	Common Point Grounding System to ground workstation components. Single-row, six-terminal strip, protective cover, three cable clips.
	3048	Grounding System for Wrist Strap/Table Mat. Easily snaps onto mats and runners; grounds two standard wrist straps. Comes complete with ring connector and 15 ft. (4,6 m) ground cord.
	991	- 262
	3050	Snap Fastener, female. For 8200 Series Table and Floor Mats and Runners.
90	3051	Ground Cord with center snap for standard field service kits. Wrist strap cord section 10 ft. (3,0 m); ground cord section 5 ft. (1,5 m).
	3057	Monitor Stand-By Jack. Allows operator to disconnect a ground cord from the wrist band and leave the workstation without deactivating the 3M workstation monitor. When the jack is grounded, the green light will illuminate and the yellow "caution" lamp will slowly flash.
	3063	Lightweight, Heavy-Duty Mat Ground Cord for lightweight field service kits. 5 ft. (1,5 m).
	8001	Cleaner for Static Control Mats. One quart (32 oz.) trigger-spray bottle or 5-gallon jug with spigot. An extra-strength cleaner for removing dirt and stains from all types of static control surfaces, including table and floor mats, hard laminate bench tops, and portable field service kits. It will also remove difficult grime from epoxy or tile flooring. Used full strength, it is a clear, colorless, water-based liquid which leaves no tacky or corrosive residue.
ESOT Stini, Control Surface Observed		