SAFETY DATA SHEET

CW8100 CircuitWorks(R) No Clean Flux Dispensing Pen

1. IDENTIFICATION OF THE SUBSTANCE/MIXTURE AND OF THE COMPANY/UNDERTAKING

Identification of the substance	or mixture
Product name	: CW8100 CircuitWorks(R) No Clean Flux Dispensing Pen
Chemical name	: CW8100 CircuitWorks(R) No Clean Flux Dispensing Pen
Product type	: Liquid.
Use of the substance/mixture	: Soldering agents - Flux agents for soldering
Company/undertaking identific	<u>ation</u>
Manufacturer	: ITW Chemtronics 8125 Cobb Center Drive Kennesaw, GA 30152 Tel. 770-424-4888 or toll free 800-645-5244
Distributor	:
Importer	: ITW Contamination Control BV Saffierlaan 5 VZ-2132 Hoofddorp The Netherlands
	Email: info@itw-cc.com
	Tel: +31 88 1307 400 FAX: +31 88 1307 499
e-mail address of person responsible for this SDS	: askchemtronics@chemtronics.com
Emergency telephone number (with hours of operation)	: Chemtrec - 1-800-424-9300 or collect 703-527-3887
2. HAZARDS IDENTIF	ICATION
The sum doubt is also sifted as downs	news and the temperature 4000/45/50 and the annual descents

The product is classified as dangerous according to Directive 1999/45/EC and its amendments.

Classification	: F; R11 Xi; R36 R43, R67
Physical/chemical hazards	: Highly flammable.
Human health hazards	: Irritating to eyes. May cause sensitisation by skin contact. Vapours may cause drowsiness and dizziness.

See Section 11 for more detailed information on health effects and symptoms.

3. COMPOSITION/INFORMATION ON INGREDIENTS

3	CAS number	%	EC number	Classification	
propan-2-ol	67-63-0	60 - 90	200-661-7	F; R11 Xi; R36 R67	[1] [2]
rosin See Section 16 for the full text of the R-phrases declared above.	73138-82-6	5 - 15	277-299-1	R43	[1]

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

[1] Substance classified with a health or environmental hazard

[2] Substance with a workplace exposure limit

Occupational exposure limits, if available, are listed in Section 8.

4. FIRST AID MEASURES

First-aid measures

Inhalation

: Move exposed person to fresh air. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. Keep person warm and at rest. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Get medical attention. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such as a collar, tie, belt or waistband.

CW8100 CircuitWorks(R) No Clean Flux Dispensing Pen				
4. FIRST AID MEAS	SURES			
Ingestion	: Wash out mouth with water. Remove dentures if any. Move exposed person to fresh air. Keep person warm and at rest. If material has been swallowed and the exposed person is conscious, give small quantities of water to drink. Stop if the exposed person feels sick as vomiting may be dangerous. Do not induce vomiting unless directed to do so by medical personnel. If vomiting occurs, the head should be kept low so that vomit does not enter the lungs. Get medical attention if adverse health effects persist or are severe. Never give anything by mouth to an unconscious person. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such as a collar, tie, belt or waistband.			
Skin contact	: Flush contaminated skin with plenty of water. Remove contaminated clothing and shoes. Wash contaminated clothing thoroughly with water before removing it, or wear gloves. Continue to rinse for at least 10 minutes. Get medical attention. In the event of any complaints or symptoms, avoid further exposure. Wash clothing before reuse. Clean shoes thoroughly before reuse.			
Eye contact	 Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for and remove any contact lenses. Continue to rinse for at least 10 minutes. Get medical attention. 			
Protection of first-aiders	: No action shall be taken involving any personal risk or without suitable training. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Wash contaminated clothing thoroughly with water before removing it, or wear gloves.			
Notes to physician	: No specific treatment. Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.			
See Section 11 for more de	tailed information on health effects and symptoms.			

5. FIRE-FIGHTING MEASURES

Г

Extinguishing media	
Suitable	: Use dry chemical, CO ₂ , water spray (fog) or foam.
Not suitable	: Do not use water jet.
Special exposure hazards	: Highly flammable liquid. In a fire or if heated, a pressure increase will occur and the container may burst, with the risk of a subsequent explosion. The vapour/gas is heavier than air and will spread along the ground. Vapours may accumulate in low or confined areas or travel a considerable distance to a source of ignition and flash back. Runoff to sewer may create fire or explosion hazard.
	Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. Move containers from fire area if this can be done without risk. Use water spray to keep fire-exposed containers cool.
Hazardous thermal decomposition products	: Hazardous decomposition products. Decomposition products may include the following materials: carbon dioxide carbon monoxide
Special protective equipment for fire-fighters	: Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

6. ACCIDENTAL RELEASE MEASURES

Personal precautions	:	No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilt material. Shut off all ignition sources. No flares, smoking or flames in hazard area. Avoid breathing vapour or mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment (see Section 8).
Environmental precautions	:	Avoid dispersal of spilt material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).
Methods for cleaning up		
Small spill	:	Stop leak if without risk. Move containers from spill area. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Use spark-proof tools and explosion-proof equipment. Dispose of via a licensed waste disposal contractor.
Large spill	:	Stop leak if without risk. Move containers from spill area. Approach the release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see section 13). Use spark-proof tools and explosion-proof equipment. Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilt product. Note: see section 1 for emergency contact information and section 13 for waste disposal.

CW8100 CircuitWorks(R) No Clean Flux Dispensing Pen

7. HANDLING AND STORAGE

Handling	Put on appropriate personal protective equipment (see Section 8). Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Persons with a history of skin sensitization problems should not be employed in any process in which this product is used. Do not get in eyes or on skin or clothing. Do not ingest. Avoid breathing vapour or mist. Use only with adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Do not enter storage areas and confined spaces unless adequately ventilated. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Store and use away from heat, sparks, open flame or any other ignition source. Use explosion-proof electrical (ventilating, lighting and material handling) equipment. Use non-sparking tools. Take precautionary measures against electrostatic discharges. To avoid fire or explosion, dissipate static electricity during transfer by earthing and bonding containers and equipment before transferring material. Empty containers retain product residue and can be hazardous. Do not reuse container.
Storage	: Store in accordance with local regulations. Store in a segregated and approved area. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see section 10) and food and drink. Eliminate all ignition sources. Separate from oxidizing materials. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabelled containers. Use appropriate containment to avoid environmental contamination.
Packaging materials	
Recommended	: Use original container.

8. EXPOSURE CONTROLS/PERSONAL PROTECTION

Exposure limit values	
Ingredient name	Occupational exposure limits
propan-2-ol	ACGIH TLV (United States, 1/2009). STEL: 400 ppm 15 minute(s). TWA: 200 ppm 8 hour(s).
Recommended monitoring procedures	: If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to European Standard EN 689 for methods for the assessment of exposure by inhalation to chemical agents and national guidance documents for methods for the determination of hazardous substances.
Exposure controls	
Occupational exposure controls	: Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls also need to keep gas, vapour or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.
Hygiene measures	: Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.
Respiratory protection	: Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary. Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator.
Hand protection	: Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary.
Eye protection	: Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists or dusts.
Skin protection	: Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.
Environmental exposure controls	: Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels.

9. PHYSICAL AND CHEMICAL PROPERTIES

General information	
Appearance	
Physical state	: Liquid.
Colour	: Colourless to light yellow. [Light]
Odour	: Alcohol-like. [Slight]

Date	of	issue/Date of
revis	ior	1 IIII

CW8100 CircuitWorks(R) No	Clean Flux	Dispensing Pen			
9. PHYSICAL AND (CHEMIC	AL PROPERTI	ES		
Important health, safety and	environme	ntal information			
Boiling point Melting point	: 82°C (1 : -89°C (
Flash point	`	cup: 12°C (53.6°F). (Tagliabue)		
Relative density		Water = 1)	ragilabae.)		
Vapour density	: >1 (Air	,			
Evaporation rate (butyl acetate = 1)	: 1.7 (pro	pan-2-ol) compared v	vith butyl acetate	е	
Other information Auto-ignition temperature	· Low	est known value: 399	°C (750 2°E) (n	ropan-2-ol)	
10. STABILITY AND			с (: сс. <u> </u>		
Stability		duct is stable.			
Conditions to avoid	braze, s		pose container	or flame). Do not pres is to heat or sources of	
Materials to avoid	: Highly r	eactive or incompatib g materials			
Hazardous decomposition products	: Under r	-	torage and use,	, hazardous decompos	ition products should
11. TOXICOLOGICAI		MATION			
Potential acute health effects	2				
Inhalation	: Vapour	s may cause drowsine	ess and dizzines	SS.	
Ingestion	: No kno	wn significant effects	or critical hazar	ds.	
Skin contact	: May ca	use skin irritation. Ma	ay cause sensiti	isation by skin contact	
Eye contact	: Irritating	to eyes.			
Acute toxicity					
Product/ingredient name propan-2-ol		Result LD50 Dermal LD50	Species Rabbit Rat	Dose 12800 mg/kg 2735 mg/kg	Exposure - -
		Intraperitoneal LD50 Intravenous	Rat	1088 mg/kg	-
		LD50 Oral	Rat	5045 mg/kg	-
		LD50 Oral TDLo	Rat Rat	5000 mg/kg 800 mg/kg	-
		Intraperitoneal	. at	ooo mg/ng	
		LC50 Inhalation	Rat	16000 ppm	8 hours
Potential chronic health effe	<u>cts</u>	Gas.			
Chronic effects			ergic reaction m	nay occur when subse	quently exposed to
Carcinogenicity	very lov	wn significant effects	or critical hazar	de	
Mutagenicity		wn significant effects			
Teratogenicity		wn significant effects			
Developmental effects		wn significant effects			
Fertility effects		wn significant effects			
Over-exposure signs/sympto		0			
Inhalation	nausea headac	e symptoms may inclu or vomiting he ess/fatigue	ide the following	g:	
		ss/vertigo			
Ingestion	: No spe	cific data.			
Skin	: Adverse irritation redness		ide the following	g:	
Eyes	: Adverse irritation watering redness	g	ide the followinູ	g:	
Target organs	Contair		cause damage	he following organs: e to the following organ	

12. ECOLOGICAL IN				
Environmental effects	: No known significant e	ffects or critical hazards.		
Aquatic ecotoxicity Product/ingredient name propan-2-ol	Test -	Result Acute LC50 11130000 ug/L Fresh water	Species Fish - Fathead minnow - Pimephales promelas - Juvenile (Fledgling, Hatchling, Weanling) - 4 to 8 weeks - 1.1 to 3.1 cm	Exposure 96 hours
	-	Acute LC50 10400000 to 10600000 ug/L Fresh water	Fish - Fathead minnow - Pimephales promelas - 29 days - 20 mm - 0.103 g	96 hours
	-	Acute LC50 9640000 to 10000000 ug/L Fresh water	Fish - Fathead minnow - Pimephales promelas - 31 days - 20.6 mm - 0.117 g	96 hours
	-	Acute LC50 6550000 to 7450000 ug/L Fresh water	Fish - Fathead minnow - Pimephales promelas - 31 days - 17.4 mm - 0.082 g	96 hours
	-	Acute LC50 4200000 ug/L Fresh water	Fish - Harlequinfish, red rasbora - Rasbora heteromorpha - 1 to 3 cm	96 hours
	-	Acute LC50 1400000 to 1950000 ug/L Marine water	Crustaceans - Common shrimp, sand shrimp - Crangon crangon	48 hours
	-	Acute LC50 >1400000 ug/L	Fish - Western mosquitofish - Gambusia affinis - 20 to 30 mm	96 hours
Conclusion/Summary <u>Biodegradability</u>	: Not available.			
Conclusion/Summary	: Not available.			
Other adverse effects	: No known significant e	ffects or critical hazards.		
13. DISPOSAL CON	SIDERATIONS			
Methods of disposal	SIDERATIONS The generation of waste should be avoided or minimised wherever possible. Empty containers or liners may retain some product residues. This material and its container must be disposed of in a safe way. Dispose of surplus and non-recyclable products a licensed waste disposal contractor. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Avoid dispersal of spilt material and runoff and contact with soil, waterways, drains and sewers			

Hazardous waste : The classification of the product may meet the criteria for a hazardous waste.

14. TRANSPORT INFORMATION

International transport regulations							
Regulatory information			Classes	PG*	Label	Additional information	
ADR/RID Class	Not regulated.	-	-	-		-	
ADN/ADNR Class	Not regulated.	-	-	-		-	
IMDG Class	Not regulated.	-	-	-		-	
IATA Class	Not regulated.	-	-	-		-	

PG* : Packing group

sewers.

CW8100 CircuitWorks(R) No Clean Flux Dispensing Pen

15. REGULATORY INFORMATION

EU regulations

Classification and labeling have been determined according to EU Directives 67/548/EEC and 1999/45/EC (including amendments) and take into account the intended product use.

Highly flammable, IrritantRisk phrases: R11- Highly flammable. R36- Irritating to eyes. R43- May cause sensitisation by skin contact. R67- Vapours may cause drowsiness and dizziness.Safety phrases: S24- Avoid contact with skin. S37- Wear suitable gloves.Contains: rosinProduct use: Professional applications.Europe inventory: All components are listed or exempted.	Hazard symbol or symbols	
R36- Irritating to eyes.R43- May cause sensitisation by skin contact.R67- Vapours may cause drowsiness and dizziness.Safety phrases: S24- Avoid contact with skin.S37- Wear suitable gloves.Contains: rosinProduct use: Professional applications.		Highly flammable, Irritant
S37- Wear suitable gloves. Contains : rosin Product use : Professional applications.	Risk phrases	R36- Irritating to eyes. R43- May cause sensitisation by skin contact.
Product use : Professional applications.	Safety phrases	
	Contains	: rosin
Europe inventory : All components are listed or exempted.	Product use	: Professional applications.
	Europe inventory	: All components are listed or exempted.

16. OTHER INFORMATION

Full text of R-phrases referred to in sections 2 and 3 - Europe	:	R11- Highly flammable. R36- Irritating to eyes. R43- May cause sensitisation by skin contact. R67- Vapours may cause drowsiness and dizziness.
Full text of classifications referred to in sections 2 and 3 - Europe	-	F - Highly flammable Xi - Irritant
<u>History</u>		
Date of printing	:	12/6/2011.
Date of issue/Date of revision	1	12/6/2011.
Date of previous issue	1	No previous validation.
Version	:	8
Prepared by	:	Not available.

Notice to reader

To the best of our knowledge, the information contained herein is accurate. However, neither the above-named supplier, nor any of its subsidiaries, assumes any liability whatsoever for the accuracy or completeness of the information contained herein.

Final determination of suitability of any material is the sole responsibility of the user. All materials may present unknown hazards and should be used with caution. Although certain hazards are described herein, we cannot guarantee that these are the only hazards that exist.