

SOURIAU

25 Grumbacher Road
York, Pa 17406
USA

Tel: 717-767-6705
Fax: 717-505-5945
www.souriau.com


Subject: Product Change Notification Change on UTO coupling gasket and receptacle housing

Product Part Number:

All 0, 1, 7 type receptacles of the UT0/UT0W series are affected. Product part numbers remain the same.

UT0*T* and UT0*N* connector part numbers and HA* harness with a UTO receptacle are not impacted by this modification.

Description of Change: A groove is added in the UTO receptacle, and the design of the coupling gasket is changed



Reason for Change: Avoid the dislodging of the seal during shipment and to improve the dynamic sealing.

Anticipated Impact on Form, Fit, or Function: None

Implementation Date: Immediate, Souriau can deliver original receptacle design until current stock depletion. Existing product is functionable. The anticipated effectivity across entire line will be 01/01/13.