

ITW Switches An Illinois Tool Works Company 2550 Millbrook Drive Buffalo Grove, IL 60089 Ph: 800.544.3354

Fax: 847.876.9440

November 12, 2014

To: ITW Switches Product Managers

Re: Discontinued Product

Due to diminished volumes, the following parts are being discontinued:

030-808-005 (possible sub of 030-808-030 .30 shaft length vs .05)

11-204 (no sub, screw terminal no longer available)

16-40441 (sub mil version 16-488051)

48M212W (no sub)

48M212G (no sub)

Please refer to our website for product drawings of recommended part substitutions.

All last time buy orders need to be received by December 10, 2014. Please contact Customer Service if we can assist you in any way through this process.

Best regards,

Candy Banks National Distribution Manager

, . .