



# Product Change Notice

PCN Number: 15-0834-03  
Issue Date: 05-JANUARY-2016

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:**

SP1481ECN-L/TR	SP1481ECN-L	SP1481EEN-L/TR	SP1481EEN-L
SP1485ECN-L/TR	SP1485ECN-L	SP1485EEN-L/TR	SP1485EEN-L
SP1485EMN-L/TR	SP1485EMN-L	SP481ECN-L/TR	SP481ECN-L
SP481EEN-L/TR	SP481EEN-L	SP485CN-L/TR	SP485CN-L
SP485ECN-L/TR	SP485ECN-L	SP485EEN-L/TR	SP485EEN-L
SP485EMN-L/TR	SP485EMN-L	SP485EN-L/TR	SP485EN-L

**CHANGE CATEGORY:**

<input type="checkbox"/> Material	<input type="checkbox"/> Process	<input type="checkbox"/> Package
<input type="checkbox"/> Design	<input type="checkbox"/> Datasheet	<input type="checkbox"/> Packing/Shipping
<input checked="" type="checkbox"/> Other: Alternate assembly location		

**DESCRIPTION OF CHANGE:**

Qualified JCET, China, for assembly of the listed parts.

**IMPACT OF CHANGE:**

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 05-APRIL-2016

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.