

Product Family	Micro-Fit	10673973	
		GCN Number	
Series	43020, 36727, 36795, 36856, 68801, 79736, 79916	March 10, 2015	
		Date Issued	
Reason For Change	New, Modified, Or Replacement Tooling		
Change Description	This letter is to inform you that Molex is building new molds to make Micro-Fit 43020 series Plugs. The current molds are being replaced due to excessive ware. The new molds will run the 14 through 24 circuit sizes. As previously notified we will be changing materials when the replacement tools are completed.		
Feries image - Reference only			
Part Numbers Affected	Please refer to CustomerPartList.csv attached to	e-mail message.	
Reason For Short Notice Exception			
Assessment Of Change (How Product Will Be Qualified & Validated)	Product from the new molds will be fully qualified before it is released to production.		
Internal Molex Qualification Date (Planned Date Information Available)	March 27, 2015		
Sample Availability Date (Changed Part)	March 27, 2015		
Date of Implementation	April 10, 2015		
Method of Identifying Change	Product molded after April 10, 2015 can contain this change.		
Recommended Replacement Parts	Not Applicable		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com