

# **Accessories & Production Aids**



#### CT-1

 CROWN<sub>®</sub> lead-free tip tinner and cleaner to maintain your Edsyn CROWN<sub>®</sub> tips or any heavy duty tips (1.5 oz. or 42.5g)



#### WP286

- WIGAPRY® desoldering aid
- Use to straighten pins or leads and remove circuit devices



### **WP556**

WIGAPRY® mini screwdriver and calibration aid tool



 SMD helper helps remove surface mount devices while using soldering or hot air tools



#### ST706

 SMD helper helps lift and remove surface mount devices while using hot air tools (.002 shim, .238 width)



#### LT-1

 LONER® lead -free tip tinner and cleaner to maintain your Edsyn LONER® soldering tips (.5 oz or 14.2g)



# **RB641**

 SMD shim blade replacement with staticsafe spool holder to be used with ST706 or ST800 SMD helpers



### WS630

 SMD pull wire replacement and static-safe spool holder to be used with ST706 or ST800 SMD helpers [Dia: .01 in. (.25 mm) L: 10 ft (3.05 m)]



# TC383

 K-Type thermocouple and subminiature connector assembly with ZD13 desoldering tip and RS383 retaining sleeve attached (use as a calibration aid with MS412 temperature measuring system)



#### WT618

• Dual ended wrench for removing hot air tips (set of 2)



# WT619

 Tip wrench for removing desoldering tips using RS383 retaining sleeve (comes with UC274 clamp for attaching to station for easy access)



## WT620

 Socket wrench for removing smaller hot air tips that use RN432 and RN433 retaining nuts



### **OL111**

• O-Ring lube for lubrication and longer tool life



# MS412

 Compact digital meter system suitable for measuring and calibrating soldering or desoldering tip temperatures. Displays in C° and F°.

Note: This section is limited. For a complete list ask for Edsyn's Hand Tools Catalog solely dedicated to production aids and accessories.

www.edsyn.com













