

CMIO-AICC-AMPHENOL Product Change Notification

Part Numbers Concerned :	57 Series, 157 series, 57LE23500620C98, 57LE40360730044	Originator:	PPM- Megan Teng
Product Description:	Centronics, Micro-Ribbon, 57 Series, 57LE Board connector 157Series, IDC connector	Issue Date:	10 th , APR., 2017
		PCN NO:	P-17-00002
Distribution:	Zinc Plating is concerning restrict process regarding to local government environmental policy		

Product Change Notice

Due to the plating material of Zinc is the restrict substance regards to local government environmental policy, the current metal shells of 57/ 57LE and 157 series using Zinc plating will be rolling change to Nickel plating.

The change doesn't impact to product fit, form and functional factors at all but only the appearance color of metal shell is obviously different.

- **color of metal shell appearance would be different**

Zinc Plating On Metal Shell (Old)



Nickel Plating On Metal Shell (New)



Background:

Environmental Policy

Product Part Number Affected:

5710012P, 57100221H, 5710022P, 5710140 , 571014010 , 57101404 ,
57101405 , 571024013 , 571024014 , 57102404 , 5710302P, 5710312P,
5710360 , 571036013 , 571036014 , 571036017 , 571036025 , 571036026 ,
571036027 , 5710500 , 5710500101448 , 571050014 , 571050014448 ,
571050022 , 571050027 , 5710500375448 , 571050046 , 571050046424 ,
571050048 , 571050054 , 57105006 , 57105006402 , 571050069424 ,
571050069448 , 57105007 , 571050073 , 571050077 , 571050077448 ,

CMIO-AICC-AMPHENOL
Product Change Notification

57105008 , 57105008424 , 571050095 , 571050095448 , 571050099 , 5710640 ,
571064011 , 5710640398 , 5710640448281 , 5715232P , 5718152P , 5718862P ,
571925142 , 571925502 , 5719422 , 571947 , 571966502 , 57198812P ,
57198962P , 5720140 , 572014012 , 57201404 , 57201408 , 5720240 ,
572024011 , 572024011424 , 572024011448 , 572024014 , 572024014424 ,
572024014448 , 57202402 , 572024023 , 572024024 , 57202402424 ,
572024024448461 , 57202402448 , 572024025 , 572024025448 , 572024029 ,
57202408 , 572032P , 5720360 , 572036010 , 572036020 , 572036020448 ,
572036021 , 57203609 , 5720500 , 572050015 , 572050019 , 572050031 ,
572050057 , 572050058 , 57205006 , 572050065 , 572050065448 , 57205007 ,
572050073 , 57205007448 , 572050077424 , 572050079 , 572050085 ,
572050087 , 572050087448 , 57205009 , 5720640 , 5720640398 ,
5720640448281 , 5720872P , 5720882P , 5730140 , 57301406448 , 5730240 ,
5730240424 , 5730240448 , 5730240485 , 5730360 , 5730360375448 ,
5730360424 , 5730360448 , 5730360485 , 5730500 , 573050021 ,
573050021448 , 573050021448485 , 573050021485 , 573050028 , 57305003 ,
57305003424 , 57305003448 , 5730500375 , 5730500424 , 5730500448 ,
5730500485 , 5730500524 , 5730501 , 57331401 , 57332401 , 57333601 ,
57333601448 , 57335001 , 57335001448 , 57336401 , 57336402 , 5740140 ,
574014011 , 574014011398 , 574014016 , 574014027 , 5740140398 ,
57401408 , 5740240 , 574024011 , 574024014 , 574024015 , 574024016 ,
574024018398 , 5740240398 , 5740240448 , 57402409 , 5740360 , 574036012 ,
574036016 , 574036021 , 574036021424 , 574036021448 , 574036022 ,
574036023 , 574036024 , 574036024424 , 5740360375448 , 574036039448 ,
5740360398 , 5740360424 , 5740360448 , 57403609 , 57403609424 , 5740500 ,
574050016 , 574050023 , 574050023424 , 574050024 , 574050024398 ,
574050024448 , 574050024448441 , 574050026 , 574050026448 , 574050027 ,
574050027438 , 574050028441 , 574050031448441 , 574050032448 ,
574050036 , 5740500398 , 57405004 , 5740500424 , 5740500441 ,
5740500512 , 57405009 , 57455003 , 5750140 , 5750240 , 5750360 , 5750500 ,
5760140 , 5760140398 , 5760240 , 5760360 , 5760360424 , 5760500 ,
5760500424 , 577050012 , 577064016 , 577064017 , 577064018398448 ,
579214011 , 579214012 , 579236011 , 579264512448 , 57LE23500620C98 ,
57LE40360730044 , 157116402 , 157116404448 , 15712140 , 157122403 ,
15712360 , 15712500 , 1571250014 , 1571250014448 , 1571250027 ,
157125003 , 1571250030448 , 15712500448 , 157126402 , 157126402448 ,
15712640448 , 157126405448 , 15722140 , 15722240 , 15722360 , 15722500 ,
1572250014 , 1572250015441 , 1572250019 , 1572250020448 ,
1572250020494 , 157225003 , 1572250031448 , 157225003448 ,
15722500441448 , 15722640 , 15722640448 , 157226405 , 15732140 ,
15732240424472 , 15732360 , 15732360424 , 157323604451 , 157323605448 ,
15732500 , 1573250010 , 1573250014 , 1573250016448 , 1573250016448B ,
1573250017 , 1573250017B , 1573250018 , 1573250018AL , 1573250018B ,
15732500424 , 15732500448 , 157325005 , 157325005448 , 157326401 ,
157326403 , 157326403424472 , 157335001 , 15742140 , 15742360 ,
15742360441 , 15742500 , 1574250014475 , 15742500424 , 15742500441 ,
157425005441 , 157425005441472 , 157425005448488 , 15752140 , 15752360 ,
15752500 , 15762140 , 15762240 , 15762240448 , 15762360 , 15762500 ,
157625003 , 15762500424 , 15762500448 , 157625007 , 157625007448 ,
157625007510 , 157625008 , 1577164020448 , 1577250018 , 1577250018448 ,

CMIO-AICC-AMPHENOL
Product Change Notification

1577250022, 1577250022B, 157725003 , 157725003431 , 157725003448P,
157725003450 , 157725003472 , 157725003B, 1577250042448 ,
1577250042448B, 1577250046448 , 1577250049448 , 1577250050B,
1577250051448 , 1577250051448B, 1577250053448 , 1577250053448B,
1577250053508 , 1577250054448B, 1577250055448 , 1577250059 ,
1577250061 , 1577250062508 , 1577264016 , 1577264020448 , 157726403431 ,
1577264044 , 1577264044448 , 1577264047448 , 1577264048448 ,
1577264049448 , 1577264056 , 1577264056448 , 1577264057B,
1577264058448 , 1578250018 , 1578250022 , 1578250022B, 157825003 ,
157825003424 , 157825003431 , 157825003448 , 157825003448B,
157825003448P, 157825003B, 1578250046448 , 1578250048B,
1578250049448 , 1578250050448 , 1578264016 , 1578264016448 ,
1578264018 , 1578264018448 , 1578264021 , 1578264021398 ,
1578264022398 , 157826403431 , 1578264048448, 1578264049448

Implementation date:

It will be rolling change of using out current stock till 28th, SEP., 2017, no Zinc plating on metal shell any more after the deadline.

Recommended Action:

Sales team informs customers about the changes for the affected P/N

DOC#:QRF-04-041 A