Connectors for control signals









Туре		Number of poles	Description	Order no.
CM 02 L 14S-61 P F	70,30 UNET 24	6 + PE	Surface-mounted connector with flange, tipped with filters 6x1 nF Operating current: 2 A	932 988-100
CM 02 E 20-15 P	12-16 UNE 5-2A 22 22 22 22 22 22 22 22 22 22 22 22 2	7	Surface-mounted connector with flange, contacts with solder bucket Operating current: 16 A	933 050-100
CM 02 E 20-7 P	7 7 7 10 10 10 10 10 10 10 10 10 10 10 10 10	8	Surface-mounted connector with flange, contacts with solder bucket Operating current: 10 A	932 845-100
CM 02 E 20-27 P	116-16 (1763-22A	14	Surface-mounted connector with flange, contacts with solder bucket Operating current: 5 A	933 062-100
CM 02 E 20-29 P	11-18 LMF 2A 10-18 LMF 2A 10	17	Surface-mounted connector with flange, contacts with solder bucket Operating current: 4 A	933 063-100

