

<b>NO:</b> REL - 200	<b>PRODUCT:</b> G8V / G8VA / G8V-RH – Automotive Plug-In Relay
<b>DATE:</b> January 2018	<b>TYPE:</b> DISCONTINUATION – Streamline Product Offering


## G8V / G8VA / G8V-RH Automotive Plug-In Relay – DISCONTINUATION

In an effort to streamline our product offering and focus on popular models of Omron’s line of Automotive Plug-In Relays, OMRON will discontinue the G8V / G8VA / G8V-RH Automotive Plug-In relay models at the end of June 2018. There are no suggested replacements for these relays series. Please carefully read through this notification; should you have any additional questions, however, please communicate with the Automotive Relay Product Specialist.

**NOTE: This notice is only applicable to the Americas / General use customers**

**LAST Order date (Last Time Buy Date)**

**May 31, 2018**



**G8V / G8VA / G8V-RH Details of the Changes:**

Discontinued Product	Suggested Replacement
Model G8V	No recommended replacement
Model G8VA	No recommended replacement
Model G8V-RH	No recommended replacement

**Note: Existing Automotive OEM’s are currently excluded due to contractual agreements.**

\* Sales teams should communicate this discontinuation with their OEM's and CEM's.  
For further technical support and any questions, please communicate with Product Marketing.

Specifications in this product news are as of the issue date and are subject to change without notice.  
Only main changes in specifications are described in this document. Please be sure to read the relevant catalogs, datasheets, product specifications, instructions, and manuals for precautions and necessary information when using products.  
This PCN is intended for use in the Americas  
Last time buy dates are subject to change based on availability