


Product Change Notification

INDUCTIVE COMPONENTS



April, 2018

Certain Part Numbers in the Bourns® Model 5200 Hash Choke Series

Change to Packaging Method & MOQ/Mult Quantities

Bourns is changing the packaging method for certain part numbers in the [Model 5200](#) Hash Choke Series to better protect the components during shipping and handling. The new packaging uses a Styrofoam tray for better protection.

Part Number	Current Packaging	New Packaging
5230-RC 5240-RC 5248-RC 5250-RC 5252-RC 5254-RC 5256-RC 5258-RC		

As the result of the packaging change, the Minimum Order Quantity (MOQ) / Multiples Quantity (Mult) of the affected part numbers will be adjusted.

Part Number	Current MOQ/Mult	Revised MOQ/Mult
5230-RC	5760/96	5040/144
5240-RC	5032/148	5040/144
5248-RC	5016/44	5040/144
5250-RC	5070/130	5040/144
5252-RC	5040/60	5040/144
5254-RC	5040/60	5040/144
5256-RC	5040/42	5040/144
5258-RC	5040/60	5040/144

Users should verify that the described changes will not impact the performance of the product in their specific applications.

IC1822

The changes to the packaging method and the MOQ/Mult quantities will not affect the products' form, fit, function, quality or reliability. The quality of the packaging should be improved.

Implementation dates are as follows:

*Date that manufacturing of existing packaging and MOQ/Mult quantities will cease: **May 12, 2018***

*Date that deliveries of revised packaging and MOQ/Mult quantities will begin: **May 13, 2018***

*First date code using the above changes: **1820***

If you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).