

1 Products affected


Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.			
SBU PG PUG Type							
02 007 013 0000002303	See list below	Connectors	Appliance Outlet 16A 4797-5	-			
*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)							

List of part numbers affected						
3-102-168	3-102-321	3-102-322	3-102-323	3-102-324		
3-102-335	3-103-009	3-103-012	3-103-014	3-103-016		
3-103-252	3-103-566	3-103-636	3-104-613	3-104-614		
3-109-980	3-110-069					

2 Type of change

- Change of material
- Change of approval
- Change of marking
- Change of packaging label

3 Detailed description of change



Product Change Notification				PCN for 4797-5				
owner	creation date	release date	released by	change order no	rev	page	D40 000 604	
vettersa	20.08.2018	20.09.2018	limachcl	2016092	Α	1 of 2	D10-028-631	



4 Reason of change

- Material consolidation.
- Appearance consolidation (colour according to 4710-5)
- **New CCC Approval**

5 Release date

Fit

The change will be rolled-out starting ww 39/2018 (Date code 1839 or higher on label) and lasts approx. 6 months depending on the variant.

Impact of change and recommended action

Form Yes Approval sign: CCC added to moulding part

Appearance of colour No No change for dimension **Function** No No change in function

Manufacturing No change for manufacturing site No

Label Yes Approval sign: CCC added to packaging label

Packaging No No change in packaging

Reference Documents / Attachments

Kind of document	Remarks
Data Sheet	

Product Change Notification				PCN for 4797-5				
owner	creation date	release date	released by	change order no	rev	page	D40 000 604	
vettersa	20.08.2018	20.09.2018	limachcl	2016092	Α	2 of 2	D10-028-631	