

Product Change Notification

Date: 11 - 12 - 18

PCN - 9245

Title Change:

Size 20 contact Insertion Bit modification

Product (s) Affected:

356-20

Reason for Change:

Insertion bit was bottoming out prior to contact inserting completely into pocket detail on some of the Con-X Cable and Inline connectors.

Description of Change:

Shortened shoulder location 0.040 from front tip where contact is held.

Estimated Schedule for Change:

Change implemented immediately

Customer Acknowledgement

(To be filled out by customer and returned to Conxall)

The indicated Customer Notification letter was received and acknowledged by the undersigned authority.

Name: _____

Signature

Print

Company: _____

Location: _____

Title: _____

Date: _____