



28-Mar-2018

PCN #:E-18-001373

Subject:RF relay series

Description of Change: Relay marking process for RF relay series will be changed from pad printing to laser marking!

Reason: Product Improvement. Dear Customer, you are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. These parts are affected by the change mentioned above!

Impact of Change:form - fit - function

Key Dates:

Contact By Date:22-Jun-2018

Implementation Date:22-Jun-2018

Product Affected

2-1833005-3

1-1833005-4

(Alias Part Numbers:

"RFJ33012")

1-1833005-5

(Alias Part Numbers:

"RFJ33024")

2-1415536-4

(Alias Part Numbers:

"RF900009WG")

6-1415535-6

(Alias Part Numbers:

"RF900007WG")

Product Affected

2-1833005-5

1-1833005-9

9-1415520-1

(Alias Part Numbers:

"RFH54005WG")

2-1833005-0

7-1415517-1

(Alias Part Numbers:

"RF334012WG")

2-1415520-1

(Alias Part Numbers:

"RFH34005WG")

3-1415521-1

(Alias Part Numbers:

"RFH54024WG")

1-1833005-3

(Alias Part Numbers:

"RF900011WG")

1-1415519-1

(Alias Part Numbers:

"RF3D4012WG")

4-1415512-1

(Alias Part Numbers:

"RFHD4024")

1-1833005-8

1415511-1

(Alias Part Numbers:

"RFH34024")

9-1415536-2

(Alias Part Numbers:

"RF900010WG")

9-1415521-1

(Alias Part Numbers:

"RFHD4012WG")

6-1415520-1

(Alias Part Numbers:

"RFH34024WG")

1-1833005-6

2-1833005-7

2-1833005-2

Product Affected

1415522-1

(Alias Part Numbers:
"RFHD4024WG")

2-1415521-1

(Alias Part Numbers:
"RFH54012WG")

1415521-1

(Alias Part Numbers:
"RFH54006WG")

2-1833005-4

2-1833005-6

8-1415513-1

(Alias Part Numbers:
"RF334012")

6-1415510-1

(Alias Part Numbers:
"RFH34012")

4-1415528-1

(Alias Part Numbers:
"RF900003WG")

9-1415513-1

(Alias Part Numbers:
"RF334024")

4-1415518-1

(Alias Part Numbers:
"RF354012WG")

4-1415520-1

(Alias Part Numbers:
"RFH34009WG")

8-1415517-1

(Alias Part Numbers:
"RF334024WG")

1-1415521-1

(Alias Part Numbers:
"RFH54009WG")

5-1415520-1

(Alias Part Numbers:
"RFH34012WG")

6-1415511-1

(Alias Part Numbers:

Product Affected

"RFH54012")

5-1415520-2

2-1833005-8

3-1415520-1

(Alias Part Numbers:

"RFH34006WG")

5-1415517-1

(Alias Part Numbers:

"RF334006WG")

2-1833005-1

9-1415520-2

3-1415530-1

(Alias Part Numbers:

"RFJ34012")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.