



20-Dec-2018

PCN #:P-18-016641

Subject:Manufacturing Location Change of Menlo Park Appliances Tubing RNF-100 Products

Description of Change: Manufacturing location change. Back in 2016 (see PCN P-16-013872) TE connectivity notified that we have qualified RNF-100 for Manufacture in the Trutnov plant and would start the manufacturing transfer process. Since this time, we have learned many lessons and faced many challenges in this complex transfer. Consequently, we need to process future product transfers within this project a little differently. To do this we will be issuing new part numbers to all the transferring products which have the Unit of measure of Feet. Future Units of Measure will be either Piece or [Metres.We](#) will retrospectively issue new part numbers for the RNF-100 parts that have already moved for manufacture in the Trutnov plant. As part of the production move, we will start to ship additional RNF-100 tubing products after 28th February 2019 from the Trutnov facility. After this date TE reserves the right to provide qualified products from Menlo or Trutnov manufacturing locations.

Reason: Dear Customer, we hereby inform you about a transfer of processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. Upon request, a PPAP Level 2 will be available if it concerns a transfer of a tool which produces a finished TE-product. A PPAP Level 1 will be available if it concerns a component of a TE-product, where the production location of the finished TE-product remains unchanged. If you require such a PPAP, please notify the responsible TE Sales Contact within 14 calendar days after receipt of this PCN. TE will also be changing the Unit of measure for the - STK descriptions. The original UOM was either Feet for the new parts the UOM is Piece

Key Dates:

Contact By Date:28-Feb-2019
Implementation Date:28-Feb-2019

Product Affected

5053302039

(Alias Part Numbers:

"1193878-3"

"RNF-100-1-RD-STK")

5053824030

(Alias Part Numbers:

"1193891-4"

"RNF-100-3/32-GN-SP")

077449-000

(Alias Part Numbers:

"3-1197863-5"

"RNF-100-1/4-WH-STK-CS5551")

5070074081

(Alias Part Numbers:

"2-1193964-9"

"RNF-100-3/8-CL-SP")

5053442033

(Alias Part Numbers:

"5-1193887-7"

"RNF-100-3-BK-STK")

648425-000

(Alias Part Numbers:

"8-1195118-4"

"RNF-100-1/2-YO-FSP")

570898-000

(Alias Part Numbers:

"1-1198935-0"

"RNF-100-3/32-GN-SP-CS5004")

992377-000

(Alias Part Numbers:

"8-1197675-3"

"RNF-100-1/4-YO-SP-CS7554")

5070044083

(Alias Part Numbers:

"1193961-7"

"RNF-100-1/8-CL-SP")

Product Affected

5055184015

(Alias Part Numbers:

"7-1193901-0"

"RNF-100-3/64-GN-SP")

5053174051

(Alias Part Numbers:

"3-1193860-0"

"RNF-100-3/8-BU-SP")

507011M074

(Alias Part Numbers:

"4-1193969-6"

"RNF-100-1-1/2CL-SP-CS5533")

459730-000

(Alias Part Numbers:

"1-1199022-2"

"RNF-100-3/64-WH-SP-CS5004")

A16446-000

(Alias Part Numbers:

"5-1201677-3"

"RNF-100-1/2-BK-SP-CS5004")

5052862030

(Alias Part Numbers:

"4-1193822-4"

"RNF-100-3/64-YO-STK")

505339M063

(Alias Part Numbers:

"3-1193886-3"

"RNF-100-2-BK-SP-CS5004")

5070094075

(Alias Part Numbers:

"8-1193966-5"

"RNF-100-3/4-CL-SP")

875675-000

(Alias Part Numbers:

"2-1196812-8"

"RNF-100-1-CL-SP-CS7535")

507006M070

(Alias Part Numbers:

"1193964-2"

"RNF-100-1/4-CL-SP-CS5823")

Product Affected

5053322031

(Alias Part Numbers:

"4-1193880-7"

"RNF-100-1-BU-STK")

5053184075

(Alias Part Numbers:

"1193861-2"

"RNF-100-3/8-WH-SP")

CL4287-000

(Alias Part Numbers:

"RNF-100-3/8-CL-STK-CS7250")

505349L026

(Alias Part Numbers:

"3-1193889-9"

"RNF-100-4-BK-STK-CS6162")

5070124025

(Alias Part Numbers:

"6-1193969-8"

"RNF-100-2-CL-SP")

980937-000

(Alias Part Numbers:

"1197580-6"

"RNF-100-3/4-YO-SP-CS7554")

5052912033

(Alias Part Numbers:

"2-1193825-4"

"RNF-100-1/16-YO-STK")

5070064069

(Alias Part Numbers:

"2-1193963-6"

"RNF-100-1/4-CL-SP")

505299L168

(Alias Part Numbers:

"7-1193834-7"

"RNF-100-1/8-BK-STK-CS7250")

505284L054

(Alias Part Numbers:

"1193822-5"

"RNF-100-3/64-BKSTK-CS6162")

602739-000

Product Affected

(Alias Part Numbers:

"9-1194770-3"

"RNF-100-2-BK-SP-CS7443")

289705-000

(Alias Part Numbers:

"5-1192196-4"

"RNF-100-1/2-YO-SP-CS7554")

C41441-000

(Alias Part Numbers:

"9-1201922-7"

"RNF-100-3/16-WH-SP-CS7807")

5053152042

(Alias Part Numbers:

"5-1193857-9"

"RNF-100-3/8-RD-STK")

5052884046

(Alias Part Numbers:

"RNF-100-3/64-WH-SP"

"1832037-1")

CU1870-000

507010L066

(Alias Part Numbers:

"5-1193968-7"

"RNF-100-1-CL-STK-CS6128")

131379-000

(Alias Part Numbers:

"1-1190955-6"

"RNF-100-4.5/1.9-CL-SP")

505304L157

(Alias Part Numbers:

"6-1193840-7"

"RNF-100-3/16-BKSTK-CS5529")

505308M104

(Alias Part Numbers:

"5-1193844-0"

"RNF-100-3/16-WH-SP-CS7075")

5053112154

(Alias Part Numbers:

"3-1193849-5"

"RNF-100-1/4-YO-STK")

Product Affected

5054024019

(Alias Part Numbers:

"7-1193892-7"

"RNF-100-3/32-BN-SP")

E36334-000

(Alias Part Numbers:

"2-1202162-8"

"RNF-100-2-BK-STK-CS7250")

5070104071

(Alias Part Numbers:

"9-1193967-0"

"RNF-100-1-CL-SP"

"RNF-100-1-X")

5070052056

(Alias Part Numbers:

"1-1193962-3"

"RNF-100-3/16-CL-STK")

C04348-000

(Alias Part Numbers:

"6-1201690-3"

"RNF-100-3/64-BK-STKCS7250")

5053942010

(Alias Part Numbers:

"7-1193891-5"

"RNF-100-3/64-BN-STK")

5054094026

(Alias Part Numbers:

"8-1193893-5"

"RNF-100-1/8-GY-SP")

5053372025

(Alias Part Numbers:

"9-1193884-7"

"RNF-100-1-1/2-BU-STK")

5054034020

(Alias Part Numbers:

"9-1193892-4"

"RNF-100-3/32-OR-SP")

033961-000

(Alias Part Numbers:

"1-1190263-0"

Product Affected

"RNF-100-1-CL-SP-CS7312")

5053082106

(Alias Part Numbers:

"8-1193843-5"

"RNF-100-3/16-WH-STK")

5053964008

(Alias Part Numbers:

"9-1193891-4"

"RNF-100-3/64-VT-SP")

590529-000

(Alias Part Numbers:

"5-1194671-2"

"RNF-100-1/2-RD-SP-CS7465")

035373-000

(Alias Part Numbers:

"4-1190273-3"

"RNF-100-1/8-RD-SP-CS7554")

5050964002

(Alias Part Numbers:

"9-1193817-4"

"RNF-100-NO.301-BK-SP")

5054082014

(Alias Part Numbers:

"6-1193893-6"

"RNF-100-1/8-VT-STK")

5054532024

(Alias Part Numbers:

"2-1193900-4"

"RNF-100-1/16-GN-STK")

5070132019

(Alias Part Numbers:

"1193970-8"

"RNF-100-3-CL-STK")

5050094015

(Alias Part Numbers:

"7-1193814-4"

"RNF-100-3/16-VT-SP")

5053412043

(Alias Part Numbers:

"6-1193886-9"

Product Affected

"RNF-100-2-YO-STK")

5054102023

(Alias Part Numbers:

"1193894-1"

"RNF-100-3/16-BN-STK")

5054032019

(Alias Part Numbers:

"9-1193892-1"

"RNF-100-3/32-OR-STK")

5054194017

(Alias Part Numbers:

"7-1193895-3"

"RNF-100-3/8-GY-SP")

971681-000

(Alias Part Numbers:

"8-1197510-7"

"RNF-100-1/2-WH-SP-CS7554")

5055182014

(Alias Part Numbers:

"6-1193901-6"

"RNF-100-3/64-GN-STK")

505424M023

(Alias Part Numbers:

"5-1193896-7"

"RNF-100-3/4-BN-SP-CS5321")

CN4288-000

(Alias Part Numbers:

"RNF-100-1/8-BK-STK-CS8794")

946138-000

(Alias Part Numbers:

"9-1199506-9"

"RNF-100-3/8-VT-SP-CS5004")

5053204041

(Alias Part Numbers:

"3-1193865-9"

"RNF-100-1/2-RD-SP"

"RNF-100-1/2-2"

"RNF-100-1/2-2")

505314L546

(Alias Part Numbers:

Product Affected

"9-1193854-8"

"RNF-100-3/8-BK-STKCS5004")

CN1085-000

5053234078

(Alias Part Numbers:

"1-1193868-4"

"RNF-100-1/2-WH-SP")

505289L146

(Alias Part Numbers:

"5-1193824-6"

"RNF-100-1/16-BKSTK-CS7224")

505316L197

(Alias Part Numbers:

"1-1193859-1"

"RNF-100-3/8-YO-STK-CS6162")

505298L204

(Alias Part Numbers:

"3-1193832-1"

"RNF-100-3/32-WH-STKCS7224")

5054314013

(Alias Part Numbers:

"5-1193897-4"

"RNF-100-1-1/2-BN-SP")

505314M378

(Alias Part Numbers:

"9-1193854-9"

"RNF-100-3/8-BK-SP-CS5074")

EM1153-000

5072012002

(Alias Part Numbers:

"9-1193971-7"

"RNF-100-1-1/4-CL-STK")

969515-000

(Alias Part Numbers:

"4-1197495-3"

"RNF-100-1-WH-FSP")

505323L075

(Alias Part Numbers:

"5-1193868-3"

"RNF-100-1/2-WH-STK-CS5529")

Product Affected

EJ1387-000

5053534026

(Alias Part Numbers:

"1193890-9"

"RNF-100-4-WH-SP")

CJ6363-000

(Alias Part Numbers:

"RNF-100-1-OR-FSP"

"4-1899833-9")

505313M118

(Alias Part Numbers:

"3-1193852-7"

"RNF-100-1/4-WH-SP-CS7375")

737004-000

(Alias Part Numbers:

"8-1197987-4"

"RNF-100-1-CL-FSP-CS7312")

194267-000

(Alias Part Numbers:

"5-1191409-8"

"RNF-100-1/8-WH-STK-CS5592")

5054064021

(Alias Part Numbers:

"4-1193893-0"

"RNF-100-1/8-BN-SP")

5070144011

(Alias Part Numbers:

"4-1193970-2"

"RNF-100-4-CL-SP")

5053134121

(Alias Part Numbers:

"7-1193851-1"

"RNF-100-1/4-WH-SP")

5053262136

(Alias Part Numbers:

"5-1193872-8"

"RNF-100-3/4-YO-STK")

5053324032

(Alias Part Numbers:

"5-1193880-1"

Product Affected

"RNF-100-1-BU-SP")

152573-000

(Alias Part Numbers:

"7-1191102-2"

"RNF-100-3/8-WH-SP-CS7554")

5054442026

(Alias Part Numbers:

"7-1193899-6"

"RNF-100-3/4-GN-STK")

5053192266

(Alias Part Numbers:

"1-1193862-2"

"RNF-100-1/2-BK-STK")

214347-000

(Alias Part Numbers:

"3-1191548-6"

"RNF-100-3/8-YO-SP-CS7554")

5053042176

(Alias Part Numbers:

"8-1193838-6"

"RNF-100-3/16-BK-STK")

505319L259

(Alias Part Numbers:

"9-1193863-1"

"RNF-100-1/2-BK-STK-CS7224")

5053274063

(Alias Part Numbers:

"4-1193874-2"

"RNF-100-3/4-BU-SP")

5053532025

(Alias Part Numbers:

"1193890-2"

"RNF-100-4-WH-STK")

5052892107

(Alias Part Numbers:

"5-1193823-3"

"RNF-100-1/16-BK-STK")

536285-000

(Alias Part Numbers:

"5-1197893-7"

Product Affected

"RNF-100-1/2-BK-SP-CS7387")

5053914036

(Alias Part Numbers:

"4-1193891-1"

"RNF-100-3/16-GN-SP")

107637-000

(Alias Part Numbers:

"7-1197918-1"

"RNF-100-1.3MM-CL-STK")

EK2003-000

062931-000

(Alias Part Numbers:

"8-1190475-7"

"RNF-100-3/4-RD-SP-CS5006")

505328M195

(Alias Part Numbers:

"5-1193875-4"

"RNF-100-3/4-WH-SP-CS5529")

5053022046

(Alias Part Numbers:

"8-1193836-1"

"RNF-100-1/8-BU-STK")

707357-000

(Alias Part Numbers:

"1-1195545-5"

"RNF-100-1/2-CL-STK-CS7312")

CS6422-000

152125-000

(Alias Part Numbers:

"5-1191099-6"

"RNF-100-1-CL-FSP")

5070082131

(Alias Part Numbers:

"2-1193965-3"

"RNF-100-1/2-CL-STK")

5053252050

(Alias Part Numbers:

"8-1193871-6"

"RNF-100-3/4-RD-STK")

CP2013-000

Product Affected

5070142010

(Alias Part Numbers:

"3-1193970-8"

"RNF-100-4-CL-STK")

5052852029

(Alias Part Numbers:

"1-1193822-4"

"RNF-100-3/64-RD-STK")

5053104060

(Alias Part Numbers:

"4-1193848-9"

"RNF-100-1/4-RD-SP"

"RNF-100-1/4-2")

5053124054

(Alias Part Numbers:

"8-1193850-2"

"RNF-100-1/4-BU-SP")

5054022018

(Alias Part Numbers:

"7-1193892-4"

"RNF-100-3/32-BN-STK")

CX2365-000

(Alias Part Numbers:

"RNF-100-1/4-WH-SP-CS7674"

"4-1899832-0")

505328L194

(Alias Part Numbers:

"5-1193875-3"

"RNF-100-3/4-WH-STK-CS5006")

5053164200

(Alias Part Numbers:

"4-1193858-7"

"RNF-100-3/8-YO-SP")

EM6957-000

5053002039

(Alias Part Numbers:

"1193835-9"

"RNF-100-1/8-RD-STK")

5053482021

(Alias Part Numbers:

Product Affected

"7-1193888-8"

"RNF-100-3-WH-STK")

505323L152

(Alias Part Numbers:

"5-1193868-4"

"RNF-100-1/2-WH-STK-CS5004")

5053272062

(Alias Part Numbers:

"3-1193874-4"

"RNF-100-3/4-BU-STK")

5052932105

(Alias Part Numbers:

"1-1193826-7"

"RNF-100-1/16-WH-STK")

507005M059

(Alias Part Numbers:

"1193963-1"

"RNF-100-3/16-CL-SP-CS5006")

5053172050

(Alias Part Numbers:

"1-1193860-9"

"RNF-100-3/8-BU-STK")

505329L157

(Alias Part Numbers:

"5-1193877-5"

"RNF-100-1-BK-STK-CS5529")

5053484022

(Alias Part Numbers:

"8-1193888-2"

"RNF-100-3-WH-SP")

5052924038

(Alias Part Numbers:

"7-1193825-7"

"RNF-100-1/16-BU-SP")

5070102070

(Alias Part Numbers:

"7-1193967-7"

"RNF-100-1-CL-STK")

5052974051

(Alias Part Numbers:

Product Affected

"1193831-9"

"RNF-100-3/32-BU-SP")

CP2329-000

5053464025

(Alias Part Numbers:

"3-1193888-8"

"RNF-100-3-YO-SP")

5053154043

(Alias Part Numbers:

"6-1193857-7"

"RNF-100-3/8-RD-SP")

EG0542-000

(Alias Part Numbers:

"RNF-100-3/64-GY-STK")

505443M027

(Alias Part Numbers:

"6-1193899-9"

"RNF-100-3/8-GN-SP-CS5321")

505323M076

(Alias Part Numbers:

"5-1193868-5"

"RNF-100-1/2-WH-SP-CS5529")

505331L136

(Alias Part Numbers:

"1-1193879-3"

"RNF-100-1-YO-STK-CS5529")

505293L102

(Alias Part Numbers:

"7-1193826-0"

"RNF-100-1/16-WH-STKCS5529")

5054412028

(Alias Part Numbers:

"4-1193898-4"

"RNF-100-1/4-GN-STK")

442923-000

(Alias Part Numbers:

"4-1193329-9"

"RNF-100-1/4-RD-SP-CS7554")

5070134020

(Alias Part Numbers:

Product Affected

"1-1193970-3"

"RNF-100-3-CL-SP")

507007M082

(Alias Part Numbers:

"1193965-9"

"RNF-100-3/8-CL-SP-CS5868")

505442M022

(Alias Part Numbers:

"2-1193899-0"

"RNF-100-1/8-GN-SP-CS5006")

187446-000

(Alias Part Numbers:

"6-1199162-1"

"RNF-100-3/8-WH-FSP-CS5004")

507003L069

(Alias Part Numbers:

"8-1193960-3"

"RNF-100-3/32-CL-STKCS5733")

5053012086

(Alias Part Numbers:

"7-1193835-3"

"RNF-100-1/8-YO-STK")

5054002025

(Alias Part Numbers:

"4-1193892-0"

"RNF-100-1/16-VT-STK")

5070024041

(Alias Part Numbers:

"3-1193959-4"

"RNF-100-1/16-CL-SP")

5054112017

(Alias Part Numbers:

"2-1193894-0"

"RNF-100-3/16-OR-STK")

EK2384-000

CN7633-000

(Alias Part Numbers:

"RNF-100-3/16-GN-SP-CS5004")

5053414044

(Alias Part Numbers:

Product Affected

"7-1193886-2"

"RNF-100-2-YO-SP")

505344L068

(Alias Part Numbers:

"1193888-3"

"RNF-100-3-BK-STKCS5004")

EK0733-000

5053242179

(Alias Part Numbers:

"1-1193869-9"

"RNF-100-3/4-BK-STK")

505314J376

(Alias Part Numbers:

"9-1193854-6"

"RNF-100-3/8-BK-SP-SM")

5054552026

(Alias Part Numbers:

"5-1193900-3"

"RNF-100-1/2-GN-STK")

5054444027

(Alias Part Numbers:

"8-1193899-1"

"RNF-100-3/4-GN-SP")

5050034021

(Alias Part Numbers:

"3-1193814-8"

"RNF-100-1/4-GY-SP")

507012L052

(Alias Part Numbers:

"9-1193969-7"

"RNF-100-2-CL-STK-CS7312")

505441M037

(Alias Part Numbers:

"8-1193898-0"

"RNF-100-1/4-GN-SP-CS5006")

E93634-000

(Alias Part Numbers:

"1-1200701-5"

"RNF-100-1/8-BK-STK-CS5592")

5053352027

Product Affected

(Alias Part Numbers:

"6-1193883-8"

"RNF-100-1-1/2-RD-STK")

060537-000

(Alias Part Numbers:

"8-1190458-7"

"RNF-100-3/4-BU-FSP")

5053282198

(Alias Part Numbers:

"1193875-3"

"RNF-100-3/4-WH-STK")

908548-000

(Alias Part Numbers:

"1197875-3"

"RNF-100-1/4-BN-STK")

505322M055

(Alias Part Numbers:

"8-1193867-9"

"RNF-100-1/2-BU-SP-CS5529")

5053514018

(Alias Part Numbers:

"7-1193889-0"

"RNF-100-4-YO-SP")

F26945-000

(Alias Part Numbers:

"1-1201492-8"

"RNF-100-1/2-WH-SP-CS5004")

5054052018

(Alias Part Numbers:

"2-1193893-2"

"RNF-100-3/32-GY-STK")

EM1152-000

5070114069

(Alias Part Numbers:

"8-1193968-0"

"RNF-100-1-1/2-CL-SP")

505334J097

(Alias Part Numbers:

"3-1193883-3"

"RNF-100-1-1/2-BK-SP-SM")

Product Affected

505318M076

(Alias Part Numbers:

"5-1193861-2"

"RNF-100-3/8-WH-SP-CS5321")

5053122053

(Alias Part Numbers:

"7-1193850-3"

"RNF-100-1/4-BU-STK")

769283-000

(Alias Part Numbers:

"4-1195994-9"

"RNF-100-3/8-WH-FSP")

5070032071

(Alias Part Numbers:

"1193960-3"

"RNF-100-3/32-CL-STK")

597155-000

(Alias Part Numbers:

"5-1194722-5"

"RNF-100-3/4-WH-STK-CS5004")

548283-000

(Alias Part Numbers:

"6-1194315-6"

"RNF-100-1/8-WH-SP-CS5004")

505320L078

(Alias Part Numbers:

"7-1193865-1"

"RNF-100-1/2-RD-STK-CS5318")

5053142385

(Alias Part Numbers:

"2-1193853-6"

"RNF-100-3/8-BK-STK")

505298M148

(Alias Part Numbers:

"3-1193832-2"

"RNF-100-3/32-WH-SP-CS7375")

CN8371-000

(Alias Part Numbers:

"RNF-100-3/8-WH-SP-CS5004")

411221-000

Product Affected

(Alias Part Numbers:

"3-1193101-5"

"RNF-100-1/2-CL-FSP")

5054574018

(Alias Part Numbers:

"9-1193900-0"

"RNF-100-1-GN-SP")

5054582015

(Alias Part Numbers:

"1-1193901-6"

"RNF-100-1-1/2-GN-STK")

003347-000

(Alias Part Numbers:

"3-1190025-7"

"RNF-100-3/8-YO-FSP")

505318L160

(Alias Part Numbers:

"5-1193861-0"

"RNF-100-3/8-WH-STKCS5004")

507013L017

(Alias Part Numbers:

"2-1193970-9"

"RNF-100-3-CL-STK-CS7250")

505344M031

(Alias Part Numbers:

"1193888-4"

"RNF-100-3-BK-SP-CS5529")

108587-000

(Alias Part Numbers:

"2-1190793-2"

"RNF-100-3/8-BU-SP-CS7554")

5053944011

(Alias Part Numbers:

"7-1193891-6"

"RNF-100-3/64-BN-SP")

507008M136

(Alias Part Numbers:

"2-1193966-9"

"RNF-100-1/2-CL-SP-CS6162")

5053472022

Product Affected

(Alias Part Numbers:

"5-1193888-8"

"RNF-100-3-BU-STK")

5053014087

(Alias Part Numbers:

"8-1193835-1"

"RNF-100-1/8-YO-SP"

"RNF-100-1/8-4")

5053384055

(Alias Part Numbers:

"3-1193885-3"

"RNF-100-1-1/2-WH-SP")

5054142012

(Alias Part Numbers:

"7-1193894-5"

"RNF-100-1/4-OR-STK")

145659-000

(Alias Part Numbers:

"4-1191052-0"

"RNF-100-3/16-YO-SP-CS7554")

5054062020

(Alias Part Numbers:

"3-1193893-6"

"RNF-100-1/8-BN-STK")

5052914034

(Alias Part Numbers:

"3-1193825-0"

"RNF-100-1/16-YO-SP")

EM1154-000

CM1138-000

(Alias Part Numbers:

"RNF-100-1/4-RD-SP-CS7387")

5053244180

(Alias Part Numbers:

"4-1193869-0"

"RNF-100-3/4-BK-SP"

"RNF-100-3/4-0SP")

5052964055

(Alias Part Numbers:

"7-1193829-3"

Product Affected

"RNF-100-3/32-YO-SP")

5053084107

(Alias Part Numbers:

"9-1193843-5"

"RNF-100-3/16-WH-SP")

505349L050

(Alias Part Numbers:

"4-1193889-0"

"RNF-100-4-BK-STKCS5004")

5050092016

(Alias Part Numbers:

"7-1193814-0"

"RNF-100-3/16-VT-STK")

507007L078

(Alias Part Numbers:

"1193965-7"

"RNF-100-3/8-CL-STK-CS5006")

CU1245-000

CP1255-000

5054044014

(Alias Part Numbers:

"1-1193893-3"

"RNF-100-3/32-VT-SP")

505324L175

(Alias Part Numbers:

"7-1193870-3"

"RNF-100-3/4-BK-STK-CS5529")

5053024047

(Alias Part Numbers:

"8-1193836-7"

"RNF-100-1/8-BU-SP"

"RNF-100-1/8-6")

507004L079

(Alias Part Numbers:

"9-1193961-1"

"RNF-100-1/8-CL-STK-CS6162")

505288L042

(Alias Part Numbers:

"4-1193823-0"

"RNF-100-3/64-WH-STKCS7156")

Product Affected

5054014021

(Alias Part Numbers:

"6-1193892-4"

"RNF-100-1/16-GY-SP")

5052962054

(Alias Part Numbers:

"6-1193829-8"

"RNF-100-3/32-YO-STK")

5054154016

(Alias Part Numbers:

"9-1193894-8"

"RNF-100-1/4-VT-SP")

5058632005

(Alias Part Numbers:

"2-1193905-7"

"RNF-100-1-1/4-RD-STK")

C32783-000

(Alias Part Numbers:

"8-1202034-4"

"RNF-100-1/4-GY-SP-CS5004")

5070014034

(Alias Part Numbers:

"RNF-100-3/64-CL-SP"

"1642707-1")

5053072046

(Alias Part Numbers:

"1-1193843-7"

"RNF-100-3/16-BU-STK")

505293M103

(Alias Part Numbers:

"7-1193826-1"

"RNF-100-1/16-WH-SP-CS7375")

C16906-000

(Alias Part Numbers:

"8-1202034-3"

"RNF-100-3/8-BK-STK-CS7387")

5052922037

(Alias Part Numbers:

"6-1193825-8"

"RNF-100-1/16-BU-STK")

Product Affected

595885-000

(Alias Part Numbers:

"1194712-2"

"RNF-100-1/4-CL-STK-CS7312")

5050814014

(Alias Part Numbers:

"6-1193817-1"

"RNF-100-2-GN-SP")

302739-000

(Alias Part Numbers:

"3-1192293-5"

"RNF-100-1/2-GY-SP")

5052902037

(Alias Part Numbers:

"7-1193824-4"

"RNF-100-1/16-RD-STK")

CM3484-000

(Alias Part Numbers:

"RNF-100-3/16-RD-SP-CS5533")

9053854002

(Alias Part Numbers:

"2-1197035-2"

"RNF-100-NO.301-CL-SP")

289569-000

(Alias Part Numbers:

"6-1192195-1"

"RNF-100-1/8-GN-SP-CS7554")

5052954041

(Alias Part Numbers:

"1-1193829-8"

"RNF-100-3/32-RD-SP")

C92102-000

(Alias Part Numbers:

"4-1201282-8"

"RNF-100-1/2-CL-FSPCS7312")

CM1137-000

(Alias Part Numbers:

"RNF-100-1/4-YO-SP-CS7387")

804093-000

(Alias Part Numbers:

Product Affected

"1197882-8"

"RNF-100-3/32-BU-SP-CS5004")

5053462024

(Alias Part Numbers:

"3-1193888-2"

"RNF-100-3-YO-STK")

5052942218

(Alias Part Numbers:

"1-1193827-7"

"RNF-100-3/32-BK-STK")

292801-000

(Alias Part Numbers:

"5-1192219-1"

"RNF-100-1-BK-FSP")

5053132120

(Alias Part Numbers:

"5-1193851-9"

"RNF-100-1/4-WH-STK")

5053182074

(Alias Part Numbers:

"9-1193860-3"

"RNF-100-3/8-WH-STK")

5053222056

(Alias Part Numbers:

"4-1193867-3"

"RNF-100-1/2-BU-STK")

5053312138

(Alias Part Numbers:

"5-1193878-8"

"RNF-100-1-YO-STK")

5053144386

(Alias Part Numbers:

"4-1193853-5"

"RNF-100-3/8-BK-SP"

"RNF-100-3/8-0")

5072014003

(Alias Part Numbers:

"1193972-1"

"RNF-100-1-1/4-CL-SP")

505338M052

Product Affected

(Alias Part Numbers:

"5-1193885-9"

"RNF-100-1-1/2-WH-SPCS5529")

EK0731-000

264250-000

(Alias Part Numbers:

"4-1197910-9"

"RNF-100-1/4-GY-STK")

494900-000

(Alias Part Numbers:

"2-1198914-3"

"RNF-100-1/16-BN-SP-CS5004")

505319J257

(Alias Part Numbers:

"8-1193863-8"

"RNF-100-1/2-BK-SP-SM")

140621-000

(Alias Part Numbers:

"5-1191019-6"

"RNF-100-3/64-WH-SP-CS5551")

5053362070

(Alias Part Numbers:

"1193884-8"

"RNF-100-1-1/2-YO-STK")

5054424024

(Alias Part Numbers:

"9-1193898-4"

"RNF-100-1/8-GN-SP")

507009M078

(Alias Part Numbers:

"6-1193967-4"

"RNF-100-3/4-CL-SP-CS7312")

505324M353

(Alias Part Numbers:

"7-1193870-6"

"RNF-100-3/4-BK-SP-CS5004")

505313M225

(Alias Part Numbers:

"3-1193852-9"

"RNF-100-1/4-WH-SP-CS7465")

Product Affected

5054554027

(Alias Part Numbers:

"5-1193900-5"

"RNF-100-1/2-GN-SP")

5054224013

(Alias Part Numbers:

"2-1193896-1"

"RNF-100-1/2-VT-SP")

5053452021

(Alias Part Numbers:

"1-1193888-4"

"RNF-100-3-RD-STK")

5054072011

(Alias Part Numbers:

"5-1193893-5"

"RNF-100-1/8-OR-STK")

289987-000

(Alias Part Numbers:

"6-1192198-2"

"RNF-100-1/4-BK-STK-CS5004")

904565-000

(Alias Part Numbers:

"5-1197029-2"

"RNF-100-3/4-WH-SP-CS7554")

5053912035

(Alias Part Numbers:

"3-1193891-5"

"RNF-100-3/16-GN-STK")

5053264137

(Alias Part Numbers:

"6-1193872-5"

"RNF-100-3/4-YO-SP")

5053404021

(Alias Part Numbers:

"4-1193886-9"

"RNF-100-2-RD-SP")

5053474023

(Alias Part Numbers:

"6-1193888-2"

"RNF-100-3-BU-SP")

Product Affected

5053194267

(Alias Part Numbers:

"3-1193862-4"

"RNF-100-1/2-BK-SP"

"RNF-100-1/2-0")

5053342101

(Alias Part Numbers:

"2-1193882-6"

"RNF-100-1-1/2-BK-STK")

5070092074

(Alias Part Numbers:

"7-1193966-2"

"RNF-100-3/4-CL-STK")

5054054019

(Alias Part Numbers:

"2-1193893-5"

"RNF-100-3/32-GY-SP")

934187-000

(Alias Part Numbers:

"1-1197239-4"

"RNF-100-1/2-GN-FSP")

774257-000

(Alias Part Numbers:

"5-1196029-3"

"RNF-100-3/8-GN-FSP")

C13257-000

(Alias Part Numbers:

"1-1201299-0"

"RNF-100-3/32-OR-SPCS5004")

042463-000

(Alias Part Numbers:

"6-1190325-3"

"RNF-100-3/16-CL-SP-CS7312")

507006L064

(Alias Part Numbers:

"9-1193963-9"

"RNF-100-1/4-CL-STK-CS6162")

5053114155

(Alias Part Numbers:

"4-1193849-3"

Product Affected

"RNF-100-1/4-YO-SP"

"RNF-100-1/4-4")

900337-000

(Alias Part Numbers:

"4-1196998-8"

"RNF-100-3/4-WH-FSP")

105309-000

(Alias Part Numbers:

"8-1190769-5"

"RNF-100-2-BK-SP-CS7465")

5054164023

(Alias Part Numbers:

"1-1193895-4"

"RNF-100-3/8-BN-SP")

505305M036

(Alias Part Numbers:

"7-1193841-3"

"RNF-100-3/16-RD-SP-CS6162")

C30357-000

(Alias Part Numbers:

"7-1199656-0"

"RNF-100-1/2-BK-FSP-CS5004")

5054282008

(Alias Part Numbers:

"1-1193897-8"

"RNF-100-1-OR-STK")

969117-000

(Alias Part Numbers:

"5-1197492-9"

"RNF-100-1/16-WH-STKCS5551")

505319L439

(Alias Part Numbers:

"9-1193863-2"

"RNF-100-1/2-BK-STKCS5004")

5052872029

(Alias Part Numbers:

"7-1193822-5"

"RNF-100-3/64-BU-STK")

142003-000

(Alias Part Numbers:

Product Affected

"1-1191029-3"

"RNF-100-3/4-BK-FSP")

5053614015

(Alias Part Numbers:

"5-1193890-8"

"RNF-100-3-GN-SP")

C28473-000

(Alias Part Numbers:

"1-1201734-9"

"RNF-100-1/4-CL-SP-CS7312")

5070022040

(Alias Part Numbers:

"2-1193959-4"

"RNF-100-1/16-CL-STK")

5052984151

(Alias Part Numbers:

"6-1193831-9"

"RNF-100-3/32-WH-SP")

155907-000

(Alias Part Numbers:

"3-1191126-7"

"RNF-100-3/32-CL-SP-CS7607")

5054114018

(Alias Part Numbers:

"2-1193894-4"

"RNF-100-3/16-OR-SP")

504570-000

(Alias Part Numbers:

"2-1199022-5"

"RNF-100-3/32-YO-SP-CS5004")

7655194002

(Alias Part Numbers:

"4-1195959-0"

"RNF-100-NO.322-BK-SP")

5053982024

(Alias Part Numbers:

"1-1193892-1"

"RNF-100-1/16-BN-STK")

5052952040

(Alias Part Numbers:

Product Affected

"1-1193829-1"

"RNF-100-3/32-RD-STK")

408941-000

(Alias Part Numbers:

"5-1193084-6"

"RNF-100-3/8-RD-FSP")

394029-000

(Alias Part Numbers:

"9-1192955-9"

"RNF-100-3/8-CL-SP-CS7312")

5056842009

(Alias Part Numbers:

"9-1193902-2"

"RNF-100-1-1/4-BK-STK")

5053524020

(Alias Part Numbers:

"8-1193889-8"

"RNF-100-4-BU-SP")

5053292160

(Alias Part Numbers:

"3-1193876-7"

"RNF-100-1-BK-STK")

5054324010

(Alias Part Numbers:

"6-1193897-5"

"RNF-100-1-1/2-OR-SP")

EK0732-000

CN7632-000

(Alias Part Numbers:

"RNF-100-3/16-BU-SP-CS5004")

CU0518-000

(Alias Part Numbers:

"RNF-100-1.3MM-CL-SP")

5053432036

(Alias Part Numbers:

"2-1193887-4"

"RNF-100-2-WH-STK")

5053454024

(Alias Part Numbers:

"1-1193888-8"

Product Affected

"RNF-100-3-RD-SP")

533409-000

(Alias Part Numbers:

"5-1194187-7"

"RNF-100-3/8-BU-FSP")

073906-000

(Alias Part Numbers:

"9-1199125-2"

"RNF-100-1.1MM-CL-STK")

E20260-000

(Alias Part Numbers:

"3-1202073-9"

"RNF-100-1/4-VT-SP-CS5004")

EG5869-000

4114612001

(Alias Part Numbers:

"1-1193103-6"

"RNF-100-NO.333-CL-STK")

EM1281-000

999221-000

(Alias Part Numbers:

"3-1197725-2"

"RNF-100-1/4-GN-SP-CS7387")

5054004026

(Alias Part Numbers:

"4-1193892-4"

"RNF-100-1/16-VT-SP")

507008L128

(Alias Part Numbers:

"2-1193966-6"

"RNF-100-1/2-CL-STK-CS6162")

CX5930-000

505306M080

(Alias Part Numbers:

"6-1193842-4"

"RNF-100-3/16-YO-SP-CS6162")

5070062068

(Alias Part Numbers:

"1-1193963-3"

"RNF-100-1/4-CL-STK"

Product Affected

"RNF-100-1/4-CL-STK")

CN7634-000

(Alias Part Numbers:

"RNF-100-3/16-RD-SP-CS5004")

5053494030

(Alias Part Numbers:

"1-1193889-6"

"RNF-100-4-BK-SP")

479606-000

(Alias Part Numbers:

"2-1199141-1"

"RNF-100-3/16-BK-STKCS7224")

314363-000

(Alias Part Numbers:

"5-1192379-2"

"RNF-100-1/2-BU-FSP")

F68207-000

(Alias Part Numbers:

"5-1201301-0"

"RNF-100-1-BK-SP-CS5004")

505349M027

(Alias Part Numbers:

"4-1193889-2"

"RNF-100-4-BK-SP-CS5529")

F44472-000

(Alias Part Numbers:

"9-1201717-0"

"RNF-100-1-CL-STK-CS7620")

280249-000

(Alias Part Numbers:

"2-1192074-3"

"RNF-100-1/4-WH-SP-CS7554")

5053054039

(Alias Part Numbers:

"3-1193841-7"

"RNF-100-3/16-RD-SP")

5053202040

(Alias Part Numbers:

"3-1193865-0"

"RNF-100-1/2-RD-STK")

Product Affected

832204-000

(Alias Part Numbers:

"6-1199983-5"

"RNF-100-3/4R-BK-STK")

911779-000

(Alias Part Numbers:

"2-1197081-1"

"RNF-100-3/8-CL-FSP")

D95475-000

(Alias Part Numbers:

"1-1201793-1"

"RNF-100-092/078-CL-SP")

5053092267

(Alias Part Numbers:

"2-1193845-2"

"RNF-100-1/4-BK-STK")

505326L134

(Alias Part Numbers:

"3-1193873-3"

"RNF-100-3/4-YO-STK-CS5529")

CR1834-000

051417-000

(Alias Part Numbers:

"8-1190393-4"

"RNF-100-3/4-GN-FSP")

5070122027

(Alias Part Numbers:

"5-1193969-9"

"RNF-100-2-CL-STK")

452338-000

(Alias Part Numbers:

"7-1198934-2"

"RNF-100-3/32-VT-SP-CS5004")

5053294161

(Alias Part Numbers:

"5-1193876-3"

"RNF-100-1-BK-SP")

798993-000

(Alias Part Numbers:

"4-1197862-6"

Product Affected

"RNF-100-3/8-WH-STK-CS5551")

332803-000

(Alias Part Numbers:

"9-1197857-0"

"RNF-100-1.5MM-CL-STK")

5057394003

(Alias Part Numbers:

"1193904-3"

"RNF-100-1-1/4-WH-SP")

CL6871-000

(Alias Part Numbers:

"RNF-100-135/149-BK-SP-CS8779")

5053512017

(Alias Part Numbers:

"6-1193889-7"

"RNF-100-4-YO-STK")

330665-000

(Alias Part Numbers:

"3-1192498-1"

"RNF-100-NO.338-CL-STK")

5054134024

(Alias Part Numbers:

"5-1193894-6"

"RNF-100-1/4-BN-SP")

071275-000

(Alias Part Numbers:

"3-1190535-5"

"RNF-100-1/2-BK-FSP")

643267-000

(Alias Part Numbers:

"6-1195082-8"

"RNF-100-1/2-WH-FSP")

505310M057

(Alias Part Numbers:

"1193849-5"

"RNF-100-1/4-RD-SP-CS5529")

505319M260

(Alias Part Numbers:

"9-1193863-3"

"RNF-100-1/2-BK-SP-CS6162")

Product Affected

505321L152

(Alias Part Numbers:

"6-1193866-6"

"RNF-100-1/2-YO-STK-CS6162")

446253-000

(Alias Part Numbers:

"1-1193354-2"

"RNF-100-3/4-CL-FSP")

5054334012

(Alias Part Numbers:

"7-1193897-4"

"RNF-100-1-1/2-VT-SP")

525326-000

(Alias Part Numbers:

"9-1198114-7"

"RNF-100-1/4-RD-STK-CS7675")

505313L117

(Alias Part Numbers:

"3-1193852-6"

"RNF-100-1/4-WH-STK-CS5529")

505391M034

(Alias Part Numbers:

"6-1193891-4"

"RNF-100-3/16-GN-SP-CS5321")

E95708-000

(Alias Part Numbers:

"8-1199962-6"

"RNF-100-3/8-BK-STK-CS7728")

542451-000

(Alias Part Numbers:

"1-1194253-4"

"RNF-100-1-1/2-WHSTKCS5004")

507002L038

(Alias Part Numbers:

"9-1193959-0"

"RNF-100-1/16-CL-STKCS6128")

5054184014

(Alias Part Numbers:

"5-1193895-2"

"RNF-100-3/8-VT-SP")

Product Affected

505344L030

(Alias Part Numbers:

"1193888-2"

"RNF-100-3-BK-STK-CS7224")

507002M045

(Alias Part Numbers:

"9-1193959-2"

"RNF-100-1/16-CL-SP-CS5868")

5054252011

(Alias Part Numbers:

"6-1193896-6"

"RNF-100-3/4-OR-STK")

507009L073

(Alias Part Numbers:

"6-1193967-1"

"RNF-100-3/4-CL-STK-CS6162")

F40630-000

(Alias Part Numbers:

"5-1200482-7"

"RNF-100-1/2-WH-FSP-CS5004")

CN3422-000

5054042013

(Alias Part Numbers:

"1193893-9"

"RNF-100-3/32-VT-STK")

5050812013

(Alias Part Numbers:

"5-1193817-8"

"RNF-100-2-GN-STK")

643616-000

(Alias Part Numbers:

"3-1198935-1"

"RNF-100-3/32-BN-SP-CS5004")

329073-000

(Alias Part Numbers:

"2-1192488-2"

"RNF-100-3/8-RD-SP-CS7554")

CR8361-000

(Alias Part Numbers:

"5-1899816-9")

Product Affected

104168-000

(Alias Part Numbers:

"5-1197918-1"

"RNF-100-1/4-VT-STK")

539127N001

(Alias Part Numbers:

"6-1194230-8"

"RNF-100-1/16-BKSTK-CS5318")

5053422019

(Alias Part Numbers:

"1193887-1"

"RNF-100-2-BU-STK")

654193-000

(Alias Part Numbers:

"6-1195161-8"

"RNF-100-1-RD-FSP")

5052934106

(Alias Part Numbers:

"2-1193826-7"

"RNF-100-1/16-WH-SP")

5052934161

(Alias Part Numbers:

"3-1193826-3"

"RNF-100-1/16-WH-SP-CS5004")

5053994016

(Alias Part Numbers:

"3-1193892-1"

"RNF-100-1/16-OR-SP")

505329M158

(Alias Part Numbers:

"5-1193877-7"

"RNF-100-1-BK-SP-CS5529")

5070084132

(Alias Part Numbers:

"3-1193965-6"

"RNF-100-1/2-CL-SP"

"RNF-100-1/2-X")

EG9112-000

955297-000

(Alias Part Numbers:

Product Affected

"9-1197395-7"

"RNF-100-3/16-WH-SP-CS7554")

186504-000

(Alias Part Numbers:

"4-1199983-7"

"RNF-100-1/2R-BK-STK")

5070034072

(Alias Part Numbers:

"1-1193960-3"

"RNF-100-3/32-CL-SP")

505324J174

(Alias Part Numbers:

"7-1193870-2"

"RNF-100-3/4-BK-SP-SM")

914696-000

(Alias Part Numbers:

"4-1198914-2"

"RNF-100-1-WH-SP-CS5004")

EM1156-000

CL0554-000

(Alias Part Numbers:

"RNF-100-3/32-CL-SP-CS8764")

691461-000

(Alias Part Numbers:

"1195429-3"

"RNF-100-1/2-WH-STK-CS5551")

505329L252

(Alias Part Numbers:

"5-1193877-6"

"RNF-100-1-BK-STKCS5004")

5053004040

(Alias Part Numbers:

"1-1193835-6"

"RNF-100-1/8-RD-SP")

CS6003-000

(Alias Part Numbers:

"RNF-100-0.543-BK-SP"

"1899833-1")

5058604001

(Alias Part Numbers:

Product Affected

"2-1193905-3"

"RNF-100-1-1/4-BU-SP")

5054272012

(Alias Part Numbers:

"1193897-2"

"RNF-100-1-BN-STK")

5053434037

(Alias Part Numbers:

"3-1193887-0"

"RNF-100-2-WH-SP")

CZ7155-000

505300M037

(Alias Part Numbers:

"5-1193835-9"

"RNF-100-1/8-RD-SP-CS5529")

505333M212

(Alias Part Numbers:

"5-1193881-1"

"RNF-100-1-WH-SP-CS7465")

F11826-000

(Alias Part Numbers:

"3-1200396-6"

"RNF-100-3/8-BK-FSP-CS7743")

F36947-000

(Alias Part Numbers:

"5-1201769-9"

"RNF-100-3/64-WH-STKCS5321")

5070012033

(Alias Part Numbers:

"7-1193958-3"

"RNF-100-3/64-CL-STK")

967171-000

(Alias Part Numbers:

"6-1197478-0"

"RNF-100-1/2-CL-STK-CS7620")

505315M040

(Alias Part Numbers:

"2-1193858-4"

"RNF-100-3/8-RD-SP-CS5533")

505314L377

Product Affected

(Alias Part Numbers:

"9-1193854-7"

"RNF-100-3/8-BK-STK-CS7224")

5053444034

(Alias Part Numbers:

"6-1193887-4"

"RNF-100-3-BK-SP")

590417-000

(Alias Part Numbers:

"7-1194670-1"

"RNF-100-1-1/4-WH-SPCS7312")

5053392064

(Alias Part Numbers:

"7-1193885-6"

"RNF-100-2-BK-STK")

5058634006

(Alias Part Numbers:

"2-1193905-9"

"RNF-100-1-1/4-RD-SP")

D71856-000

(Alias Part Numbers:

"3-1201923-8"

"RNF-100-1/8-WH-SP-CS7807")

5053214155

(Alias Part Numbers:

"9-1193865-5"

"RNF-100-1/2-YO-SP")

5053254051

(Alias Part Numbers:

"9-1193871-3"

"RNF-100-3/4-RD-SP")

651721-000

(Alias Part Numbers:

"3-1195145-8"

"RNF-100-3/4-RD-FSP")

5054104024

(Alias Part Numbers:

"1193894-6"

"RNF-100-3/16-BN-SP")

CX0799-000

Product Affected

(Alias Part Numbers:

"RNF-100-1-CL-FSP-CS5868"

"7-1899832-2")

5052842057

(Alias Part Numbers:

"3-1193821-9"

"RNF-100-3/64-BK-STK")

CL4285-000

(Alias Part Numbers:

"RNF-100-3/32-BK-STK-CS5529")

5053332136

(Alias Part Numbers:

"9-1193880-0"

"RNF-100-1-WH-STK")

5050154002

(Alias Part Numbers:

"1193815-7"

"RNF-100-NO.302-BK-SP")

505324M176

(Alias Part Numbers:

"7-1193870-4"

"RNF-100-3/4-BK-SP-CS5074")

5052982150

(Alias Part Numbers:

"6-1193831-0"

"RNF-100-3/32-WH-STK")

5053102059

(Alias Part Numbers:

"4-1193848-0"

"RNF-100-1/4-RD-STK")

507009L137

(Alias Part Numbers:

"6-1193967-2"

"RNF-100-3/4-CL-STKCS7250")

5052854030

(Alias Part Numbers:

"1-1193822-8"

"RNF-100-3/64-RD-SP")

139431-000

(Alias Part Numbers:

Product Affected

"1-1191011-7"

"RNF-100-3/4-BK-STK-CS5004")

5053612014

(Alias Part Numbers:

"5-1193890-6"

"RNF-100-3-GN-STK")

5056844010

(Alias Part Numbers:

"9-1193902-5"

"RNF-100-1-1/4-BK-SP")

5053984025

(Alias Part Numbers:

"1-1193892-5"

"RNF-100-1/16-BN-SP")

5053074047

(Alias Part Numbers:

"2-1193843-9"

"RNF-100-3/16-BU-SP")

5053284199

(Alias Part Numbers:

"1-1193875-4"

"RNF-100-3/4-WH-SP")

5053374026

(Alias Part Numbers:

"1193885-2"

"RNF-100-1-1/2-BU-SP")

D67400-000

(Alias Part Numbers:

"2-1200813-2"

"RNF-100-4.5/1.9-CL-STK")

5053344102

(Alias Part Numbers:

"4-1193882-5"

"RNF-100-1-1/2-BK-SP")

467625-000

(Alias Part Numbers:

"1193505-8"

"RNF-100-1-YO-FSP")

339581-000

(Alias Part Numbers:

Product Affected

"8-1192562-6"

"RNF-100-3/8-BK-SP-CS7227")

507012M030

(Alias Part Numbers:

"9-1193969-8"

"RNF-100-2-CL-SP-CS7312")

5053424020

(Alias Part Numbers:

"1193887-4"

"RNF-100-2-BU-SP")

505332M029

(Alias Part Numbers:

"8-1193880-0"

"RNF-100-1-BU-SP-CS5529")

505343L033

(Alias Part Numbers:

"4-1193887-7"

"RNF-100-2-WH-STK-CS5529")

A09061-000

(Alias Part Numbers:

"1-1201492-1"

"RNF-100-4-BK-STK-CS5592")

507011L073

(Alias Part Numbers:

"4-1193969-3"

"RNF-100-1-1/2CLSTK-CS7250")

5053232077

(Alias Part Numbers:

"1193868-6"

"RNF-100-1/2-WH-STK")

5053064084

(Alias Part Numbers:

"9-1193841-6"

"RNF-100-3/16-YO-SP")

5053162199

(Alias Part Numbers:

"4-1193858-1"

"RNF-100-3/8-YO-STK")

5053354028

(Alias Part Numbers:

Product Affected

"7-1193883-2"

"RNF-100-1-1/2-RD-SP")

EM1155-000

391163-000

(Alias Part Numbers:

"3-1192936-2"

"RNF-100-NO.337-CL-STK")

559029-000

(Alias Part Numbers:

"1-1194413-1"

"RNF-100-1/2-RD-FSP")

CP9849-000

5054212011

(Alias Part Numbers:

"1193896-3"

"RNF-100-1/2-OR-STK")

5053212154

(Alias Part Numbers:

"8-1193865-9"

"RNF-100-1/2-YO-STK")

5053224057

(Alias Part Numbers:

"5-1193867-1"

"RNF-100-1/2-BU-SP")

5070072080

(Alias Part Numbers:

"1-1193964-8"

"RNF-100-3/8-CL-STK"

"RNF-100-3/8-CL-STK")

5053304040

(Alias Part Numbers:

"1193878-9"

"RNF-100-1-RD-SP")

756061-000

(Alias Part Numbers:

"4-1195892-8"

"RNF-100-1-BU-FSP")

505334L190

(Alias Part Numbers:

"3-1193883-5"

Product Affected

"RNF-100-1-1/2-BKSTKCS5004")

408675-000

(Alias Part Numbers:

"7-1193082-0"

"RNF-100-1-RD-SP-CS7465")

5053364071

(Alias Part Numbers:

"1-1193884-4"

"RNF-100-1-1/2-YO-SP")

5070054057

(Alias Part Numbers:

"RNF-100-3/16-CL-SP"

"1832014-1")

5053822029

(Alias Part Numbers:

"9-1193890-8"

"RNF-100-3/32-GN-STK")

CR8171-000

340378-000

(Alias Part Numbers:

"6-1198798-4"

"RNF-100-1-YO-STK-CS7465")

5053992015

(Alias Part Numbers:

"2-1193892-8"

"RNF-100-1/16-OR-STK")

0555824003

(Alias Part Numbers:

"1190424-6"

"RNF-100-1-1/4-GN-SP")

5053382054

(Alias Part Numbers:

"2-1193885-7"

"RNF-100-1-1/2-WH-STK")

5052874030

(Alias Part Numbers:

"8-1193822-0"

"RNF-100-3/64-BU-SP")

5054122017

(Alias Part Numbers:

Product Affected

"3-1193894-8"

"RNF-100-3/16-GY-STK")

5053052038

(Alias Part Numbers:

"3-1193841-1"

"RNF-100-3/16-RD-STK")

5054572017

(Alias Part Numbers:

"8-1193900-7"

"RNF-100-1-GN-STK")

5053032136

(Alias Part Numbers:

"4-1193837-4"

"RNF-100-1/8-WH-STK")

5052992172

(Alias Part Numbers:

"1-1193833-7"

"RNF-100-1/8-BK-STK")

5053402020

(Alias Part Numbers:

"4-1193886-5"

"RNF-100-2-RD-STK")

6060114001

(Alias Part Numbers:

"4-1194794-9"

"RNF-100-3/8-BK-BULK-SP")

536753-000

(Alias Part Numbers:

"3-1194213-2"

"RNF-100-1/8-YO-SP-CS7554")

505333L133

(Alias Part Numbers:

"4-1193881-9"

"RNF-100-1-WH-STK-CS6162")

F34682-000

(Alias Part Numbers:

"8-1201755-5"

"RNF-100-3/4-WH-STK-CS5592")

5054124018

(Alias Part Numbers:

Product Affected

"4-1193894-1"

"RNF-100-3/16-GY-SP")

C21606-000

(Alias Part Numbers:

"5-1200701-1"

"RNF-100-3/16-WH-STKCS5592")

A87326-000

(Alias Part Numbers:

"8-1202161-4"

"RNF-100-3-BK-STK-CS7250")

505320M039

(Alias Part Numbers:

"7-1193865-2"

"RNF-100-1/2-RD-SP-CS5529")

5054432028

(Alias Part Numbers:

"2-1193899-7"

"RNF-100-3/8-GN-STK")

505303L132

(Alias Part Numbers:

"1-1193838-6"

"RNF-100-1/8-WH-STK-CS5529")

121380-000

(Alias Part Numbers:

"5-1198936-8"

"RNF-100-3/32-RD-SP-CS5004")

505301M083

(Alias Part Numbers:

"3-1193836-7"

"RNF-100-1/8-YO-SP-CS5529")

573229-000

(Alias Part Numbers:

"6-1194550-9"

"RNF-100-3/32-CL-SP-CS5868")

A62384-000

(Alias Part Numbers:

"6-1201922-6"

"RNF-100-3/4-BK-SP-CS7807")

5053062083

(Alias Part Numbers:

Product Affected

"8-1193841-5"

"RNF-100-3/16-YO-STK")

E70690-000

(Alias Part Numbers:

"8-1201456-4"

"RNF-100-3/8-BK-FSP-CS5004")

302031-000

(Alias Part Numbers:

"9-1192287-3"

"RNF-100-3/16-WH-SP-CS5551")

507001M038

(Alias Part Numbers:

"1-1193959-5"

"RNF-100-3/64-CL-SP-CS5868")

505290L035

(Alias Part Numbers:

"1-1193825-1"

"RNF-100-1/16-RD-STKCS5529")

CX3220-000

5054434029

(Alias Part Numbers:

"3-1193899-2"

"RNF-100-3/8-GN-SP")

CL7864-000

(Alias Part Numbers:

"RNF-100-1/2-RD-FSP-CS5004")

5054092025

(Alias Part Numbers:

"7-1193893-9"

"RNF-100-1/8-GY-STK")

505306L079

(Alias Part Numbers:

"6-1193842-0"

"RNF-100-3/16-YO-STKCS5529")

339249-000

(Alias Part Numbers:

"4-1192560-6"

"RNF-100-5/8-BK-SP")

5053394065

(Alias Part Numbers:

Product Affected

"8-1193885-6"

"RNF-100-2-BK-SP")

5054414029

(Alias Part Numbers:

"5-1193898-0"

"RNF-100-1/4-GN-SP")

505294J213

(Alias Part Numbers:

"3-1193828-0"

"RNF-100-3/32-BK-SP-SM")

505303L212

(Alias Part Numbers:

"1-1193838-7"

"RNF-100-1/8-WH-STK-CS5551")

5058654004

(Alias Part Numbers:

"4-1193905-1"

"RNF-100-1-1/4-YO-SP")

5054074012

(Alias Part Numbers:

"5-1193893-8"

"RNF-100-1/8-OR-SP")

EG0543-000

(Alias Part Numbers:

"RNF-100-3/64-VT-STK")

465337-000

(Alias Part Numbers:

"1193489-3"

"RNF-100-3/4-YO-FSP")

5054584016

(Alias Part Numbers:

"2-1193901-0"

"RNF-100-1-1/2-GN-SP")

5054534025

(Alias Part Numbers:

"3-1193900-0"

"RNF-100-1/16-GN-SP")

5054254012

(Alias Part Numbers:

"6-1193896-9"

Product Affected

"RNF-100-3/4-OR-SP")

5054422023

(Alias Part Numbers:

"8-1193898-8"

"RNF-100-1/8-GN-STK")

5053334137

(Alias Part Numbers:

"9-1193880-9"

"RNF-100-1-WH-SP")

514393-000

(Alias Part Numbers:

"8-1194040-9"

"RNF-100-1/2-RD-SP-CS7554")

507012L029

(Alias Part Numbers:

"9-1193969-6"

"RNF-100-2-CL-STK-CS7250")

CW7384-000

257084-000

(Alias Part Numbers:

"3-1199500-4"

"RNF-100-1/8-BK-STK-CS7224")

507201M006

(Alias Part Numbers:

"1193972-8"

"RNF-100-1-1/4-CL-SPCS7312")

5051514001

(Alias Part Numbers:

"3-1193819-9"

"RNF-100-NO.300-BK-SP")

EM1151-000

5053954012

(Alias Part Numbers:

"8-1193891-4"

"RNF-100-3/64-OR-SP")

505318L073

(Alias Part Numbers:

"4-1193861-9"

"RNF-100-3/8-WH-STK-CS5529")

043300-000

Product Affected

(Alias Part Numbers:

"5-1197931-1"

"RNF-100-3/8-CL-SP-CS7465")

5053314139

(Alias Part Numbers:

"6-1193878-3"

"RNF-100-1-YO-SP")

5054214012

(Alias Part Numbers:

"1193896-6"

"RNF-100-1/2-OR-SP")

CW3362-000

505298L147

(Alias Part Numbers:

"3-1193832-0"

"RNF-100-3/32-WH-STKCS5004")

5052864031

(Alias Part Numbers:

"5-1193822-1"

"RNF-100-3/64-YO-SP")

BM9739-000

CN2757-000

(Alias Part Numbers:

"RNF-100-1/2-BK-STK-CS7387")

5054144013

(Alias Part Numbers:

"7-1193894-9"

"RNF-100-1/4-OR-SP")

951101-000

(Alias Part Numbers:

"1-1197355-8"

"RNF-100-3/16-RD-SP-CS7554")

5053034137

(Alias Part Numbers:

"5-1193837-2"

"RNF-100-1/8-WH-SP")

CR0866-000

540963-000

(Alias Part Numbers:

"7-1194242-7"

Product Affected

"RNF-100-3/8-BK-FSP")

505329M253

(Alias Part Numbers:

"5-1193877-8"

"RNF-100-1-BK-SP-CS7387")

548166-000

(Alias Part Numbers:

"5-1201677-2"

"RNF-100-3/4-WH-SP-CS5004")

507013M018

(Alias Part Numbers:

"3-1193970-2"

"RNF-100-3-CL-SP-CS5006")

5052904038

(Alias Part Numbers:

"8-1193824-2"

"RNF-100-1/16-RD-SP")

5070042082

(Alias Part Numbers:

"RNF-100-1/8-CL-STK"

"1642972-1")

5070044140

(Alias Part Numbers:

"1-1193961-5"

"RNF-100-1/8-CL-SP-CS7312")

5052882045

(Alias Part Numbers:

"1193823-1"

"RNF-100-3/64-WH-STK")

5057392002

(Alias Part Numbers:

"1193904-1"

"RNF-100-1-1/4-WH-STK")

295547-000

(Alias Part Numbers:

"2-1192239-2"

"RNF-100-1/2-RD-SP-CS5006")

5054084015

(Alias Part Numbers:

"6-1193893-9"

Product Affected

"RNF-100-1/8-VT-SP")

EJ2978-000

(Alias Part Numbers:

"RNF-100-0.112-CL-STK")

5053492029

(Alias Part Numbers:

"1-1193889-0"

"RNF-100-4-BK-STK")

CM9488-000

5052972050

(Alias Part Numbers:

"1193831-1"

"RNF-100-3/32-BU-STK")

507005L055

(Alias Part Numbers:

"9-1193962-8"

"RNF-100-3/16-CL-STKCS5006")

863727-000

(Alias Part Numbers:

"4-1196726-3"

"RNF-100-3/8-WH-SP-CS5074")

D48425-000

(Alias Part Numbers:

"7-1202052-3"

"RNF-100-NO.342-CL-STK")

5070112068

(Alias Part Numbers:

"7-1193968-1"

"RNF-100-1-1/2-CL-STK")

600510-000

(Alias Part Numbers:

"7-1198933-3"

"RNF-100-1/4-A1-YO-SP")

5054174014

(Alias Part Numbers:

"3-1193895-6"

"RNF-100-3/8-OR-SP")

CA4833-000

(Alias Part Numbers:

"RNF-100-2-OR-SP"

Product Affected

"6-1899526-9")

5906772001

(Alias Part Numbers:

"7-1194672-6"

"RNF-100-NO.334-CL-STK")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.