



GL8200 - PRODUCT CHANGE NOTICE

Overview

DATE ISSUED:	March 29, 2019	TRACKING NUMBER:	4134704
ISSUED BY:	Product Management		
PRODUCTS AFFECTED:	GL8200		
SKUS AFFECTED:	1102574		
BULLETIN:	Product Change Notice		
URGENCY:	Normal		
FOR DISTRIBUTION TO	All GL8200 customers and distributors		

Summary

GL8200 is suffering from supplier end of life notification on its memory. To overcome this difficulty, Sierra Wireless is introducing new SKU supporting memory component adjustment.

Details of Change

New GL8200 SKU configuration: **1104500**, based on 5.5.25.0 firmware, have completed its hardware and software validation, and backward compatible with legacy GL8200 configuration.

Please refer to following SKU replacement table:

	Old SKU	New SKU
GL8200	1102574	1104500
Availability	Last time ship: June 2019	Now

Effective Date

Customer are expected to transition their order immediately to secure continuity of their applications and services.

More information

For more information please contact your Sierra Wireless sales/technical representative for assistance.

Product Line Management
Sierra Wireless