



22-Apr-2019

PCN #:P-19-017247

Subject:PDL header

Description of Change: The orientation of PDL header will change in the tray.

Reason: Product [improvement](#). In order to raise efficiency, We plan to package PDL headers with automatic packaging machines. But the products direction in the tray packaged with packaging machine is different with current manual package. The products will rotate 180 in the tray.

Key Dates:

Contact By Date:18-Jul-2019

Implementation Date:18-Jul-2019

Product Affected

179839-1

179848-4

917845-4

179841-2

1827197-1

1376172-1

179846-1

9-179844-1

179843-1

179844-6

179848-6

917845-6

179841-4

1376172-6

179846-6

Product Affected

179844-1

179848-1

179840-6

179847-1

179838-2

179840-4

179848-2

917745-4

179841-6

179839-9

917353-1

2317123-1

179838-1

179846-2

917845-1

179844-2

179844-4

179846-4

179849-1

179840-1

917745-1

179841-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.