

12500 TI Boulevard, MS 8640, Dallas, Texas 75243

## Notification# 20180711002 Datasheet for TPS51200-Q1 Information Only

Date: July 12, 2018 To: PREMIER FARNELL PCN

Dear Customer:

This is an information-only announcement of a change to the datasheet for a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (<u>PCN ww admin team@list.ti.com</u>).

Sincerely,

PCN Team SC Business Services

## Information Only Attachments

## **Products Affected:**

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

## DEVICE

TPS51200QDRCRQ1

CUSTOMER PART NUMBER null

Technical details of this Product Change follow on the next page(s).

PCN Number:			307110			PCN Date:	J	uly	12, 201	.8
Title: Datas	heet fo	r TPS5	51200-	Q1						
<b>Customer Con</b>	tact:	<u>PCN</u>	Manag	<u>er</u>				De	pt:	Quality Services
Change Type:										
Assembly Site			Design				Wafer	· Bump Site		
Assembly Process			$\square$						Bump Material	
Assembly Materials				Part number change					Bump Process	
Mechanical Specification					Test Site					· Fab Site · Fab Materials
Packing/Shipping/Labeling			ng		Test Process					Fab Process
Notification Details										
Description of Change:										
Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.										
TEXAS INSTRUMENTS SLUS984C -NOVEMBER 2009 - REVISED APRIL 2018										
Changes from Revision B (September 2015) to Revision C Page										
Changed pinout diagram for compatibility with HTML versioin of the data sheet										
• Added REFOUT specification for $-1 \text{ mA} \le I_{\text{REFOUT}} \le 1 \text{ mA}$ , condition										
Corrected Typical Characteristics condition statement										
Added Figure 4										
Added Figure 9										
Added Receiving Notification of Documentation Updates sectiion										
The datasheet number will be changing.										
Device Family				Change From:				Change To:		
TPS51200-Q1				SLUS984B			SLUS984C			
These changes may be reviewed at the datasheet links provided.										
http://www.ti.com/product/TPS51200-Q1										
Reason for Change:										
To accurately reflect device characteristics.										
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):										
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.										
Changes to product identification resulting from this PCN:										
None.										
Product Affected:										
TPS51200QDR	CRQ1									
For questions regarding this notice, e-mails can be sent to the regional contacts shown below										

or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com