



Product Change Notification

Current Date: 23-Jul-2019

TE Connectivity

Product Change Notification: P-19-017593

PCN Date: 08-JUL-19

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Multiple Products

Description of Changes

Change of shipping location from HL20 to EPDC

Reason for Changes:

Product improvement. TE changed NA shipping location of parts affected by Section 301 tariffs on China origin goods to HL20 in Hermosillo, Mexico, to mitigate tariff impact for customers consuming the parts outside the US. As a long term strategy, those parts are being moved to the newly setup Foreign Trade Zone (FTZ) in EPDC. This will allow customers to pick up China origin parts at same location as several other NA made TE parts, and streamline their supply chain by using their warehouses in Southern US to consolidate shipments to plants. To prevent being charged a surcharge for tariffs, customers must use bonded carriers to pick up parts, and ship to a FTZ.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

15-OCT-2019

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1376352-1	NO						
1534120-1	NO						
1565894-1	NO						
1717138-4	NO						
1717138-6	NO						
1718562-1	NO						
172494-1	NO						
172500-4	NO						
172517-1	NO						
1732175-1	NO						
174044-2	NO						
174046-2	NO						
174047-2	NO						
174257-2	NO			"0-0174257-2", "CA9323-000", "AMPS-0-0174257-2"			
174465-1	NO			"0-0174465-1"			
1746894-1	NO						
174910-2	NO						
174931-1	NO			"0-0174931-1"			
178602-1	NO						
179254-2	NO						
2-174357-2	NO						
2112058-1	NO						
213088-4	NO						

2137704-1	NO						
2137704-2	NO						
2137711-3	NO						
2137722-1	NO						
2137735-1	NO						
2137740-3	NO						
2137740-4	NO						
2294653-1	NO						
2294655-1	NO						
2822346-1	NO						
2822390-1	NO						
284425-1	NO						
3-1437837-1	NO			"104233", "E0VB-13A506-C", "E0VB-13A506-CA", "1000023086"			
316390-7	NO						
348794-4	NO						
6-1355688-1	NO						
776001-1	NO						
8-1393292-4	NO			"V23074A1001A403"			
965430-1	NO			"0-0965430-1", "CF4304-000", "AMPS-0-0965430-1"			

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1376352-1	NO		TYC1376352-1				

1534120-1	NO		TYC1534120-1			
1717138-4	NO					
1717138-6	NO		TYC1717138-6			
1718562-1	NO					
172494-1	NO		TYC172494-1			
172500-4	NO					
172517-1	NO					
1732175-1	NO					
174044-2	NO		TYC174044-2			
174046-2	NO		TYC174046-2			
174047-2	NO		TYC174047-2			
174257-2	NO		TYC174257-2	"O-0174257-2", "CA9323-000", "AMPS-0-0174257-2"		
174465-1	NO		TYC174465-1	"O-0174465-1"		
1746894-1	NO					
174910-2	NO					
174931-1	NO		TYC174931-1	"O-0174931-1"		
178602-1	NO		TYC178602-1			
2822346-1	NO		TYC2822346-1			
2822390-1	NO		TYC2822390-1			
284425-1	NO					
316390-7	NO		TYC316390-7			
6-1355688-1	NO		TYC6-1355688-1			
776001-1	NO		TYC776001-1			
8-1393292-4	NO		TYC8-1393292-4	"V23074A1001A403"		
965430-1	NO		TYC965430-1	"O-0965430-1", "CF4304-000", "AMPS-0-0965430-1"		

Customer: TTI Inc (3164508)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1376352-1	NO						
1534120-1	NO						
174046-2	NO						
178602-1	NO						
179254-2	NO						
2137704-1	NO						
2137704-2	NO						
2137711-3	NO						
2137722-1	NO						
2137735-1	NO						
2137740-3	NO						
2137740-4	NO						
2294653-1	NO						
2294655-1	NO						
2822390-1	NO						
3-1437837-1	NO			"104233", "E0VB-13A506-C", "E0VB-13A506-CA", "1000023086"			
316390-7	NO						
348794-4	NO						
776001-1	NO						

Customer: TTI Electronics Asia Pte Ltd. (1407161)

Location: Kowloon Bay

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2822390-1	NO						

Customer: TTI Inc (1281288)

Location: Fort Worth

Agreement Number: TTI002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1376352-1	NO						
1534120-1	NO						
174044-2	NO						
174046-2	NO						
174047-2	NO						
174257-2	NO			"0-0174257-2", "CA9323-000", "AMPS-0-0174257-2"			
174931-1	NO			"0-0174931-1"			
178602-1	NO						
2-174357-2	NO						
213088-4	NO						
2822346-1	NO						
2822390-1	NO						
3-	NO			"104233", "E0VB-13A506-C", "E0VB-			

1437837-1				13A506-CA", "1000023086"			
316390-7	NO						
348794-4	NO						
776001-1	NO						
8-1393292-4	NO			"V23074A1001A403"			

Customer: TTI Electronics Asia Pte Ltd. (2771300)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1565894-1	NO						
174046-2	NO						
2822390-1	NO						

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1376352-1	NO						
1534120-1	NO						
174044-2	NO						
174046-2	NO						
174047-2	NO						

174257-2	NO			"0-0174257-2", "CA9323-000", "AMPS-0-0174257-2"			
174931-1	NO			"0-0174931-1"			
178602-1	NO						
179254-2	NO						
2-174357-2	NO						
213088-4	NO						
2137704-1	NO						
2137704-2	NO						
2137711-3	NO						
2137722-1	NO						
2137735-1	NO						
2137740-3	NO						
2137740-4	NO						
2294653-1	NO						
2294655-1	NO						
2822346-1	NO						
2822390-1	NO						
3-1437837-1	NO			"104233", "EOVB-13A506-C", "EOVB-13A506-CA", "1000023086"			
316390-7	NO						
348794-4	NO						
776001-1	NO						
8-1393292-4	NO			"V23074A1001A403"			

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1376352-1	NO		TYC1376352-1				
1717138-4	NO						
1717138-6	NO		TYC1717138-6				
1718562-1	NO						
172494-1	NO		TYC172494-1				
172517-1	NO						
1732175-1	NO						
174044-2	NO		TYC174044-2				
174046-2	NO		TYC174046-2				
174047-2	NO		TYC174047-2				
174257-2	NO		TYC174257-2	"0-0174257-2", "CA9323-000", "AMPS-0-0174257-2"			
174465-1	NO		TYC174465-1	"0-0174465-1"			
1746894-1	NO						
174910-2	NO						
174931-1	NO		TYC174931-1	"0-0174931-1"			
178602-1	NO		TYC178602-1				
2822346-1	NO		TYC2822346-1				
2822390-1	NO		TYC2822390-1				
284425-1	NO						
316390-7	NO		TYC316390-7				
965430-1	NO		TYC965430-1	"0-0965430-1", "CF4304-000", "AMPS-0-0965430-1"			

Customer: Tti Inc (3065672)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-174357-2	NO						

Customer: TTI Electronic (Thailand) Ltd (3084974)

Location: Huaykwang Bangkok

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2112058-1	NO						

Customer: TTI Electroncis Asia Pte LTD (3055204)

Location: Seoul

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1376352-1	NO						

Customer: TTI Electronics Asia Pte Ltd. (2771300)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1565894-1	NO						
174046-2	NO						
2822390-1	NO						

Customer: TTI Inc (3165288)

Location: Chatsworth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
776001-1	NO						