



09-Jul-2019

PCN #:P-19-017598

Subject:Power distribution blocks DBL

Description of Change: ABB logo on the DBL covers to be changed by TE logo

Reason: Product improvement.

Key Dates:

Product Affected

1SNL308010R0000

1SNL317531R0000

1SNL312510R0000

1SNS320001Z1722

(Alias Part Numbers:
"1003919-E")

1SNL316010R0000

1SNS320001Z1723

(Alias Part Numbers:
"1003920-E")

1SNS320001Z1725

(Alias Part Numbers:
"1003922-E")

1SNS320001Z1724

(Alias Part Numbers:
"1003921-E")

1SNL340010R0000

1SNS320001Z1727

(Alias Part Numbers:
"1003924-E")

Product Affected

1SNL325010R0000

1SNS320001Z1726

(Alias Part Numbers:

"1003923-E")

1SNL317510R0000

1SNL312530R0000

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.
