



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000969

DATE: 26-Jul-2019

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	DG201ADY/GG8	DG201ADY+			Part reactivated from prior notice: M000875
Reactivation	DG403DY/GG8	DG403DY+			Part reactivated from prior notice: M000875
Reactivation	DS1726U/GG8	DS1726U+			Part reactivated from prior notice: M0009651
Reactivation	MAX1033BEUP/GG8	MAX1033BEUP+			Part reactivated from prior notice: M0009651
Reactivation	MAX1183ECM/GG8	N/A			Part reactivated from prior notice: M0009651
Reactivation	MAX1270AEAI/GG8	MAX1270AEAI+			Part reactivated from prior notice: M000875
Reactivation	MAX1287EKA/GG8	MAX1287EKA+			Part reactivated from prior notice: M000875
Reactivation	MAX1485EUB/GG8	MAX1485EUB+			Part reactivated from prior notice: M000875
Reactivation	MAX156AEWI/GG8	MAX156AEWI+			Part reactivated from prior notice: M000875
Reactivation	MAX16053AUT/GG8	MAX16053AUT+			Part reactivated from prior notice: M000875
Reactivation	MAX16922ATPC/V+	N/A			Part reactivated from prior notice: M0009391
Reactivation	MAX16922ATPC/V+T	N/A			Part reactivated from prior notice: M0009631
Reactivation	MAX1709EUI/GG8	MAX1709EUI+			Part reactivated from prior notice: M000875
Reactivation	MAX1793EUE25/GG8	MAX1793EUE25+			Part reactivated from prior notice: M0009651
Reactivation	MAX1836EUT50/GG8	MAX1836EUT50+			Part reactivated from prior notice: M0009411
Reactivation	MAX1932ETC/GG8	MAX1932ETC+			Part reactivated from prior notice: M000875
Reactivation	MAX194AEWE/GG8	MAX194AEWE+			Part reactivated from prior notice: M000875
Reactivation	MAX1989MEE/GG8	MAX1989MEE+			Part reactivated from prior notice: M0009621
Reactivation	MAX2112ETI/GG8	MAX2112ETI+			Part reactivated from prior notice: M0009651
Reactivation	MAX292EWE/GG8	MAX292EWE+			Part reactivated from prior notice: M000875
Reactivation	MAX3002ETP/GG8	MAX3002ETP+			Part reactivated from prior notice: M0009651
Reactivation	MAX3002EUP/GG8	MAX3002EUP+			Part reactivated from prior notice: M000875
Reactivation	MAX301ESE/GG8	MAX301ESE+			Part reactivated from prior notice: M000875
Reactivation	MAX3033EEUE/GG8	MAX3033EEUE+			Part reactivated from prior notice: M000875
Reactivation	MAX3043ESE/GG8	MAX3043ESE+			Part reactivated from prior notice: M000875
Reactivation	MAX3045BEUE/GG8	MAX3045BEUE+			Part reactivated from prior notice: M000875

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Aug-2019

Reactivation	MAX3077EASA/GG8	MAX3077EASA+			Part reactivated from prior notice: M000875
Reactivation	MAX3077EESA/GG8	MAX3077EESA+			Part reactivated from prior notice: M000875
Reactivation	MAX307EUI/GG8	MAX307EUI+			Part reactivated from prior notice: M000875
Reactivation	MAX3087ESA/GG8	MAX3087ESA+			Part reactivated from prior notice: M000875
Reactivation	MAX3093EEUE/GG8	MAX3093EEUE+			Part reactivated from prior notice: M000875
Reactivation	MAX3094EEUE/GG8	MAX3094EEUE+			Part reactivated from prior notice: M000875
Reactivation	MAX3095ESE/GG8	MAX3095ESE+			Part reactivated from prior notice: M000875
Reactivation	MAX312EUE/GG8	MAX312EUE+			Part reactivated from prior notice: M000875
Reactivation	MAX313EUE/GG8	MAX313EUE+			Part reactivated from prior notice: M000875
Reactivation	MAX313LESE/GG8	MAX313LESE+			Part reactivated from prior notice: M000875
Reactivation	MAX3160EAP/GG8	MAX3160EAP+			Part reactivated from prior notice: M000875
Reactivation	MAX3160EEAP/GG8	MAX3160EEAP+			Part reactivated from prior notice: M000875
Reactivation	MAX3161EEAG/GG8	MAX3161EEAG+			Part reactivated from prior notice: M0009651
Reactivation	MAX318ESA/GG8	MAX318ESA+			Part reactivated from prior notice: M000875
Reactivation	MAX3221EEAE/GG8	MAX3221EEAE+			Part reactivated from prior notice: M000875
Reactivation	MAX3224EAAP/GG8	MAX3224EAAP+			Part reactivated from prior notice: M000875
Reactivation	MAX3283EAUT/GG8	MAX3283EAUT+			Part reactivated from prior notice: M000875
Reactivation	MAX333AEUP/GG8	MAX333AEUP+			Part reactivated from prior notice: M0009651
Reactivation	MAX333AEWP/GG8	MAX333AEWP+			Part reactivated from prior notice: M000875
Reactivation	MAX3373EEKA/GG8	MAX3373EEKA+			Part reactivated from prior notice: M000875
Reactivation	MAX3430ESA/GG8	MAX3430ESA+			Part reactivated from prior notice: M000875
Reactivation	MAX3485ESA/GG8	MAX3485ESA+			Part reactivated from prior notice: M000875
Reactivation	MAX3490EESA/GG8	MAX3490EESA+			Part reactivated from prior notice: M000875
Reactivation	MAX3490ESA/GG8	MAX3490ESA+			Part reactivated from prior notice: M0009651
Reactivation	MAX354EWE/GG8	MAX354EWE+			Part reactivated from prior notice: M000875
Reactivation	MAX396EWI/GG8	MAX396EWI+			Part reactivated from prior notice: M000875
Reactivation	MAX4203EUA/GG8	MAX4203EUA+			Part reactivated from prior notice: M0009651
Reactivation	MAX4222EEE/GG8	MAX4222EEE+			Part reactivated from prior notice: M0009621
Reactivation	MAX4232AUA/GG8	MAX4232AUA+			Part reactivated from prior notice: M0009651
Reactivation	MAX4239ATT+	N/A			Part reactivated from prior notice: M0009621
Reactivation	MAX4239ATT+T	N/A			Part reactivated from prior notice: M0009621
Reactivation	MAX4312EEE/GG8	MAX4312EEE+			Part reactivated from prior notice: M0009651
Reactivation	MAX4444ESE/GG8	MAX4444ESE+			Part reactivated from prior notice: M0009621
Reactivation	MAX4447ESE/GG8	MAX4447ESE+			Part reactivated from prior notice: M000875
Reactivation	MAX4461TETT+T	N/A			Part reactivated from prior notice: M0009631
Reactivation	MAX4545EAP/GG8	MAX4545EAP+			Part reactivated from prior notice: M000875

Reactivation	MAX4581AUE/GG8	MAX4581AUE+			Part reactivated from prior notice: M000875
Reactivation	MAX4614EUD/GG8	MAX4614EUD+			Part reactivated from prior notice: M0009651
Reactivation	MAX4635EUB/GG8	MAX4635EUB+			Part reactivated from prior notice: M000875
Reactivation	MAX488EESA/GG8	MAX488EESA+			Part reactivated from prior notice: M000875
Reactivation	MAX490EESA/GG8	MAX490EESA+			Part reactivated from prior notice: M000875
Reactivation	MAX4947ETG/GG8	MAX4947ETG+			Part reactivated from prior notice: M000875
Reactivation	MAX5066AUI/GG8	MAX5066AUI+			Part reactivated from prior notice: M0009651
Reactivation	MAX5090CATE/GG8	MAX5090CATE+			Part reactivated from prior notice: M000875
Reactivation	MAX5308EUE/GG8	MAX5308EUE+			Part reactivated from prior notice: M0009651
Reactivation	MAX5402EUA/GG8	MAX5402EUA+			Part reactivated from prior notice: M0009651
Reactivation	MAX5887EGK/GG8	N/A			Part reactivated from prior notice: M0009141
Reactivation	MAX604ESA/GG8	MAX604ESA+			Part reactivated from prior notice: M000875
Reactivation	MAX6126A21/GG8	MAX6126A21+			Part reactivated from prior notice: M0009651
Reactivation	MAX6126AASA25/GG8	MAX6126AASA25+			Part reactivated from prior notice: M0009651
Reactivation	MAX6138AEXR21/GG8	MAX6138AEXR21+			Part reactivated from prior notice: M000875
Reactivation	MAX6138AEXR25/GG8	MAX6138AEXR25+			Part reactivated from prior notice: M000875
Reactivation	MAX6138AEXR50/GG8	MAX6138AEXR50+			Part reactivated from prior notice: M000875
Reactivation	MAX6166AESA/GG8	MAX6166AESA+			Part reactivated from prior notice: M0009651
Reactivation	MAX6176AASA/GG8	MAX6176AASA+			Part reactivated from prior notice: M000875
Reactivation	MAX618EEEE/GG8	MAX618EEEE+			Part reactivated from prior notice: M0009651
Reactivation	MAX6314US26D1/GG8	MAX6314US26D1+			Part reactivated from prior notice: M000875
Reactivation	MAX6328XR31/GG8	MAX6328XR31+			Part reactivated from prior notice: M000875
Reactivation	MAX6338GUB/GG8	MAX6338GUB+			Part reactivated from prior notice: M000875
Reactivation	MAX6338LUB/GG8	MAX6338LUB+			Part reactivated from prior notice: M000875
Reactivation	MAX6390XS29D4/GG8	MAX6390XS29D4+			Part reactivated from prior notice: M000875
Reactivation	MAX6412UK22/GG8	MAX6412UK22+			Part reactivated from prior notice: M000875
Reactivation	MAX6412UK31/GG8	MAX6412UK31+			Part reactivated from prior notice: M000875
Reactivation	MAX6412UK46/GG8	MAX6412UK46+			Part reactivated from prior notice: M000875
Reactivation	MAX6418UK44/GG8	MAX6418UK44+			Part reactivated from prior notice: M000875
Reactivation	MAX6433UK/GG8	MAX6433UK+			Part reactivated from prior notice: M000875
Reactivation	MAX6459UTA/GG8	MAX6459UTA+			Part reactivated from prior notice: M0009651
Reactivation	MAX6605MXK/GG8	MAX6605MXK+			Part reactivated from prior notice: M0009651
Reactivation	MAX6613MXK/GG8	MAX6613MXK+			Part reactivated from prior notice: M000875
Reactivation	MAX6703SKA/GG8	MAX6703SKA+			Part reactivated from prior notice: M000875
Reactivation	MAX6709AUB/GG8	MAX6709AUB+			Part reactivated from prior notice: M0009651
Reactivation	MAX6709FUB/GG8	MAX6709FUB+			Part reactivated from prior notice: M0009651

Reactivation	MAX6710DUT/GG8	MAX6710DUT+			Part reactivated from prior notice: M000875
Reactivation	MAX6747KA29/GG8	MAX6747KA29+			Part reactivated from prior notice: M0009651
Reactivation	MAX6818EAP/GG8	MAX6818EAP+			Part reactivated from prior notice: M0009651
Reactivation	MAX6897PALT/GG8	MAX6897PALT+			Part reactivated from prior notice: M000875
Reactivation	MAX690AESA/GG8	MAX690AESA+			Part reactivated from prior notice: M000875
Reactivation	MAX691AESE/GG8	MAX691AESE+			Part reactivated from prior notice: M000875
Reactivation	MAX691AEWE/GG8	MAX691AEWE+			Part reactivated from prior notice: M000875
Reactivation	MAX6957AAX/GG8	MAX6957AAX+			Part reactivated from prior notice: M000875
Reactivation	MAX7408EUA/GG8	MAX7408EUA+			Part reactivated from prior notice: M000875
Reactivation	MAX797ESE/GG8	MAX797ESE+			Part reactivated from prior notice: M000875
Reactivation	MAX803SEXR/GG8	MAX803SEXR+			Part reactivated from prior notice: M000875
Reactivation	MAX809LEUR/GG8	MAX809LEUR+			Part reactivated from prior notice: M000875
Reactivation	MAX811SEUS/GG8	MAX811SEUS+			Part reactivated from prior notice: M000875
Reactivation	MAX8213AESE/GG8	MAX8213AESE+			Part reactivated from prior notice: M000875
Reactivation	MAX8214ACSE/GG8	MAX8214ACSE+			Part reactivated from prior notice: M000875
Reactivation	MAX821LUS/GG8	MAX821LUS+			Part reactivated from prior notice: M000875
Reactivation	MAX821TUS/GG8	MAX821TUS+			Part reactivated from prior notice: M0009621
Reactivation	MAX823TEUK/GG8	MAX823TEUK+			Part reactivated from prior notice: M000875
Reactivation	MAX836EUS/GG8	MAX836EUS+			Part reactivated from prior notice: M000875
Reactivation	MAX8516EUB/GG8	MAX8516EUB+			Part reactivated from prior notice: M0009691
Reactivation	MAX8520ETP/GG8	MAX8520ETP+			Part reactivated from prior notice: M000875
Reactivation	MAX8556ETE/GG8	MAX8556ETE+			Part reactivated from prior notice: M0009651
Reactivation	MAX8655ETN/GG8	MAX8655ETN+			Part reactivated from prior notice: M000817
Reactivation	MAX8860EUA33/GG8	MAX8860EUA33+			Part reactivated from prior notice: M0009651
Reactivation	MAX8869EUE33/GG8	MAX8869EUE33+			Part reactivated from prior notice: M000875
Reactivation	MAX8891EXK15+	N/A			Part reactivated from prior notice: M0009631
Reactivation	MAX8973AEWI+T	N/A			Part reactivated from prior notice: M0009651
Reactivation	MAX9110EKA/GG8	MAX9110EKA+			Part reactivated from prior notice: M000875
Reactivation	MAX9130EXT/GG8	MAX9130EXT+			Part reactivated from prior notice: M000875
Reactivation	MAX9374AEKA/GG8	MAX9374AEKA+			Part reactivated from prior notice: M000875
Reactivation	MAX9378EUA/GG8	MAX9378EUA+			Part reactivated from prior notice: M000875
Reactivation	MAX9384EWP/GG8	MAX9384EWP+			Part reactivated from prior notice: M0009651
Reactivation	MAX9939AUB/GG8	MAX9939AUB+			Part reactivated from prior notice: M0009621
Reactivation	MAX999EUK/GG8	MAX999EUK+			Part reactivated from prior notice: M000875
Reactivation	MX574AJEWI/GG8	MX574AJEWI+			Part reactivated from prior notice: M000875
Lead-Free Conversion	VT1314SFCR-001	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Aug-2019

Lead-Free Conversion	VT1546MBFQ-008	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Lead-Free Conversion	VT341LFCR-ADJ	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Lead-Free Conversion	VT356FCR-ADJ-005	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Lead-Free Conversion	VT357FCR-ADJ	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	806-0586-21+T	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	806-0586-22+	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	806-0586-22+T	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	806-0674-20+D	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	8100603EA	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG305AAK/883B	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG387AAK/883B	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG401DJ+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG417LDJ+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG442CJ+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG445CY+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG445CY+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1050U-005+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1085LZ-25B2+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1091LUA-040+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1100U-75+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1270AB-70#	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1270AB-70IND#	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1314+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1813R-15-U+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1982-035-01-F5+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS21Q354B+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS2430AB-002-E1+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS2704RQC+T10	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-W0R+1T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28E05X-047-B5+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28EL25Q+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28EL25Q+U	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS33X42+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS3640B+DIE	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	DS9106L-PK0+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS9106S-PK0+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Aug-2019

Discontinuance	DS9106S-YL0+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DSK4X-S+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICL7621ACSA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1021BETX+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1026BEEE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1044C/D	MAX1044C/D+	26-Jul-2019	26-Jul-2019	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX1062CEUB+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1082ACUE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1085ACSA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1091BCEI+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1093BCEG+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1121EGK+D	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11291ENX+CGQ	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11291ENX+TCGQ	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1142AEAP+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11607EWC+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11607EWC+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11801EWC+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1245ACAP+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1245BCAP+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1265ACEI+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1271AENG+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX138EPL+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX139CMH+D	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14540EEWP+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14550AEETB+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14560EWC+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14587EEWL+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14589EEWL+TG2B	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14592EEWE+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14638EZA+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14646EEWE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14677EZA+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14709ENL+TCGZ	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX149BCPP+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX152CPP+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Aug-2019

Discontinuance	MAX15566GTG+	N/A	25-Jan-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15566GTG+T	N/A	25-Jan-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15566TGTG+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16005DTE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16014TT+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16021PTEM+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16033LLB31+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16092UK28BGA+	N/A	20-Jul-2019	20-Jul-2019	The part was not released
Discontinuance	MAX16092UK28BGA+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX160CPN+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16131WTNN00+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1623EVKIT	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX16909SATE/V+CMF	N/A	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX16931ATLR/V+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16979RATE/V+CMF	N/A	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX16979SATE/V+CMF	N/A	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX17007BGTI+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17009GTL+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17009GTL+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17020ETJ+TCCM	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17042EVKIT#	MAX17047EVKIT#	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX17042G+T	MAX17047G+T10	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17042G+U	MAX17047G+	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17058X003+T10	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1707EVCMODU	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX1711EVKIT	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX1714AEVKIT	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX1714BEVKIT	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX1718MSEVKIT	MAX1718EVKIT	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX17582EVKIT+	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX17582GTM+T	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17841GUE+	MAX17841BGUE+	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17841GUE/V+TCEN	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1813EVKIT	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX182BCWI+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Aug-2019

Discontinuance	MAX190ACWG+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX19695ZEXF+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX197BEAI+C10272	MAX197BEAI+	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX1988ETM+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX20030ATMA/V+TW	MAX20030BATMA/V+T	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX20030ATMA/V+W	MAX20030BATMA/V+	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX20030ATMC/V+TW	MAX20030BATMC/V+T	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX20030ATMC/V+W	MAX20030BATMC/V+	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX20030ATMD/V+T	MAX20030BATMD/V+T	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX20030ATME/V+	MAX20030BATME/V+	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX20030ATME/V+T	MAX20030BATME/V+T	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX20030ATMF/V+	MAX20030BATMF/V+	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX20030ATMF/V+T	MAX20030BATMF/V+T	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX20031ATMA/V+TW	MAX20031BATMA/V+T	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX20031ATMA/V+W	MAX20031BATMA/V+	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX20031ATMC/V+W	MAX20031BATMC/V+	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX200EWP+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX20459ATJAE/V+	N/A	25-Jul-2020	24-Jan-2021	The part was not released
Discontinuance	MAX20459ATJB/V+	N/A	25-Jul-2020	24-Jan-2021	The part was not released
Discontinuance	MAX20459ATJB/V+T	N/A	25-Jul-2020	24-Jan-2021	The part was not released
Discontinuance	MAX20800T-B02#	N/A	26-Jul-2019	26-Jul-2019	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX20800T-D02#	MAX20800T-D00#	26-Jul-2019	26-Jul-2019	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX2151BETJ+TWCL4	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX267ACWG+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX2689EVKIT#	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX2769BC/D	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX30131EWA+	MAX30131CWA+	25-Jul-2020	24-Jan-2021	The part was not released
Discontinuance	MAX30131EWA+T	MAX30131CWA+T	25-Jul-2020	24-Jan-2021	The part was not released
Discontinuance	MAX30132EWA+	MAX30132CWA+	25-Jul-2020	24-Jan-2021	The part was not released
Discontinuance	MAX30132EWA+T	MAX30132CWA+T	25-Jul-2020	24-Jan-2021	The part was not released
Discontinuance	MAX30134EWA+	MAX30134CWA+	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX30134EWA+T	MAX30134CWA+T	26-Jul-2019	26-Jul-2019	The part was not released
Discontinuance	MAX314LCPE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX31782ETL+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX31820SLMCR+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3243CAI+TG38	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Aug-2019

Discontinuance	MAX3345EEVKIT	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX3377EETD+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3460CSD+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3468CPA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3646ETG+TC86	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX399CPE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX40026ATA/V+	N/A	25-Jul-2020	24-Jan-2021	The part was not released
Discontinuance	MAX40026ATA/V+T	N/A	25-Jul-2020	24-Jan-2021	The part was not released
Discontinuance	MAX40027EVKIT+	MAX40027EVKIT#	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX4023ESE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4053CPE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4210BEUA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4391CPA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX44281UANS+	N/A	20-Jul-2019	20-Jul-2019	The part was not released
Discontinuance	MAX4482ASA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4482ASA+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4506MJA	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4530CPP+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4546CEE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4550CWI+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4552CPE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4572CAI+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4578CWP+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4758EWX+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4787EXK+TC7Q	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4950CTO+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4950CTO+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5021EUA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5023SASA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5087AATE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5087AATE+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX535ACPA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX539ACPA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5581AEUP+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5860DUXH+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5860PUXH+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Aug-2019

Discontinuance	MAX6331LUR+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6331LUR+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6377UR27+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6377UR27+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6387LT23D3+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6391KA46+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6391KA46+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6427MRUR+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX642AESA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6461XR27+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6711LEXS+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6794TPLD2+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6866UK23D1S+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6868UK23D1S+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6881ETE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6888BETE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6961ATH+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX704TEPA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX706SMJA	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX709SCUA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX734CPA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX7405CPA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX7409CPA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX754ESE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX767EVKIT-SO	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX77665AEWQ+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77665AEWQ+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77819EWB+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77819XEWB+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX804TCSA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX814KEPA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX819LEPA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8563EEE+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT15+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT15+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT16+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Aug-2019

Discontinuance	MAX8640YELT18+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT82+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT16+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8744ETJ+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8744ETJ+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8805WEVKIT+	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX8841ELT33+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8877EZK25+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8877EZK25+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX890LESA/V+	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8929EVKIT+	N/A	26-Jul-2019	26-Jul-2019	EVKIT is No Longer Supported
Discontinuance	MAX8983EWE+TCAW	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8983EWE+TCAX	N/A	25-Jul-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9290GTM/V+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9372EKA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9550EZK+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9652ASA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX96911DGTJ/VY+TW	MAX96911DGTJ/VY+	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX96911DGTJY+TE2	MAX96911DGTJ/VY+	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX96911GGTJ/VY+TW	MAX96911GGTJ/VY+T	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX96911GGTJ/VY+W	MAX96911GGTJ/VY+	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX96911GGTJY+TE2	MAX96911GGTJ/VY+T	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX96912EGTMY+TE2	MAX96912EGTM/VY+T	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MAX97000EWA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX97000EWA+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX97002EWP+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX97002EWP+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724AEBC+G45	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724AEBC+TG45	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX973CPA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX982CPA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX983EPA+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9880AEWM+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9880AEWM+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9895AEWX+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9895AEWX+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 26-Aug-2019

Discontinuance	MAX9963AGCCQ+D	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ622X-2613+	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7524AQ	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7533LCWE+TG52	MX7533LCWE+T	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	MXD1815UR31+T	N/A	18-Oct-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	VT1317SFCY	VT1317SFCX	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1317SFCY-001	VT1317SFCX-001	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1320MFQR	VT1320MFQX	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1321MFQR	VT1321MFQX	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1322MFQR	N/A	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1323MFQR	VT1323MFQX	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1328MFQR	VT1328MFQX	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1331SFCR	VT1331SFCX	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1332SFCR	N/A	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1335SFCR	N/A	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1336SAFCR	N/A	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT1336SFCR	N/A	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT350AFCR-ADJ	N/A	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT351AFCR-ADJ	VT351AFCX-ADJ	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT354FQR-ADJ	N/A	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT357FCR-ADJ-005	N/A	25-Jan-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	VT357FCR-ADJ-007	N/A	25-Jan-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	VT382BFCN-ADJ-001	VT382BFCX-ADJ-001	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT382BFCR-ADJ	VT382BFCX-ADJ	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT382FCR-ADJ	VT382FCX-ADJ	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT386FC-ADJ	N/A	25-Jan-2020	24-Jan-2021	Part can no longer be manufactured
Discontinuance	VT386FCR-ADJ	N/A	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT386FCZ-ADJ	N/A	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured
Discontinuance	VT451RFCR-ADJ	N/A	26-Jul-2019	26-Jul-2019	Part can no longer be manufactured