



06-Aug-2019

PCN #:E-19-011635

Subject:T9S and T9V series relay

Description of Change: Optimize T9S and T9V structure, add a slot on the bobbin.

Reason: Product Improvement. Optimize T9S and T9V structure, to enhance the fixing reliability of the insulation sheet by adding a slot on the bobbin.

Key Dates:

Contact By Date:12-Nov-2019

Implementation Date:12-Nov-2019

Product Affected

2027395-4

(Alias Part Numbers:

"T9SV1K15-12-02")

2027395-5

(Alias Part Numbers:

"T9VV1K15-12S")

2027395-8

2027395-6

2027395-2

(Alias Part Numbers:

"T9SV1K15-12-01")

2027395-3

(Alias Part Numbers:

"T9SV1K15-12S")

2027395-1

(Alias Part Numbers:

"T9SV1K15-12")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.