



21-Apr-2020

PCN #:E-20-004625

Subject:B-155-03/-05/-06/-07/-11/-13 (PDs)

Description of Change: Revise the location dimensions between the solder ring and sealing rings as shown on mark-ups for the PDs listed above. These dimensions are now to be SPC controlled dimensions. This change is considered by TE Connectivity as a location change.

Reason: Customer Request. Customer complaints regarding the location of the solder ring with reference to the sealing rings. Sometimes, visually the solder ring is not centered, but the parts meet our specification and don't hinder product performance.

Key Dates:

Contact By Date:30-Apr-2020

Implementation Date:30-Apr-2020

Product Affected

A70754-000

(Alias Part Numbers:

"8-1201998-9"

"B-155-03")

E39668-000

(Alias Part Numbers:

"1-1201999-0"

"B-155-13")

D42180-000

(Alias Part Numbers:

"1201999-3"

"B-155-05")

E21385-000

(Alias Part Numbers:

Product Affected

"1201999-7"

"B-155-06")

A88975-000

(Alias Part Numbers:

"9-1201998-0"

"B-155-07")

A39093-000

(Alias Part Numbers:

"8-1201998-5"

"B-155-11")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary

from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.