

Product Change Notification

| Product Category | : | Power & Line Protection. |
|-------------------|---|--|
| Issue Date | : | 07- April - 2020 |
| Effective Date | : | 07- July - 2020 |
| LTB Date | : | 06/30/2020 |
| LTD Date | : | 12/30/2020 |
| Reason for Change | : | Phaseo brand power supplies will be replaced with a new Modicon branded UL1310 Class 2 power supply. |
| Parts Affected | : | Below are the list of part numbers which |

| Obsoleted. |
|------------|
| |

are

| EOL PART NUMBER | REPLACEMENT PART NUMBER | LTB Date | LTD Date |
|------------------------|----------------------------|-----------|------------|
| ABL8MEM24003 | ABLM1A24004 | 6/30/2020 | 12/31/2020 |
| ABL8MEM24006 | ABLM1A24006 | 6/30/2020 | 12/31/2020 |
| ABL8MEM05040 | ABLM1A05036 | 6/30/2020 | 12/31/2020 |
| ABL8MEM12020 | ABLM1A12021 | 6/30/2020 | 12/31/2020 |
| ABL8MEM24012 | ABLM1A24012 | 6/30/2020 | 12/31/2020 |
| ABL7RM24025 | ABLM1A24025 | 6/30/2020 | 12/31/2020 |
| ABL7RP1205 ABLS1A12062 | | 6/30/2020 | 12/31/2020 |
| ABL8REM24030 | ABLS1A24031 | 6/30/2020 | 12/31/2020 |





| 1 | | | |
|--------------|-------------|-----------|------------|
| ABL8REM24050 | ABLS1A24050 | 6/30/2020 | 12/31/2020 |
| ABL7RP4803 | ABLS1A48025 | 6/30/2020 | 12/31/2020 |
| ABL1REM12050 | ABLP1A12085 | 6/30/2020 | 12/31/2020 |
| ABL1REM24025 | ABLP1A24045 | 6/30/2020 | 12/31/2020 |
| ABL1REM24042 | ABLP1A24045 | 6/30/2020 | 12/31/2020 |
| ABL1REM24062 | ABLP1A24062 | 6/30/2020 | 12/31/2020 |
| ABL1REM24100 | ABLP1A24100 | 6/30/2020 | 12/31/2020 |
| ABL1RPM12083 | ABLP1A12085 | 6/30/2020 | 12/31/2020 |
| ABL1RPM24042 | ABLP1A24045 | 6/30/2020 | 12/31/2020 |
| ABL1RPM24062 | ABLP1A24062 | 6/30/2020 | 12/31/2020 |
| ABL1RPM24100 | ABLP1A24100 | 6/30/2020 | 12/31/2020 |
| ABL1A01 | ABLPA01 | 6/30/2020 | 12/31/2020 |
| ABL1A02 | ABLPA02 | 6/30/2020 | 12/31/2020 |

